

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	10/28/24	6000176/1
Home Phone	R/O Close Date	Receipt No.
	12/27/24	Original
Body	Mileage In	Mileage Out
2DR COUPE 850	39779	39779
Year	Make	Model
1993	BMW	8 SERIES
Vehicle Identification Number	Color	License Number
WBAEG2326PCB75162	WHITE	LAUREL BAKER
Account No.	Delivery Date	In-Service Date

INVENTORY: PB75162

#1 - TIRE4: MOUNT AND BALANCE 4 NEW TIRES

Work performed by 800231 : 150500008

36121116326 : VALVE STEM SET

1@85.00

1006.00

85.00

36112229730 : WHEEL SET OF 4

1@3300.00

3300.00

Freight:

200.00

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS	3585.00				
DEDUCTIBLE					
SUBLET	1006.00				
SHOP SUPPLIES	169.25				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS	4760.25				

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	5/15/25	6000561/1
Home Phone	R/O Close Date	Receipt No.
	5/20/25	Original
Body	Mileage In	Mileage Out
2DR COUPE 850	40153	40161

Year	Make	Model	License Number	Service Advisor
1993	BMW	8 SERIES		LAUREL BAKER
Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
WBAEG2326PCB75162	WHITE			

INVENTORY: PB75162

#1 - UCI: PERFORM USED VEHICLE INSPECTION Work performed by Tech 121 USED CAR INSPECTION COMPLETED.	1.50hrs @ 300.00	450.00	I
#2 - LOF: OIL AND FILTER CHANGE SERVICE, TOP OFF ALL NECESSARY FLUIDS, ADJUST TIRE PRESSURES Caused by SERVICE DUE. Work performed by Tech 121 11427510717 : BMW OIL FILTER 4.4L 540I E20 1@11.95 4601218 : WINZER COPPER WASHER 12X18 460 1@0.52 PEN5W40 : PENNZOIL 5W40 8@8.87 OIL AND FILTER REPLACED. ALL TIRE PRESSURES SET TO SPECIFICATION AND ALL NECESSARY FLUIDS TOPPED OFF.	1.00hrs @ 300.00 300.00 11.95 .52 70.96	300.00 11.95 .52 70.96	I
#3 - BRKFSH: PERFORM BRAKE FLUID EXCHANGE Caused by BRAKE FLUID DARK AND DIRTY. Work performed by Tech 121 601458 : SYNTHETIC DOT 3 AND 4 BRAKE FL 1@12.84 BRAKE SYSTEM FLUSHED AND FLUID REPLACED.	1.50hrs @ 300.00 450.00 12.84	450.00 12.84	I
#4 - ENGINEAIR: REPLACE ENGINE AIR FILTER(S) Caused by ENGINE AIR FILTERS DIRTY. Work performed by Tech 121 13721720861 : AIR FILTER 2@22.98 ENGINE AIR FILTERS REPLACED.	0.50hrs @ 300.00 150.00 45.96	150.00 45.96	I
#5 - CEL: CHECK ENGINE LIGHT IS ON. PULL CODE(S) AND PERFORM INITIAL DIAGNOSTICS Caused by CHECKED ENGINE CODES: DASH INDICATED 1221 (O2 SENSOR- BANK NOT SPECIFIED). Work performed by Tech 121 0.75hrs @ 300.00 RECOMMEND O2 SENSOR REPLACEMENT TO START.	0.75hrs @ 300.00 225.00	225.00	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	1575.00				
PARTS	142.23				
DEDUCTIBLE					
SUBLT					
SHOP SUPPLIES	85.86				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS	1803.09				