| | | No. 8562 | RNIA 94062 | THE DATE | DATE 15 G CUSTOMER ORDER NO. ORDER WRITTEN BY | TERMS TERMS (MOORE) VEG 1 | STYNG ENGINE NO. LICENSE SPEEDOMETER | ORDER INSTRUCTIONS LABOR | 349 3601 WILL 889 8000 | | complete." | ilter, Change transaxle oil | ydraulics & clutch hydraulics | cooling system | chean post of to the lobs & | Torque wheel logs, correct tine pressu | chd release cable. ADD 2 swepco | = | | | PRICE | 30 PTS JRAME BIL @ 100 bo LARTE 70 00 | | 3 GALS. ANTIFREEZE 30 00 TOTAL 238 25 | 16 988 048 40 00 FUTAL 218 50 | 9 PTS.BRANE FLUID 35 55 REPAIRS | 1 Swepco 505 12 95 F.E.T. | TOTAL FLUIDS 2/18 50 GAS | SERVICE | IF NECESTARY SUBTOTAL 109175 | LEGAL FEES, GOORT COSTS AND ANY AD- | TOTAL \$ 1129 48 |
|---------------|--|-------------------|--|----------------------------|---|---------------------------|--------------------------------------|--------------------------|------------------------|----------------------|------------------|-----------------------------|-------------------------------|----------------|-----------------------------|--|---------------------------------|---------|------------------------|------------------------|--|--|-------------------------------|--|-------------------------------|---------------------------------|---------------------------|---------------------------------------|---|------------------------------|-------------------------------------|--|
| MODENA MOTORS | Specializing in repair of Ferrari, Lamborghini and Vintage Automobiles | | 95 REDWOOD CITY, CALIFORNIA 94062 (415) 368-5819 | BAR NO. AH 64874 A A LO LA | _ | 000 | 109 | 20 REPAIR ORD | 7-17-1 | 90 TEST DRIVE & CHEC | "CHASSIS SERVICE | Change engine oil & P. 14 | & blead brake | 3 | ce spark | Whe with anti-sieze. | R+R Detaine rear deck | tive to | Agust I die Aire bu | , | 1. 1 HEREBY AUTHORIZE THE REPAIR WORK TO BOOKE ALONG WITH THE NECESSARY MATERIALS. | 2. AN EXPRESS MECHANIC'S LIEN IS ACKNOW. LEDGEN THE VHICLE TO SECURE THE AMOUNT ON REPAIRS THERETO. IN AGREET TO | SONABLE RE THAN THAT RE | 3. WE LC CE OR | 4. ESTIMATECH | OU WANT OLD PARTS, | THAT | PTER 20.3, ARTICLE CALIFORNIA BUSINES | MOBILE IS RETURNED TO CUSTOMER ARGE OF \$ WILL BE | PHONED TIME | ITLED TO | ABOVE, AND ACKNOWLEDGE RECEIPT OF THIS ESTIMATE/REPAIR ORDER |
| | | PRICE AMOUNT | /8 | t11 St b | 595 4760 | | 65 260 | 1 | 2500 | 3 45 7 | | | | | | | | | minor | Stire | | | V 1 | | 23825 | | | | | | | |
| | PARTS & MATERIAL | QUAN. DESCRIPTION | 1 NPW 1060 CAPS. | 177 | 8 503 sweeper took addi | 35 | 1 32×27 WASHER - | 2 16x33 WASHER - | 124288 OILP. HER | L CANS BOAKE CLEAN | | | | | | | | UNTES! | Am covers weeping o.// | I dle surge, sught mis | , , , | | | The second secon | TOTAL PARTS | SUBLET REPAIRS | 1 22 CRE# 0131 | 26-11-01 | | | | TOTAL SUBLET REPAIRS |

MODENA MOTORS PARTS & MATERIAL REPAIR ORDER Specializing in repair of Ferrari, Lamborghini and Vintage Automobiles No. 8574 105-111 EL CAMINO REAL PART NO. DESCRIPTION PRICE AMOUNT QUAN 570 - 884- 8000 DO CITY, CALIFORNIA 94062 3 95 CANS BRK. CLEAN (415) 368-5819 BAR NO. AH 64874 KIHCAMCOURRGET CUSTOMER ORDER NO. ORDER WRITTEN BY RIH CAM COURT GAT 36 Ferrari COUER O-RING ENGINE NO. END PL. GASKET 00 DISTR. GASKET 11 76 REPAIR ORDER INSTRUCTIONS LABOR CHECK FOR ENGINE ON lea END. PL. GKT. 6 CLEAN OFF OIL LEAK ARRAS RUN TOFINDLEAKS RTU SPALER RIBANK & LIBANK CAM COURES & REMOUEL 6×1.0 CLEAN UP MATING SURFACES, +NSTALL NEW WALLY WS#R GMM COURR GASKETS, END PLETES GASKETS, DISTR. GKTS DISTR. SPALSOCHECK IGNITION CABLES. INSTALL FIRE EXTINGUISHER. INSTALL (2 BOTTLES ADDITIVE FUEL VALUE CLEARANCE. I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. TOTAL PRICE **FLUIDS** 6 HOURS AN EXPRESS MECHANIC'S LIEN IS ACKNOW-LEDGED ON THE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO, I AGREE TO PAY REASONABLE STORAGE ON VEHICLE LEFT MORE THAN 48 HOURS AFTER NOTIFI-CATION THAT REPAIRS ARE COMPLETE. LABOR COLD QTS. TRANS. OIL @ 1000 RATE TOTAL PTS. DIFF. GREASE@ OUD 1 RONT LABOR WE WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR APTICLES LEFT IN CASE OF FIRE THEFT, ACCIDENT OR ANY OTHER CAUSE OF TROL. TOTAL GALS. ANTIFREEZE PARTS ESTIMATE CHARGE SOLO PER NO TOTAL /TOTAL PARTS QTS. OIL @ **FLUIDS** OUTSIDE SUBLET REPAIRS PTS. BRAKE FLUID INCLUDES ALL PARTS DEPO HANDLING AND DIAGNOSIS. IF ON CLOSER ANALYSIS IT IS FOUND THAT ADDITIONAL PAPAIRS ARE NECESSARY, YOU WILL BE CONTACTED FOR AUTHORIZATION PURSUANT TO DIVISION 3, CHAPTER 20.3, ARTICLE 3, SECTION 9884.9 OF THE CALIFORNIA BUSINESS AND PROFESSIONS REPAIRS SWEDID FUEL ADDITIUE. F.E.T. SUMMER TOTAL FLUIDS CODE. 6. IF AUTOMOBILE IS RETURNED TO CUSTOMER BEFORE SERVICE IS PERFORMED, A HAND-7- BOTTLE WINTER LING CHARGE OF \$ REVISED AMOUNT \$ NUMBER PHONED SUB TOTAL TIME PERSON CONSENTING _ COLLECT ANY SUMS DUE HEREUNDER THE SHOULD LEGAL ACTION BE NECESSARY TO PREVAILING PARTY SHALL BE ENTITLED TAX DITIONAL COSTS INCURRED. I HAVE READ AND UNDERSTAND THE TOTAL SUBLET REPAIRS ABOVE, AND ACKNOWLEDGE RECEIPT OF THIS ESTIMATE/REPAIR ORDER

| Specializing in repair of Ferral Lamborghini and Vintage Automobiles No. 8820 **REPAIR ORDER N | | | | | | MODENA MOTORS | |
|--|------------|------------|-------------------|---|--|--|----------------|
| 4 2007 WASHER + 65 260 2 6072 WASHER - 60 130 3 102438 OLU F. HEE - 60 130 1 124288 OLU F. HEE - 824 95 | | 331-143311 | PARTS & MATERIAL | | | Specializing in repair of Ferrari, Lamborghini and Vintage Automobiles REPAIR OR | |
| 4 2007 UNSHLE -60 120 2 6012 UNSHLE -60 120 1 127644 SUBSE CAP (update) 20 86 1 127640 SUBSE CAP (update) 20 | QUAN. | PART NO. | DESCRIPTION | PRICE | AMOUNT | 105-111 EL CAMINO REAL NO. 88 | 20 |
| ABOUT CHANGE FROM ALL BLOKEN THOUSE WASHING THE BOOK CAP () AND THE BOTTLE CHANGE FROM CAPE WASHINGTON THE PROPERTY OF THE BOOK CAPE WASHINGTON THE PROPERTY OF THE BOOK CAPE WASHINGTON THE PROPERTY OF THE BOOK CAPE WASHINGTON THE CAP | 4 | 22×27 | WASHER | 6 65 | 260 | | |
| 1 124288 OIL G. HET 2495 NAME OIL G. HET STORY OF THE PARTY OF THE PAR | 2 | 16x22 | | 1 | | DIRIUS HITCHOOL | |
| REDUMN WATER WHEN A COLD STORE STREET STORE STATE CHANGE THE STATE | 1 | 124288 | OII. A. Her | | The second secon | | RDER WRITTEN B |
| REPAIR ORDER INSTRUCTIONS CHANGE ENBANCED OIL & FILTRE & CUBIE BURED BURED HYDRAULICY CREEK PARSON REPAIR ORDER INSTRUCTIONS CHANGE FILTRE & CUBIE BURED BURED HYDRAULICY CREEK PARSON REPAIR ORDER INSTRUCTIONS CHANGE FILTRE PARSON CHANGE FILTRE PARSON CHANGE FILTRE PARSON CHECK SPARK PUBS (OL) CHECK SPARK PUBS (OL) FRONT CRILL BROKEN CHECK BATTERS (OL AT This time) FRONT CRILL BROKEN CHECK TURE LESSURE CHECK TURE CHECK TORROW CHECK TURE CHECK TURE CHECK TORROW CHECK TORROW CHECK TORROW CHECK TURE CHECK TORROW | 1 | 127644 | 1 | odate) | | ADDRESS TERMEASH MATERIALI MOS | TR 90" |
| REPAIR ORDER INSTRUCTIONS CHANGE RIGHNED DILL & FILTER & CUBIE BURGO BALLE HYDRAULICY Check pads (0e) Replie & Surge Cap CHANGE TRANSAME JURGO COCING SYSTEM CHANGE TRANSAME JIRANSAME JIRANSTO CUSE OIL CHECK SHAK PLUGS (0e) | 1 | REDUNK | / · / · | | | PHONE STUDY NO. ENGINE NO. LICENSE | 4337 |
| BURRD BRALLE HYDRASULG CNECK pads (0) Replace Surge Cap CHANGE FROM COLUMB SYSTEM' CHANGE TRANSPORT COLUMB SYSTEM' CHANGE TRANSPORT CUSE OIL STIPS CHECK A/C COE CHECK S/MK PUBS (OK) REAR EMPTY PARTY COLUMB SYSTEM' CHECK S/MK PUBS (OK) REAR EMPTY PARTY (OL AT This time) CHECK 164TS | | | | | | | |
| BURRD BRALLE HYDRASULG CNECK pads (0) Replace Surge Cap CHANGE FROM COLUMB SYSTEM' CHANGE TRANSPORT COLUMB SYSTEM' CHANGE TRANSPORT CUSE OIL STIPS CHECK A/C COE CHECK S/MK PUBS (OK) REAR EMPTY PARTY COLUMB SYSTEM' CHECK S/MK PUBS (OK) REAR EMPTY PARTY (OL AT This time) CHECK 164TS | | | | | | CHANGE ENGINE DIL & FILTER & LUBE | |
| Replace Surge Cag CHANGE TRANSPARE TRANSPARE OF TRANSPARE OF THE OUT OF THE PLANS | | | | | | | 712391 |
| CHANGE TRANSFER COLOR SYSTEM ' CHANGE TRANSFER CASE OIL S-11-95 CHECK SPANK PUBS (OK) CHECK BATTERS (OL AT This time) FRONT CHILL BROKEN CHECK TUNE TO TO CHECK T | | | 1 | | | | |
| CHANGE TRANSARE TRANSFORMER CUSE OIL 5-11-95 CHELK A/C COR) CHELK SPANK PLUGS (OK) CHECK SPANK PLUGS (OK) CHECK SPANK PLUGS (OK) CHECK SPANK PLUGS (OK) CHECK SPANK PLUGS (OK) FRONT CRILL BROKEN CHECK BATTERS (OK AT This time) CHECK BATTERS (OK AT THIS TIME) TUTAL PROSESUR SPANGE CHECK TUNE TO THE NECESSARY CHECK TO THE NECESSARY CHECK TO THE NECESSARY CHECK TO THE NECESSARY | | / , , | 1 # N 129 | | | | 11 10 11 11 |
| CHECK SPANK PLUBS (OK) CHECK SPANK PLUBS (OK) CORRECT TIRE PLESSURE FRONT CRILL BROKEN CHECK BATTERY (OK AT TA'S TIME) REAR EMPTY PAINT DISTRICT TO STORIUK TOTAL PRESSURE SALUM CHECK UGHTS CHE | 1 | pac | 10151 | | | | ATRIBLE. |
| CHECK SPARK PUBS (OK) DOTAL DOTAL DITTOR CHICK BATTERY (OK AT This time) REAL ENGINE PRINT DEFENDE CHECK BATTERY (OK AT This time) REAL ENGINE PRINTING CHECK BATTERY (OK AT THIS TIME) TOTAL BATTERY CHECK BATTERY (OK AT THIS TIME) CHECK U64TS CHECK TUNK THE RECESSARY LABOR BATTERY TOTAL BATTERY LABOR BATTERY TOTAL PARTS SUBLET REPAIRS CANL # 615 47800 April 33700 CHECK TUNK THAN ALCOHOM. LOSS OF ORANGE STORAGE OF WINCEKE CAST BATTERY LOSS OF ORANGE STORAGE OF WINCEKE CAST BATTERY LOSS OF ORANGE STORAGE OF WINCEKE CAST BATTERY LOSS OF ORANGE STORAGE STORAGE OF WINCEKE CAST ORANGE STORAGE OF WINCEKE OF ASTICKETS SUBLET REPAIRS CANL # 615 47800 April 33700 CANL # 615 47800 April 33700 TOTAL SUBLET REPAIRS CANL # 615 47800 April 33700 TOTAL SUBLET REPAIRS CHECK SPARK PURSAN ACTION PRINTS OF THE PRINTING TO CUSTOMER BATTERY THE CONTROL PRINTING TO CUSTOMER BATTERY THE CONTROL PRINTING TO CUSTOMER BATTERY THE CONTROL PRINTING TO CUSTOMER BATTERY TOTAL SUBLET REPAIRS LABOR SECURITY OF ASTICKETS THE CONTROL PRINTING TO CUSTOMER BATTERY THE CONTROL PRINTING TO CUSTOMER BATTERY TOTAL SUBLET REPAIRS LABOR SECURITY OF ASTICKETS THE CONTROL PRINTING TO CUSTOMER BATTERY TOTAL SUBLET REPAIRS LABOR SECURITY OF ASTICKETS TOTAL FILLIOS [9] 48 GAS SUB TOTAL 675 11 TAX 20 64 TOTAL SUBLET REPAIRS | 1 | 5-1 | 11-95 | | | | 111111 |
| PRONT CRILL BROKEN CHECK BATTERY (OR AT This time) REAR BURGER PAINT DICTALL TINTOKE PLENUM GASLETS SHOULD CHECK UG4TS Se replaced by Next of Check TURE LIBERTY OF THE PRESENT OF CHECK TURE LIBERTY OF THE PRESENT OF CHECK TURE LABOR STORMER STORMER STORMER OF THE PRESENT OF CHECK TO SCIUNCY LANGUAGE ON THE VEHICLE TO SCIUNCY THE PRESENT OF CHECK TO SCIUNCY THE PRESENT OF THE PRINTING TH | 3 | - | | | | | |
| REAL OUTSIDE PLANT COLD. REAL OUTSIDE PLANT COLD. REAL OUTSIDE PLANT COLD. REAL OUTSIDE PLANT COLD. REAL OUTSIDE PLANTS SUBLET REPAIRS CHICK BATTERY (OR AT This time) FILL WASHING BOTTLE CHICK UGHTS CHICK TUNE TO TAKE HOURS TO AN EXPRESS MECHANICS LIEN IS ACKNOW. AN EXPRESS MECHANICS LIEN IS ACKNOW. AN EXPRESS MECHANICS LIEN IS ACKNOW. AND HAVE RECARNED STORAGE ON VARIOUS CONTROL AND HAVE RECARNED STORAGE ON VARIOUS CONTROL TO AN OTHER COURS BOTTOM ON VARIOUS CONTROL TO AN OTHER COURS BY THE COMPLETE ON ARTICLES. SUBLET REPAIRS CANCER TO ANT OLD PARTS TO TAKE | 1 | NOTE. | | | | | |
| REAL ENTRY PAINT DELLARS FOR SHOULD CHECK THE FUND WITH THE FUND WORK AND WITH THE FUND WITH THE FUND WORK AND WORK AND WORK AND WORK AND WITH THE FUND WORK AND WOR | - reliable | FRONT | CRILL BROKE | 7 | | | |
| TOTAL SUBLET REPAIRS CHICK 164TS CHICK 164TS CHICK 164TS CHICK 164TS CHICK 164TS CHICK 164TS TUST ORIUL 1. IMERITY AUTOMIZE THE REPAIR WORK TO BECOME THE MODE TO BECOME THE MODE TO BECOME THE HOURS 1. IMERITY AUTOMIZE THE REPAIR WORK TO BECOME THE HOURS 1. IMERITY THE RECESSARY AND AUTOMIZE THE REPAIR WORK TO BECOME THE HOURS 2. AN EXPRESS MECHANIC'S LIEN IS ACKNOW. AND OF THE VEHICLE TO SECONE THE ADMIRET TO BECOME THE ADMIRET TO BECOME THE ADMIRET TO BECOME THE ADMIRET TO BECOME THE LEFT MORE TO SECONE THE ADMIRET TO BECOME THE ADMIRET TO BECOME THE HOURS 2. AN EXPRESS MECHANIC'S LIEN IS ACKNOW. AND OF THE VEHICLE TO SECONE THE ADMIRET TO SECONE THE ADMIRET TO BECOME THE LABOR OF THE ADMIRET TO SECONE THE ADMIRET TO BECOME THE ADMIRET TO BE ADMIRED TO BE ADMIR | | | | 1. 1 | ct | | 111111 |
| Se replaced Gt Next OI Change CHECK TUNK TO STORIUR 1. I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE RECESSARY WILL BE DONE ALONG WITH THE RECESSARY BELUIDS PRICE HOURS 6 2. AN EXPRESS MECHANIC'S LIER 15 ACKNOW ANTERIALS. 2. AN EXPRESS MECHANIC'S LIER 15 ACKNOW ANTERIALS. 2. AN EXPRESS MECHANIC'S LIER 15 ACKNOW ANTERIALS. 2. AN EXPRESS MECHANIC'S LIER 15 ACKNOW AND | | | | | | CHRCK 4164TS | |
| 1. I HEREBY AUTHORIZE THE BEPAIR WORK TO BE ONDE ALONG WITH THE NECESSARY WITH THE NECESSARY WATERIALS 1. I HOURS OF DONE ALONG WITH THE NECESSARY WATERIALS 1. I HOURS HEREBY WITH CHANGES LIER IS ACKNOWN OF PROPERTY OF THE CHANGES THE PARK WITH THE PARKS THEREBY WITH CHANGES THE PARK WITH THE PARKS THEREBY WITH CHANGES THE PARK WITH THE PARKS THE PARK THE | | 1 | | 1 / A / A / A / A / A / A / A / A / A / | THE RESIDENCE OF THE PARTY OF T | CHECK TUNE & TEST DRIVE | |
| AND AND THE SECONDARY OF THE PRAIRS THE PRAIRS ARE TO THE CALLY OF PLANS ADDITION ALD FREEZED AND UNDERSTAND THE BEFORE B | | - | 1 | | | 1. I HERLBY AUTHORIZE THE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY BLUIDS PRICE TOTAL HOURS | 6 |
| TOTAL SUBLET REPAIRS LEFT MORE THAN 48 HOURS AFTER NOTIFICATION THAT REPAIRS ARE COMPLETE. 34 FRONT 36 Real COLD. 35 8 66 34 FRONT 36 Real COLD. 35 8 66 36 SUBLET REPAIRS SUBLET REPAIRS 57 SUBLET REPAIRS 58 SUBLET REPAIRS 58 SUBLET REPAIRS 59 COLD WANT OLD PARTS LABOR. HANDING REPAIRS ARE NOT COLORER ANALYSIS IT IS FOUND THAT ADDITIONAL REPAIRS ARE NECESSARY, YOU WILL BE CONTACTED FOR AUTHORIZATION PURSUANT TO DIVISION S, CHECK COLD COLD. 6. IF AUTOMOBILE IS RETURNED TO CUSTOMER BEFORE SERVICE IS PERFORMED, A HANDING COLD. 6. IF AUTOMOBILE IS RETURNED TO CUSTOMER BEFORE SERVICE IS PERFORMED, A HANDING WANDED COLD. 6. IF AUTOMOBILE IS RETURNED TO CUSTOMER BEFORE SERVICE IS PERFORMED, A HANDING COLD. 70 SHOULD LEGAL ACTION BE NECESSARY TO COLEGE ANALYSIS IT IN MEDITIONAL COSTS INCURRED. TOTAL SUBLET REPAIRS 50 CONTACT OF COLOR OF THE CASE OF T | | | | | | 2. AN EXPRESS MECHANIC S LIEN IS ACKNOW. LEDGED ON THE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. I AGREE TO | 70 a |
| 34 FRONT 36 Real COLD. 10 SON DAMAGE TO VEHICLE OR ARTICLES SALE OF PIECE ACCIDENT ON ANY OTHER CAUSE BEYOND QUE CONTOL. 10 SUBLET REPAIRS TOTAL SUBLET REPAIRS | | THE PIC | essure spec | 5 | | LEFT MORE THAN 48 HOURS AFTER NOTIFI- CATION THAT REPAIRS ARE COMPLETE. PTS. DIFF. GREASE LABOR | 420 00 |
| SUBLET REPAIRS | | 34 Fro. | rt, 36 hear | COLD. | | LOSS OR DAMAGE TO VEHICLE OR ARTICLES GALS. ANTIFREEZE 30 00 PARTS | 58 66 |
| SUBLET REPAIRS 5. INCLUDES ALL PARTS, LABOR, HANDLING AND DIAGNOSIS. IF ON CLOSER ANALYSIS ARE IS FOUND THAT ADDITIONAL REPAIRS ARE IN FOUND TO CLOSE ANALYSIS AND PROFESSION TO TOTAL FLUIDS 12 95 F.E.T. CANCE # 6/5 47800 Apriox 33700 5. INCLUDES ALL PARTS, LABOR, HANDLING ANALYSIS ARE INCLUDED TO CLOSE ANALYSIS AND PROFESSION TO TOTAL FLUIDS 12 95 F.E.T. TOTAL FLUIDS 12 | | 34051 | TOTAL PARTS | | 58 66 | 4. ESTIMATE CHARGE \$ 700.00 15 app of 225 1 33 75 TOTAL FLUIDS | 191 45 |
| AND DIAGNOSIS. IF ON CLOSER ANALYSIS IT IS FOUND THAT ADDITIONAL REPAIRS ARE NECESSARY, VOU WILL BE CONTACTED FOR AUTHORIZATION PURSUANT TO DIVISION 3. CHAPTER 20.3, ARTICLE 3, SECTION 9884.9 OF THE CALIFORNIA BUSINESS AND PROFESSIONS CODE. IF AUTOMOBILE IS RETURNED TO CUSTOMER BEFORE SERVICE IS PERFORMED, A HANDLING CHARGE OF \$ WILL BE MADDED TO THE PHONED DATE TIME PERSON CONSENTING DATE TIME PERSON CONSENTING 7. SHOULD LEGAL ACTION BE NECESSARY TO COLLECT ANY SUMS DUE HEREUNDER THE DITIONAL COSTS INCURRED. TOTAL SUBLET REPAIRS 8. I HAVE READ AND UNDERRIAD THE ABOVE, AND AUKNOWLEDGE RECEINT V | | | SUBLET REPAIRS | | - 4 | S. INCLUDES ALL PARTS, LABOR, HANDLING S PIS. PLUID 177 TO REPAIRS | |
| CHAPTER 20.3, ARTICLE 3, SECTION 9884.9 OF THE CALIFORNIA BUSINESS AND PROFESSIONS TOTAL FLUIDS GAS TOTAL FLUIDS TOTAL FLUIDS GAS TOTAL FLUIDS GAS TOTAL FLUIDS TOTAL FLUIDS GAS TOTAL FLUIDS FROM CORRESTORY SUB TOTAL 675 TOTAL GAS TOTAL SUBLET REPAIRS TOTAL SUBLET REPAIRS TOTAL SUBLET REPAIRS | | - 11 | | * | | AND DIAGNOSIS. IF ON CLOSER ANALYSIS IT IS FOUND THAT ADDITIONAL REPAIRS ARE NECESSARY, YOU WILL BE CONTACTED FOR | |
| LING CHARGE OF \$ WILL BE MADE NUMBER BY SUBJECT BY PERFORMED, A HAND- LING CHARGE OF \$ WILL BE MADE NUMBER PHONED DATE TIME PERSON CONSENTING 7. SHOULD LEGAL ACTION BE NECESSARY TO COLLECT ANY SUMS DUE HEREUNDER THE PREVAILING PARTY SHALL BE ENTITLED TO LEGAL FEES, COURT COSTS AND ANY ADDITIONAL COSTS INCURRED. TOTAL SUBLET REPAIRS 1. I HAVE READ AND UNDERSTORE RECEIVE V TOTAL SUBLET REPAIRS 1. I HAVE READ AND UNDERSTORE RECEIVE V TOTAL SUBLET REPAIRS | 6 | PILC#6 | 1547800 AMIOX | 357.00 | | CHAPTER 20.3, ARTICLE 3, SECTION 9884.9 OF TOTAL FLUIDS 1914 GAS | |
| DATE TIME PERSON CONSENTING 7. SHOULD LEGAL ACTION BE NECESSARY TO COLLECT ANY SUMS DUE HEREUNDER THE PREVAILING PARTY SHALL BE ENTITLED TO LEGAL FEES, COURT COSTS AND ANY ADDITIONAL COSTS INCURRED. 8. I HAVE READ AND UNDERSTAND THE ABOVE, AND ACKNOWLEDGE RECEINT V | | | " | | | | 500 |
| TOTAL SUBLET REPAIRS PREVAILING PARTY SHALL BE ENTITLED TO LEGAL FEES, COURT COSTS AND ANY ADDITIONAL COSTS INCURRED. I HAVE READ AND UNDERSTAND THE ABOVE, AND ACKNOWLEDGE RECEINT V | | | | | | DATE TIME PERSON CONSENTING SUB TOTAL | 675 11 |
| TOTAL SUBLET REPAIRS ABOVE, AND ACKNOWLEDGE RECEIAT V TOTAL 675 #5 | | | | | | PREVAILING PARTY SHALL BE ENTITLED TO LEGAL FEES, COURT COSTS AND ANY AD- | 20 64 |
| | | тот | AL SUBLET REPAIRS | | | ABOVE, AND ACKNOWLEDGE RECEINT V | 695 75 |

MODENA MOTORS
111 EL CAMINO REAL
REDWOOD CITY, CA 94062
650-368-5819/FAX368-8217
QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION
ON FERRARI AUTOMOBILES EXCLUSIVELY [#AA151475]

R/O #: 9197 Name:

Date: 04/30/98

License # : DEALPLATE Make : FERRARI

Model: TESTAROSSA

Year: 1990

Mileage: 5038

Save Parts : NO

VIN: 87270

| AMOUNT | | | | LABOR | | | | | | |
|------------|-----|--------|--|--------------------|--|--|--|--|--|--|
| 0.00 | | | ODENA MOTORS,5/9/95, 4351 MILES. | LAST SERVICE @ M | | | | | | |
| 425.00 | | | CHASSIS SERVICE CHANGE ENGINE OIL & FILTER. CHANGE TRANSAXLE OIL& TRANSFER CASE OIL. R&R WHEELS, FLUSH AND BLEED BRAKE HYDRAULICS. ADJUST F&R TIRE PRESSURE BATTERY SERVICE. FLUSH AND BLEED CLUTCH HYDRAULICS. TEST COOLANT, REPLACE AS NEEDED, BLEED AIR FROM COOLING SYSTEM. CHECK & SET TIRE PRESSURE. | | | | | | | |
| 21.25 | | | | R & R FRONT GRILI | | | | | | |
| 0.00 | | | MATE CONTROL ADJUSTMENT ? T THIS TIME, [NO CHARGE]. | | | | | | | |
| 85.00 | | | IL SCREW LOOSE ?[. R/H TAIL LIGHT ACCESS, D REPAIR BROKEN SCREW THREADED BUNG. | R&R R/H GRILL FOR | | | | | | |
| 0.00 | | | EFECT ON REAR BUMPER,[NO CHARGE]. | TOUCH UP PAINT D | | | | | | |
| QTY AMOUNT | QTY | PRICE | v unless specified. | PARTS All parts ne | | | | | | |
| 1 492.00 | 1 | 492.00 | FRONT GRILL | 61488200 | | | | | | |
| 1 24.95 | 1 | 24.95 | OIL FILTER | 124228 | | | | | | |
| 4 2.80 | 4 | 0.70 | DRAINWASHER | 22X27 | | | | | | |

MODENA MOTORS
111 EL CAMINO REAL

REDWOOD CITY, CA 94062 650-368-5819/FAX368-8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [#AA151475] R/O#:9197

Page: 2

Name:

Date: 04/30/98

License # : DEALPLATE

Make: FERRARI

Model: TESTAROSSA

Year: 1990

Mileage: 5038

Save Parts: NO

VIN: 87270

| PARTS All parts new i | unless specified. | PRICE | QTY | AMOUNT |
|-----------------------|--------------------------------|-------|-----|--------|
| 16 X 22 | WASHER | 0.65 | 2 | 1.30 |
| 80W-90 SWEPCO | GEAR OIL | 5.00 | 19 | 95.00 |
| ANTIFREEZE | ENGINE COOLANT | 12.50 | 3 | 37.50 |
| 15W-40 SWEPCO | ENGINE OIL | 5.00 | 14 | 70.00 |
| AGIP | BRAKE FLUID | 7.95 | 4 | 31.80 |
| BRK | CLEANER | 3.95 | 1 | 3.95 |
| NPN | TAIL LIGHT LENS OVERSIZE SCREW | 0.45 | 1 | 0.45 |

RECOMMENDATIONS AND TECHNICIANS NOTES

CAM BELTS OVER 8.5 YEARS.

BRAKE BOOSTER STICKS INTERMITENTLY.

FRONT DECKLID STRUTS ANEMIC.

| Original E | stimate: 1,3 | 392.34 | | | | LABOR | 531.25 |
|------------|--------------|---------------|----------|------|-----------|---------------------|-------------|
| | Ir | ncreases to I | Estimate | | | PARTS | 759.75 |
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | 0.00 |
| Date | Time | ORuby | THORE | Emp. | New Total | SHIPPING & HANDLING | 10.00 |
| | | | | | | HAZARDOUS MATERIALS | 7.50 |
| | | | | | | SUB TOTAL | 1,308.50 |
| | | | | | | TAX | 62.68 |
| | | / | | | | TOTAL | \$ 1,371.18 |

I hereby authorize the above named business to perform the repair work listed above along with necessary materials. You and your employees may operate the above vehicle for purposes of testing, inspection or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs. Thereto it is understood that this company assumes no responsibility for loss or damafe by theft or fire to vehicles placed with them for storage, sale repair, or while road testing.

Authorized by : _____ Date :____

MODENA MOTORS
111 EL CAMINO REAL
REDWOOD CITY, CA 94062
650-368-5819 / FAX 8217
CUSTOM SERVICE, REPAIR, MECHANICAL RESTORATION
ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9605

Name:

Date: 11/09/01 License #: 4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage:

VIN: 87270

| SPECIA | L ORDER THERMAL COUPLER ECU FOR 1-6 BANK. | | | AMOUNT .00 |
|--------|---|--------|-----|---------------|
| PARTS | All parts new unless specified. | PRICE | QTY | AMOUNT |
| 141037 | THERMAL COUPLER ECU | 331.65 | 1 | 331.65 |

File

| Original E | Estimate: 36 | 2.18 | | | | LABOR | .00 |
|------------|--------------|---------------|----------|------|-----------|---------------------|--------|
| | li | ncreases to E | Estimate | | | PARTS | 331.65 |
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | .00 |
| | | | | | | SHIPPING & HANDLING | 4.00 |
| | | | | | | SUB TOTAL | 335.65 |
| | | | | | | TAX | 26.53 |
| | | 1 | | | | TOTAL | 362.18 |

| | | | 10 | 7/ | MILL | Γ | יםו | ۷ |
|-----------------|--------|---|-----|-----|------|----------|-----|---|
| Authorized by : | Date : | C | 11º | ااذ | OMER | V | IL | ١ |

MODENA MOTORS

111 EL CAMINO REAL

REDWOOD CITY, CA 94062

650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION

ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9580

Name:

Date: 08/01/07

License #:4DGJ627

Make: FERRARI

Model: TESTAROSSA

Year: 1990 Mileage: 5633

VIN: 87270

Save Parts: YES

LABOR

INSPECTION AND ESTIMATES.

NO CHARGE

AMOUNT

0,00 7,625,00

30K SERVICE WITH CAM BELTS.

REMOVE AND REPLACE ENGINE/TRANS CRADDLE ASSEMBLY

REPLACE CAM BELTS, CAM SEALS, TENSIONER BEARINGS.

POLISH CAM SEAL JOURNALS.

ADJUST 48 VALVES.

PERFORM CAM TIMING FOR ALL CAM SHAFTS.

REPLACE IGNITION CABLE LOOM CLIPS.

REPLACE ALTENATOR BELT.

REPLACE AIR PUMP BELT.

REPLACE AIR CONDITIONING COMPRESSOR BELT.

CHANGE ALL FLUIDS AND FILTERS.

INSPECT IGNITION CABLES, TEST, CLEAN.

REPLACE IGNITION ROTORS.

TEST AND CLEAN DISTRIBUTOR CAPS.

REPLACE DISTRIB. CENTER CARBON BUTTONS.

PRESSURE TEST &INSPECT COOLING SYSTEM.

REMOVE SEALED MIXTURE SCREW PLUGS.

CHECK AND ADJUST FUEL INJECTION SYSTEM, SET WITH MANOMETER, INSTALL

IDLE CAPS.

COMPLETE CHASSIS SERVICE.

CHANGE ENGINE OIL AND FILTER.

FLUSH AND BLEED BRAKE & CLUTCH HYDRAULICS.

CHANGE TRANSAXLE AND TRANSFER CASE OIL.

FILL COOLING SYSTEM AND BLEED AIR FROM SYSTEM.

ADJUST HANDBRAKE.

SERVICE BATTERY, CHARGE, LOAD TEST.

CHECK LIGHTS.

LUBE HINGES.

TORQUE WHEEL LUG BOLTS.

SET TIRE PRESSURES, 36 PSI REAR COLD, 34 PSI FRONT COLD.

TEST DRIVE.

MODENA MOTORS 111 EL CAMINO REAL

REDWOOD CITY, CA 94062 650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9580

Page: 2

Name.

Date: 08/01/07 License #:4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage: 5633 VIN: 87270

Save Parts: YES

| | 10 20 1 | | | |
|---------|---------------------------------|-------|-----|--------|
| PARTS | All parts new unless specified. | PRICE | QTY | AMOUNT |
| 117792 | FUEL FILTER | 36.15 | 2 | 72.30 |
| D8EVX | NGK SPARK PLUGS | 12.95 | 12 | 155.40 |
| 124228 | OIL FILTER | 29.50 | 1 | 29.50 |
| 122973 | A/C BELT | 25.99 | 1 | 25.99 |
| 126139 | IGNITION ROTOR | 65.01 | 2 | 130.02 |
| 137176 | AIR FILTER | 39.50 | 1 | 39.50 |
| 150075 | R/H END PLATE GASKET | 3.54 | 1 | 3.54 |
| 132452 | DISTR. SEAL | 75.20 | 2 | 150.40 |
| 150198 | DISTRIBUTOR GASKET | 4.31 | 2 | 8.62 |
| 150194 | END PLATE GASKET | 4.98 | 1 | 4.98 |
| 150195 | L/H CAM COVER GASKET | 47.65 | 1 | 47.65 |
| 150196 | R/H CAM COVER GASKET | 47.65 | 1 | 47.65 |
| 127649 | C.C. O-RING | 7.74 | 12 | 92.88 |
| 105661 | BOOSTER O-RING | 1.95 | 1 | 1.95 |
| 116750 | CAM BELT TENSIONER BEARING | 67.85 | 2 | 135.70 |
| 114639 | CAM SEAL | 7.87 | 4 | 31.48 |
| 117036 | CAM BLOCK O-RING | 5.67 | 4 | 22.68 |
| 144740 | DISTRIBUTOR CARBON BUTTON | 14.82 | 2 | 29.64 |
| 154401 | CAM BELT [UPDATED] | 49.64 | 1 | 49.64 |
| 117583 | VALVE SHIM | 12.14 | 4 | 48.56 |
| 22X27 | DRAINWASHER | 0.70 | 3 | 2.10 |
| 16 X 22 | WASHER | 0.65 | 4 | 2.60 |
| 12X18 | COPPER WASHER | 0.65 | 2 | 1.30 |
| | SWEPCO GEAR OIL | 5.00 | 19 | 95.00 |
| COOLAI | 7.1.22.00 | 15.95 | 3 | 47.85 |
| | SWEPCO ENGINE OIL | 5.00 | 15 | 75.00 |

MODENA MOTORS 111 EL CAMINO REAL REDWOOD CITY, CA 94062 650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475] R/O#:9580

Page: 3

Name:

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage: 5633

VIN: 87270

Save Parts: YES

| PARTS All parts new unl | less specified. | PRICE | QTY | AMOUNT |
|-------------------------|------------------------|-------|-----|--------|
| 503 SWEPCO | FUEL ADDITIVE | 5.95 | 1 | 5.95 |
| MERC. | BRAKE FLUID [.75L] | 13.95 | 4 | 55.80 |
| 125772 | A/P BELT 10 X 900 | 17.98 | 1 | 17.98 |
| 14X18 | COPPER WASHER | 0.60 | 2 | 1.20 |
| 114808 | CAM BOLT O-RINGS | 1.03 | 4 | 4.12 |
| 121788 | CAVI CLIP X4 | 2.30 | 4 | 9.20 |
| 121789 | CAVI CLIP X3 | 1.94 | 4 | 7.76 |
| 121790 | CAVI CLIP X2 | 2.10 | 4 | 8.40 |
| 133262 | POLYRIB ALT BELT 71449 | 15.90 | 1 | 15.90 |
| BRK | CLEANER | 3.95 | 8 | 31.60 |
| NPN | A/C COMPRESSOR O-RINGS | 2.50 | 2 | 5.00 |
| 10X14 | COPPER SEALING WASHER | 0.25 | 2 | 0.50 |
| 8X11 | COPPER FI WASHERS | 0.25 | 4 | 1.00 |
| 14X20 | A\I COP WASHER | 0.35 | 2 | 0.70 |
| 111182 | LIMITER CAP | 7.04 | 2 | 14.08 |

RECOMMENDATIONS AND TECHNICIANS NOTES

8/2/01 1:35PM ESTIMATE APPROVAL, TP CALL CUSTOMER @ 510-719-5045 ESTIMATE \$13500.00 - \$14500.00

TIRES ORIGINAL.

BRAKE MASTER/BOOSTER STICKY.

RETURN IN 300-500 MILES FOR INSPECTION AND ADJUSTMENTS.

| Original I | Estimate: 9, | 111.51 | | | | LABOR | 7,625.00 |
|------------|--------------|---------------|----------|-------|------------|---------------------|-------------|
| | h | ncreases to I | Estimate | | | PARTS | 1,531.12 |
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | 0.00 |
| Date | Time | ORaby | THOIC | Lamp. | TYCW TOTAL | SHIPPING & HANDLING | 30.00 |
| | | | | | | HAZARDOUS MATERIALS | 15.00 |
| | | | | | | SUB TOTAL | 9,201.12 |
| | | | | | | TAX | 122.49 |
| | | | 1 | | | TOTAL | \$ 9.323.61 |

| Authorized by : | Date: |
|-----------------|-------|
| | |

MODENA MOTORS 111 EL CAMINO REAL REDWOOD CITY, CA 94062

650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475] R/O#:9581

Name:

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI

Model: TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

LABOR

AMOUNT

DIAGNOSE INTERMITENT ENGINE CHECK LIGHT {SLOW-DOWN 7-12} COMING ON.

437.50

RUN D31 THERMAL COUPLER TESTS.

R&R DEFECTIVE 7-12 THERMAL COUPLER ECU.

REMOVE AND CLEAN THERMAL COUPLER PROBES.

PARTS 141037 All parts new unless specified.

THERMAL COUPLER ECU

PRICE 331.65

QTY AMOUNT

1

331.65

| | L | ncreases to H | Estimate | | |
|------|------|---------------|----------|------|-----------|
| Date | Time | OK'd By | Phone | Emp. | New Total |
| | | | | | |
| | | | | | |
| | | | | | |

LABOR 437.50
PARTS 331.65
SUBLETS .00
SHIPPING & HANDLING 5.00
SUB TOTAL 774.15
TAX 26.53
TOTAL 800.68

| Authorized by : | Date | 1 |
|-----------------|------|---|
|-----------------|------|---|



MODENA MOTORS
111 EL CAMINO REAL
REDWOOD CITY, CA 94062
650-368-5819 / FAX 8217
QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION
ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9582

Name .

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

| LABOR DIAGNOSE NO CLIMATE CONTROL FAN LOW SPEED OPERATION. REPLACE DEFECTIVE ELECTRONIC POWER TRANSISTOR FOR FAN SYSTEM [NOTE VIRGIN]. | | | | | |
|--|---------------------------------|-------|-----|--------|--|
| PARTS | All parts new unless specified. | PRICE | QTY | AMOUNT | |
| 127014 | FAN POWER TRANSISTOR W/BRACKET | 59.96 | 1 | 59.96 | |

| Iı | ncreases to E | Estimate | | |
|------|---------------|----------|--|-----------|
| Time | OK'd By | Phone | Emp. | New Total |
| | | | | |
| | | | | |
| | | | Increases to Estimate Time OK'd By Phone | |

| LABOR | 437.50 |
|---------------------|--------|
| PARTS | 59.96 |
| SUBLETS | .00 |
| SHIPPING & HANDLING | 5.00 |
| SUB TOTAL | 502.46 |
| TAX | 4.80 |
| TOTAL | 507.26 |

| Authorized by: | Date : | | U | S | [(| M | EK | CC |)۲ | 1 |
|----------------|--------|------|---|-----|----|---|----|----|----|---|
| | | 10.5 | | 407 | | | | | | |

MODENA MOTORS 111 EL CAMINO REAL REDWOOD CITY, CA 94062 650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION

ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9583

Name:

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

| LABOR A/C SERVICE | | | | |
|----------------------|--|-------------|-----------------|------------------|
| PARTS R-12 | All parts new unless specified. FREON | PRICE 59.95 | QTY 2.25 | AMOUNT 134.89 |

| Original I | Estimate: 27 | 70.68 | | | | LABOR | 125.00 |
|-----------------------|--------------|---------|-------|------|-----------|---------------------|--------|
| Increases to Estimate | | | | | PARTS | 134.89 | |
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | .00 |
| | | 1 | | | | SHIPPING & HANDLING | .00 |
| | | | | | | SUB TOTAL | 259.89 |
| | | | | | | TAX | 10.79 |
| | | | | | | TOTAL | 270.68 |

| | | ALIAMALIE DI L'INUV |
|-----------------|-------|---------------------|
| Authorized by : | Date: | CUSTOMER COPY |

MODENA MOTORS 111 EL CAMINO REAL REDWOOD CITY, CA 94062

650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9584

Name:

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI Model: TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

| LABOR | AMOUNT |
|---|--------|
| R&R DEFECTIVE INTAKE PLENUM RUBBER GASKETS. | 625.00 |
| DEDI A CE DETEDIODATED COOLANT HOCECLINDED INTAVE DI ENLIMO | |

| PARTS | All parts new unless specified. | PRICE | QTY | AMOUNT |
|--------------|---------------------------------|-------|-----|---------------|
| 121021 | INTAKE PLENUM RUBBER GASKETS | 24.94 | 4 | 99.76 |
| G/S | COOLANT HOSE | 2.95 | 20 | 59.00 |
| ZEBRA | S.S CLAMPS | 2.50 | 10 | 25.00 |
| G/S | HEATER HOSE | 2.50 | 2 | 5.00 |

| Original I | Estimate: 57 | 3.06 | | | | LABOR | 625.00 |
|------------|-----------------------|---------|-------|-----------------------------------|-----------|---------------------|--------|
| | Increases to Estimate | | | Action Color (U. 1886) 1428 a. e. | | PARTS | 188.76 |
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | .00 |
| | | 1 | 1 | | | SHIPPING & HANDLING | 5.00 |
| | | | | IE | | SUB TOTAL | 818.76 |
| | | | | | | TAX | 15.10 |
| L. | | | | | | TOTAL | 833.86 |

| Authorized by : | Date: | ALIAMALIED AADL |
|-----------------|-------|-----------------|
| | | CUSTOMER COPY |

MODENA MOTORS
111 EL CAMINO REAL
REDWOOD CITY, CA 94062
650-368-5819 / FAX 8217
QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION
ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9585

Name: Date: 08/01/07

License # : 4DGJ627 Make : FERRARI Model : TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

| LABOR | | | | AMOUNT |
|-------------------|--------------------------------------|-------|--------|---------------|
| R&R DEFECTIVE | | | 312.50 | |
| [NOTE CD CHANG | GER LOCATED ON TOP OF ACCESS PANEL]. | | | |
| PARTS All parts i | new unless specified. | PRICE | QTY | AMOUNT |
| 61571600 | FRONT DECK-LID GAS STRUTS | 44 67 | 2 | 89 34 |

| PARTS | All parts new unless specified. | PRICE | QTY | AMOUNT |
|--------------|---------------------------------|-------|-----|--------|
| 61571600 | FRONT DECK-LID GAS STRUTS | 44.67 | 2 | 89.34 |
| NPN | COTTER PINS | .35 | 4 | 1.40 |

| Original E | Estimate: 35 | ncreases to F | Estimate | 0 | ·=: | LABOR PARTS | 312.50 90.74 |
|------------|--------------|---------------|----------|------|-----------|---------------------|-----------------|
| Date | Time | OK'd By | Phone | Emp. | New Total | SUBLETS | .00 |
| | | | | | | SHIPPING & HANDLING | 5.00 |
| | | | | | | SUB TOTAL | 408.24 |
| | | | | | | TAX | 7.26 |
| | | | <u> </u> | | | TOTAL | 415.50 |

I hereby authorize the above named business to perform the repair work listed above along with necessary materials. You and your employees may operate the above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs. Thereto it is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, repair, or while road testing.

Authorized by : Date : UDIUMER CUPY

MODENA MOTORS 111 EL CAMINO REAL

REDWOOD CITY, CA 94062

650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475]

R/O#:9586

Name:

Date: 08/01/07 License #:4DGJ627 Make: FERRARI

Model: TESTAROSSA Year: 1990

Mileage : 5633 VIN : 87270

Save Parts: YES

| LABOR REBUILD WATERPUMP WITH ENGINE OUT. REPLACE OIL SEAL. PRESSURE TEST W/P. | 25 | | AMOUNT 625.00 | | | |
|--|-----------------------|-----------------|--------------------------|--|--|--|
| INSPECT AND REPLACE BULKHEAD COOLANT HOSES AND CLAMPS AS NEEDED. RETORQUE ALL HOSE CLAMPS. | | | | | | |
| REPLACE FUEL RETURN HOSES AND CLAMPS. | | | 125.00 | | | |
| CHECK FOR NO ELECTRIC WINDOW OPS ON DRIVERS SIDE, DOWN BUT NO UP. REPLACE FAULTY CONSOLE ELECTRIC WINDOW SWITCH. GLUE L/H WINDOW SEAL AND DOOR SEAL. R&R R/H DOOR PANEL FOR ACCESS, CLEAN AND LUBE WINDOW CHANNELS AND GUIDES. | | | 375.00 | | | |
| INSTALL OVERSIZE SCREWS IN FRONT SPOILER CHIN GAURD AND REPAINT DAMAGED AREAS. TOUCH UP FRONT GRILL BAY. | | | 125.00 | | | |
| TIGHTEN LOOSE R/H AND L/H DOOR LOUVERS. | | | 31.25 | | | |
| INSTALL MISSING FRONT SPOILER RUBBER PLUG. | | | .00 | | | |
| PARTS All parts new unless specified. GATES HOSE 101023 WATER PUMP O-RING | PRICE 2.95 5.92 | QTY 36 1 | AMOUNT 106.20 5.92 | | | |
| 100436 WATER PUMP NUT | 10.40 | 1 | 10.40 | | | |
| 100434 WATER PUMP LOCK TAB | 2.64 | 1 | 2.64 | | | |
| 10730321 WATER PUMP WASHER | .73 | 1 | .73 | | | |
| 130932 WATER PUMP SEAL | 33.15 | 1 | 33.15 | | | |
| 121165 W/P OIL SEAL | 8.75 | 1 | 8.75 | | | |

MODENA MOTORS 111 EL CAMINO REAL REDWOOD CITY, CA 94062 650-368-5819 / FAX 8217

QUALITY SERVICE, REPAIR, MECHANICAL RESTORATION ON FERRARI AUTOMOBILES EXCLUSIVELY [AA151475] R/O#:9586

Page: 2

Name:

Date: 08/01/07 License #: 4DGJ627 Make: FERRARI

Model: TESTAROSSA

Year: 1990

Mileage: 5633

Save Parts: YES

VIN: 87270

| PARTS All parts new un | less specified. | PRICE | QTY | AMOUNT |
|------------------------|---------------------|-------|-----|--------|
| GATES MPI | FUEL HOSE | 8.95 | 5 | 44.75 |
| ZEBRA 12 X 18 | HOSE CLAMP | 1.50 | 4 | 6.00 |
| 122944 | WATER OUTLET HOSE | 31.39 | 1 | 31.39 |
| NPN | SHEET METAL SCREWS | .45 | 5 | 2.25 |
| 615572500 | SPOILER RUBBER PLUG | 14.76 | 1 | 14.76 |

| Increases to Estimate | | | | | | |
|-----------------------|------|---------|-------|------|-----------|--|
| Date | Time | OK'd By | Phone | Emp. | New Total | |
| | | | | - | | |
| | | | | | | |
| | | | | | | |

| TOTAL | 1,824.55 |
|---------------------|--|
| TAX | 21.36 |
| SUB TOTAL | 1,803.19 |
| SHIPPING & HANDLING | 5.00 |
| SUBLETS | .00 |
| PARTS | 266.94 |
| LABOR | 1,531.25 |
| | PARTS SUBLETS SHIPPING & HANDLING SUB TOTAL |

| Authorized by : | Date: |
|-----------------|-------|
| | |

MODENA MOTORS 2745 SPRING STREET Unit D REDWOOD CITY, CA 94063 (650) 368-5819

EXCELLENCE WITHOUT COMPROMISE

Web/eMail modenamotors@yahoo.com

Fax #

R.O. 10032

Lic.

H.

Page:

Monday - Friday 8:am to 5:pm

Date

7 MAY 2008 AC244536033107

EPA

CAL000304454

1,237.50

Make FERRARI Model TESTAROSSA Miles 6,474.0

Year **1990**

Cell. #

Vin 87270

Sales: TP

License 4DGJ627 Eng. Type

Eng. No. F113 A040 *24775* Prod.

Unit Color: RED

T/L Tech. Amount

Description of Labor / Service Provided

TP

L-Mail/Pager/Remarks/PO: Fax:

Open Date 28 APR 2008 00:00

CHASSIS SERVICE NOTE EXTRA TIME FOR REMOVING AND CLEANING ALL CLOGGED BRAKE

Ready By: 7 MAY 2008 10:45

BLEEDERS.

REMOVE FRONT BRAKE PADS FOR PISTON RETRACTION.

CUSTOMER COMPLAINT:

FLUID LEAK FROM LEFT REAR.

DIAGNOSE AND REPORT.

COOLANT SURGE CAP NOT SEALING.

LH DIFF. SEAL WEEPAGE. CLEAN & REINSPECT DIFF.

REPAIR SURGE CAP SEALING SURFACE.

| TP | 165.00 |
|----|--------|
| IP | 105.00 |
| | |

| | Parts / Material | Description | Qty | Each \$ | Extended \$ |
|-----|------------------|--------------------|-------|---------|-------------|
| New | SWEPCO 503 | FUEL ADDITIVE | 1.00 | 7.50 | 7.50 |
| New | SWEPCO 15W-40 | ENGINE OIL | 14.00 | 8.50 | 119.00 |
| New | SWEPCO 80W-90 | GEAR OIL | 18.50 | 8.50 | 157.25 |
| New | ANTI FREEZE | SHELLZONE | 2.50 | 15.95 | 39.88 |
| New | 124228 | OIL FILTER | 1.00 | 30.80 | 30.80 |
| New | MERC. | BRAKE FLUID [.75L] | 2.50 | 15.95 | 39.88 |
| New | BRK | CLEANER | 3.00 | 3.95 | 11.85 |
| New | 22X27 | DRAIN WASHER | 4.00 | 0.95 | 3.80 |
| New | 16X22 | DRAIN WASHER | 2.00 | 0.85 | 1.70 |
| | | | 1.00 | 0.00 | 0.00 |

Recommended MINOR OIL WEEPAGE FROM LH DIFF SEAL AREA. BRAKE PADS 50% WORN. MINOR FRONT BRAKE CALIPER DRAG. Repairs / Notes FRONT SPOILER SCRAPPED.

Original Estimate:

\$ 1,868.12 X:

I acknowledge notice and oral approval of an increase in the original estimated price

Revision #1

Payment 1:

.00

Revision #2

Revision #3 .00

Increase

0.00

Increase

0.00

Increase

.00 0.00

I hereby authorize the above named business to perform the repair work listed above along with necessary materials. You and vour employees may operate the above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs. Thereto it is understood that this company assumes no responsibility for loss or damage to vehicle/s placed with them for storage, repair, or while road testing

Account # 21 Payment 2:

Kev#

Tot.Before Sales Tax\$ 1,834.16

Total Sale

\$ 1,868.12

\$ 1,402.50

\$ 20.00

\$ 0.00

\$ 20.00

\$ 411.66

\$ 0.00

\$ 33.96

.... 0.00 Thank You From: MODENA MOTORS

Total Due

Labor

Parts

Sublet

Environmental:

Shop Supplies

Sub Total Charges

Total Sales Tax

\$ 1,868.12

MODENA MOTORS 2745 SPRING STREET Unit D **REDWOOD CITY, CA 94063** (650) 368-5819 EXCELLENCE WITHOUT COMPROMISE

Web/eMail modenamotors@yahoo.com

Fax #

R.O. 10150

Page:

Monday - Friday 8:am to 5:pm

Date Lic.

18 APR 2011 AC244536033107

EPA

CAL000304454

1.125.00

150.00

Make FERRARI Model TESTAROSSA Miles 6,717.0

Vin 87270

Year 1990

Cell. #

Sales: TP

License 4DGJ627 Eng. Type

Eng. No. F113 A040 *24775* Prod.

Unit Color: RED

E-Mail/Pager/Remarks/PO: Fax: Open Date 6 APR 2011 00:00

Ready By: 7 APR 2011 15:45

Description of Labor / Service Provided

H. T/L Tech. Amount

TP

TP

CUSTOMER REQUEST:

COMPLETE CHASSIS SERVICE.

CUSTOMER REQUEST:

REMOVE DRIVERS SIDE SEAT FOR SUBLET REPAIR.

SUBLET REPAIR TO REPAIR LEFTHAND UPPER SIDE BOLSTER WEAR WITH

SPRAY MATCHING.

VALET SEAT TO UPHOLSTERY SHOP FOR REPAIRS.

REINSTALL SEAT.

| | Parts / Material | Description | Qty | Each \$ | Extended \$ |
|-----|------------------|--------------------|---------|---------|-------------|
| New | SWEPCO 15W-40 | ENGINE OIL | , 13.00 | 8.50 | 110.50 |
| New | SWEPCO 80W-90 | GEAR OIL | 18.50 | 8.50 | 157.25 |
| New | SWEPCO 503 | FUEL ADDITIVE | 1.00 | 7.50 | 7.50 |
| New | MERC. | BRAKE FLUID [.75L] | 2.00 | 18.95 | 37.90 |
| New | 124228 | OIL FILTER | 1.00 | 59.96 | 59.96 |
| New | 22X27 | DRAIN WASHER | 4.00 | 1.25 | 5.00 |
| New | 16X22 | DRAIN WASHER | 2.00 | 1.20 | 2.40 |
| New | SHELLZONE | ENGINE COOLANT | 2.50 | 15.00 | 37.50 |
| New | BRK | CLEANER | 1.00 | 3.57 | 3.57 |
| | | | 1.00 | 0.00 | 0.00 |

Miscellaneous/Sublet Charges

COOKS UPHOLSTERY AIR BRUSH DRIVERS SIDE LEFTHAND SIDE BOLSTER AND REPLACE DEFECTIVE STRAP SNAP.

Amount 110.00

Recommended BRAKE PADS 50% WORN. MINOR FRONT BRAKE CALIPER DRAG. LAST MAJOR SERVICE W/CAM BELTS 03/2001 @5633 Repairs / Notes MILES - OVERDUE

Original Estimate:

\$ 1,865.58 X: X:

I acknowledge notice and oral approval of an increase in the original estimated price

Revision #1

.00

Revision #2

.00 Revision #3

Increase

0.00

Increase

0.00

Increase

.00 0.00

I hereby authorize the above named business to perform the repair work listed above along with necessary materials. You and your employees may operate the above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs. Thereto it is understood that this company assumes no responsibility for loss or damage to vehicle/s placed with them for storage, repair, or while road testing.

Parts Environmental: \$ 1,275.00 \$ 421.58

Shop Supplies Sub Total Charges \$ 20.00 \$ 0.00

Sublet

Labor

\$ 20.00 \$ 110.00

Total Sales Tax

\$ 39.00

Tot.Before Sales Tax\$ 1,826.58

X: Payment 1:

.... 0.00

Account # 21

Payment 2:

Key#

0.00

Total Sale Total Due

\$ 1,865.58

Thank You From: MODENA MOTORS

\$ 1,865.58

GP Enterprises LLC

Mailing: 555 Bryant St., #505, Palo Alto, Ca 94301 Date: May 29, 2013

Shop: 3014 Rolison Road, Redwood City, CA 94063

Phone: 650-766-5405 FAX: 650-766-5405 email: gpenterprise@yahoo.com

BAR #: AJ241640

Ferrari TR #87270

Invoice Number: 13-030

| Quantity 1 | Description parts | Unit Price | Total 2000.00 |
|---------------|-------------------|------------|------------------|
| ** | GP Labor: | | |
| 46.0 | major service | 105.00 | 4830.00 |

Authorized By:

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above the above vehicle for purposes of testing. Inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of the repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, sale, repair or while road testing. Used/replaced parts will be available upon my request

GP Enterprises LLC

Mailing: 555 Bryant St., #505, Palo Alto, Ca 94301 Date: May 29, 2013

Shop: 3014 Rolison Road, Redwood City, CA 94063

Phone: 650-766-5405 FAX: 650-766-5405 email: gpenterprise@yahoo.com

BAR #: AJ241640

Ferrari TR #87270 6902 miles

Invoice Number: 13-030

Pt 243 6 - 11-13

| Quantity | Description | Unit Price | Total |
|----------|---------------------------------|------------|--------|
| 1 | oil filter | 65.00 | 65.00 |
| 1 | air filter | 62.04 | 62.04 |
| 2 | fuel filter | 35.50 | 71.00 |
| 1 | valve cover gasket kit | 386.11 | 386.11 |
| 1 | camseal kit | 174.76 | 174.76 |
| 2 | cambelt | 98.95 | 197.90 |
| 2 | cambelt tensioner bearing | 155.16 | 310.32 |
| 1 | air pump belt | 17.84 | 17.84 |
| 1 | alternator belt | 19.36 | 19.36 |
| 1 | AC belt | 28.90 | 28.90 |
| 1 | 1-6 oil drain hose | 57.90 | 57.90 |
| 1 | 7-12 oil drain hose | 39.46 | 39.46 |
| 12 | spark plug | 20.38 | 244.56 |
| 1 | water pump o-ring | 5.95 | 5.95 |
| 1 | water pump oil seal | 16.08 | 16.08 |
| 1 | water pump impellor seal | 50.62 | 50.62 |
| 1 | water pump seal - housing | 119.10 | 119.10 |
| 10 | engine bay cooling system hose | 7.85 | 78.50 |
| 2 | cylinder head connection hose | 9.20 | 18.40 |
| 3 | feet coolant return/bleed line | 4.30 | 12.90 |
| 5 | feet fuel injection return line | 3.25 | 9.75 |

| 12 | valve adjust shim | 8.10 | 97.20 |
|---|--|--|-----------|
| 17 | quart 15-50 Mobil 1 engine oil | 8.95 | 152.15 |
| 2 | zinc substitute oil additive | 19.45 | 38.90 |
| 20 | pint Swepco gear oil | 7.95 | 159.00 |
| 5 | gallon coolant - extended life type | 12.95 | 64.75 |
| 1 | fuel system cleaner | 7.50 | 7.50 |
| 6 | pint LMA brake fluid | 5.45 | 32.70 |
| 1 | misc hardware: sealing rings, washers, etc | 15.00 | 15.00 |
| 1 | misc shop chemicals: cleaners, sealers, etc | 18.00 | 18.00 |
| | Parts Subtotal | | 2571.65 |
| | | | 00.00 |
| | | | |
| ** | Outside Labor: | | |
| 1 | evacuate/retrofit to R134/recharge AC | 250.00 | 250.00 |
| ** | system | | |
| Name and Add was able and tolk one and tolk tolk tolk | Outside Labor Subtotal | | 250.00 |
| | | | |
| ** | GP Labor: | | |
| 46.00 | 30k major service inc. valve adjust, all belts | 105.00 | 4830.00 |
| ** | fluids, etc. per factory recommendations | 100.00 | 103 010 0 |
| 6.00 | replace engine bay cooling system hoses | | 630.00 |
| 0.50 | replace fuel injection return lines | | 52.50 |
| 0.00 | replace tast ingestion results and | | |
| | GP Labor Subtotal | | 5512.50 |
| | | | |
| ** | Hazardous Waste Fees: engine, trans oils, co | polant. | 30.00 |
| ** | brake fluid | | |
| ** | Shipping | | 15.00 |
| | | | |
| | TOTAL DUE | 4 Mil Spr 100 Sty 100 Sto Sm 100 St 1 | (8379.15) |
| | 101111111111111111111111111111111111111 | | |
| | | | Day O CHE |

PAID CHECK GHH13 G/XD

Notes:

- 1. tire date codes: LF 2205, RF 1905, LR 1906, RR 1906
- 2. brake pads: fronts 70% remaining, 80% rears

| A . 1 | 1 | T | |
|-------|---------|------|-----|
| Ant | horizad | LZ z | 7 . |
| Auu | horized | DY | |

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above the above vehicle for purposes of testing. Inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of the repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, sale, repair or while road testing. Used/replaced parts will be available upon my request

GP Enterprises LLC

Mailing: 555 Bryant St., #505, Palo Alto, Ca 94301 Date: Oct. 13, 2015

Shop: 3014 Rolison Road, Redwood City, CA 94063

Phone: 650-766-5405 FAX: 650-474-0779 email: gpenterprise@yahoo.com

BAR #: AJ241640

Ferrari TR #87270 7478 miles

Invoice Number: 15-087

| Quantity Parts: | Description | Unit Price | Total |
|-----------------|--|------------|------------------|
| 2 | hood strut (Mondial type) | 108.98 | 217.96 |
| | Parts Subtotal TAX | | 217.98 Resale |
| GP Labor: 1.50 | R&R both front hood struts – see note #1 | 150.00 | 225.00 |
| | GP Labor Subtotal | | 225.00 |
| | TOTAL DUE | | 442.98 |

Notes:


1. Had to remove CD changer to access lower portion of strut

Authorized By:

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above the above vehicle for purposes of testing. Inspection or delivery at my risk. An express mechanics lien is acknowledged on the above vehicle to secure the amount of the repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to vehicles placed with them for storage, sale, repair or while road testing. Used/replaced parts will be available upon my request

| OTY. | PARTS AND MATERIALS | PRIC | CE | car | repa | 49 | SCOTTS | TTS VALLEY, CA 95066 USA WWW.canepa co | | 3/ | 068 |
|--------|---|---|------------------------|---|---|------------------------|----------------------|--|--|--|--------------------|
| | अध्यक्ष देशकार्य अध्यक्षित स्थापिक देशकार्य । | 32 | 35 | Canepa | - P | | | 831-430-9940 | | DATE OPEN | /2017 |
| | -ignition system ligk 7162 | | | পণ্ডটো Scot | to Valley E | | | ORDER WRITTEN E | | DATE CLOSED | |
| 7 | rear dacklid shock -body, 61498100 | 102 | 50 | | | | | Amanda | | | 2019 |
| 1 | gal sea foam motor treatment -fuel | 73 | 73 | SCOTTS Val | ley CA 950 | 66 | | JOENSE NUMBER | 37 C. | ^{ЈОВ} * 5 | 701 |
| | injection system of 128 | | | YEAR, MAKE AND MODE | 1990 Ferrari T | estarossa | | ODOMETER IN | 7565 | ODOMETER O | UT/570 |
| 1 | Intake tract boot boot air inlet | 121 | 25 | colonaed | VIN 2 F F : | G 1 | 7 A | 2 1 0 0 8 7 2 | 70 | PRODUCTION DATE | 11/90 |
| 3 % | intake system, 124371 | | | | DE | CRIPTION | OF WOF | K. T. | | UOMA | INT |
| 2 | 225 S0r16 tire of goodrich gforce | 262 | co | Mechanical & | Paint/Body De | DI . | | | | | |
| | sport comp 2 92w -front tires | | | 111 | 0 | | 0 | (0) | 1 | | |
| 1 | 25wr6gfspc2 03450 | | | 42, | hours | nt 5 | 75 | perhour | 9 | 360. | 50 |
| 2 | 255 50zr16 tire bf goodrich gforce | 324 | 00 | | | | | | | | |
| | sport comp 2 99w -rear tires, | | | Restoration/D | etail Dept. | | | | | | |
| A | SSwr6gtspc2 29304 | | | M | 553 | | 11 | 6.0 | | | |
| 1 | california tire fee | 1.7 | 00 | 53, | hours | rt 5 | 63 | per hour | 3 | 520- | 10 |
| 1 | paint materials: tape, masking paper | 35 | 00 | | | | 11. | | | | |
| | sandpaper, erc. | Part Control | | | | | | | | | |
| 1 | detail materials, wax, polish | 278 | 50 | | | W118 | | | | | Art Brasellication |
| | dressing, etc. | | | Evelik i | | | | | | | and an experience |
| 1 | consumables | 194 | 50 | | | | | | 4 10 | 201 | |
| 1 | set wheel weights | 10 | 00 | 1ST EST | REV. EST. | DATE T | IME | LABOR | 7 | 201. | 100 |
| PAIF | RS, FUEL, TRANSPORTATION, MISCELLANEOUS EXPEN | SES ETC | | CONTACTED BY: | AUTHORIZED BY: | PHONE | NO. | PARTS | | 10, | 34 |
| | k N' Travel pick up car in | 166 | 70 | REVISION DETAILS: | | | | SUBLET MATERIALS | _ < | 78 | |
| - | | | | NOTICE TO CONCINCO, IN CA | SE READ IMPORTANT WARR | NOTE INTERNATIONAL | H ON BAON | FREIGHT | | 117. | 13. |
| 2111 | ont and bring to Canepa shop | | | TERMS: This is not a Rev | olving Credit Transaction. | After the 10th of 1 | the month | FUEL | | 40 | 55 |
| iel | | 40 | 99 | following the date of this is to difficulty, Impracticality | of ascertaining expenses | for negotiating. | servicing, | EPA | 116 | 75 - | |
| eig | ht (parts/sublet)-Canepa | 0 | 00 | collecting and enforcing the charge of 1½% per month Purchaser is responsible to | th If legal action is requir | ed to collect this | account, | TIRE DISPOSAL | | The Control of the Co | |
| eig | ht (parts) | 111 | 31 | of service charge is not a ACKNOWLEDGEMENT | n alternative to payment in IS MADE of receipt of a | full. | | | 7 | 2- | |
| aza | rdous materials disposal fee | 25 | 00 | | CASH OR APPROVED CRE | | | TAX | 6 | 16500 | 4 |
| or and | | | | I hereby authorize you to perio Your employees may operate vi- be responsible for loss or dan | shicle for inspection, testing, or | d delivery at my risk. | You will not | TRANSPORT | / | 60. | 10 |
| | | | | storage on vehicle left more than THAT YOU HAVE AN EXPRES | n 48 hours after natification that | repairs are complete | CHARGES | TOTAL 3- | 11 | 11 | |
| | | | | FOR PARTS AND LABOR FUR FROM ANY PRIOR REPAIR OF | RNISHED UNDER THIS REPAIR RDEAS ON THE VEHICLE. IF I | R ORDER INCLUDI | NG THOSE CHARGES, | INVOICE \$ | 6/ | 16 | |
| | | 16.44 | | I AGREE THAT THE VEHICLE THE EVENT OF LEGAL ACTION | MAY BE HELD UNTIL ALL CI | ARGES ARE PAID | IN FULL IN | 1 acknowledge notice and oral approval | of an increase | in the original estin | nate.* |
| - | | THE RESERVE AND ADDRESS OF THE PARTY OF THE | Commission of the last | COLLECTION AND FEES. | | | Total Control of | HAVE THE RESIDENCE OF THE PARTY | SECULO DE LA COMPANSIONA DEL COMPANSIONA DE LA C | STATE OF THE PARTY | |

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650



Labor Operations

Major service for time. Spark plugs recent, so was air filter. Neither were changed. Use oil and filter supplied by owner. Including adjust valves, torque cylinder heads, replace all belts, timing belt tensioner bearings and cam seals. Replace all fluids and oil filter. Tune motor, recharge A/C, tighten suspension fasteners. Inspect entire car with particular attention paid to tires, brakes, suspension and steering. Correct tire pressures, adjust parking brake, test exterior lights and test drive.

Install Newman differential housing supplied by owner. With no changes in shims the preload on carrier bearings is far too tight and There is no backlash. Remove, reinstall carrier 4 times and remove carrier bearing cones 4 times to get proper preload and backlash.

Remove broken drain plug from right cylinder head. Every drain plug in car overtightened and a sealant was used. Plugs in heads so tight the threads were damaged. I removed the broken off plug and repaired the threads on both sides but great care needs to be taken to get plugs started in threads. Threads very weak due to being over tightened. Plug repair failed pressure test. I had to redrain system, use sealant on plugs. Refill and repressure test. Right head drain still leaks. Drain system again. Order longer generic metric plugs and install. Refill and repressure test. Finally passes pressure test.

I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

left in vehicle in case of fire or theft or any other cause beyond our control.

Signed X

Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement intervals for timing belts. If your car is equipped with timing belts, ask for details.



| Year | 1990 |
|---------|-------------------|
| VIN | ZFFSG17A2L0087270 |
| Assy. # | 4500 |
| Miles | 11022 |
| License | None |

\$6,350.00

Amount

\$3,100.00

\$900.00

Parts
Sublet
Labor \$10,350.00
Tax
Total See last page

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650



Labor Operations Amount

Excessive amounts of sealant used on valve covers and cam seal housings. It was used in many areas no sealant is supposed to be used. It took a considerable amount of time to clean it all off prior to reassembly. Sealant was used on cam sprocket bolts getting silicone sealant inside oil pressurized cams. A pice of sealant in cam oiling system has caused the failure of many of these engines and needs to be cleaned out.

Clean sealant from cams. \$600.00

Still has original evap hoses in engine bay. Replace 4 hoses in front of engine from tanks to pipe.

Incl. Still has original fuel tank air vent hoses in front of engine. Replace. Incl.

Car was converted to run R134a refrigerant in the AC system. I do not consider this a good idea and have no idea why it was done. The system will not work as well and the hoses are not built to properly contain it. I was planning on refilling with R12 but the system was filled with an incompatible oil. It would have required draining and flushing the compressor, flushing the rest of the system and replacement of the dryer. For the sake of keeping as close as possible to the estimate I chose to refill with R134a. I did test the entire compressor area for leakage and found none.

Repair threads at right bank thermocouple. Damaged from overtightening and flared end so would not go back together.

I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

Parts left in vehicle in case of fire or theft or any other cause beyond our control. Sublet Signed X Labor

Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement

intervals for timing belts. If your car is equipped with timing belts, ask for details.

Tax

Total See last page

\$50.00

\$650.00

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650

| Invoice # | 222 | Make | Ferrari | Year | 1990 |
|-----------|--------------|-----------|------------|---------|-------------------|
| Date | 5/5/2021 | Model | Testarossa | VIN | ZFFSG17A2L0087270 |
| Name | Brian | Alexander | | Assy. # | 4500 |
| Address | | | | Miles | 11022 |
| Phone | 281-804-0659 | | | License | None |

Amount

Incl.

Incl

See last page

Labor Operations

Replace torn wiper blades. The only way to get exact type blade refills is to get and strip for parts entire arms and install on OE arms

Broken round C12 connector at F.I. relay box. Install new connector. Incl.

Air injection check valves rusting out. Replace valves.

Recalculate clutch preload and reshim. \$75.00

Adjust latches engine cover.

| | | abor page 1 | \$10,350.00 |
|--------|-------------|--------------|--|
| / | I | Labor page 2 | \$650.00 |
| | I | abor page 3 | \$75.00 |
| | 2222 | Total labor | \$11,075.00 |
| • 1 | Disco | ounted labor | \$500.00 |
| | | | \$10,575.00 |
| | | | |
| | | 16 4 | |
| | | | and the same of th |
| Sublet | Description | | Amount |
| FedEx | Shipping | | \$17.00 |

I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

| left in vehicle in case of fire or theft or any other cause beyond our control. | Parts | |
|---|--------|---------|
| Signed X | Sublet | \$17.00 |
| | Labor | \$75.00 |
| Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement | Tax | |

Total

intervals for timing belts. If your car is equipped with timing belts, ask for details.

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650

| Invoice # | 222 | Make | Ferrari | Year | 1990 |
|-----------|--|-----------------|--|---------|-------------------|
| Date | 5/5/2021 | Model | Testarossa | VIN | ZFFSG17A2L0087270 |
| Name | Brian | Alexander | | Assy. # | 4500 |
| Address | | | | Miles | 11022 |
| Phone | 281-804-0659 | | | License | None |
| Part # | | Description | | Qty. | Amount |
| 127649 | | O ring | | 12 | \$89.16 |
| 150198 | | Gasket | | 2 | \$36.70 |
| 137644 | | Radiator cap | | 1 | \$29.25 |
| 199820 | | Alt belt | | 1 | \$18.00 |
| 122973 | | AC belt | | 1 | \$64.05 |
| PT512R | | Tensioner pulle | ey | 2 | \$170.00 |
| 139555 | | Bushing | | 1 | \$103.79 |
| 104756 | | O ring | | 1 | \$11.73 |
| 104747 | | O ring | | 1 | \$1.68 |
| 103017 | | O ring | | 1 | \$19.71 |
| 141509 | | Seal | | 1 | \$108.18 |
| 133628 | | Seal | 5 - 5 | | \$108.18 |
| 123236 | | Seal | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | 5 | \$22.50 |
| 95860063 | | Seal | TITLE | 1 | \$2.05 |
| 101033 | The same of the sa | Seal | 1910 | -1 | \$2.50 |
| 101030 | | O ring | 1999 | 1 | \$2.00 |
| 150195 | | Valve cover gas | sket | 1 | \$122.75 |
| 150196 | | Valve cover gas | sket | 1 | \$122.75 |
| 150194 | pang pantang and angular stangers | End gasket | 5 | I | \$24.00 |
| 150075 | | End gasket | | 1 | \$10.00 |
| 114639 | | Seal | | 4 | \$81.00 |
| 117036 | | O ring | | 4 | \$30.00 |
| 10257060 | | Drain plug seal | | 7 | \$7.00 |
| 101496 | | Drain plug seal | | 2 | \$2.00 |

I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

| left in vehicle in case of fire or theft or any other cause beyond our control. | Parts | \$1,188.98 |
|---|--------|---------------|
| Signed X | Sublet | |
| | Labor | |
| Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement | Tax | |
| intervals for timing belts. If your car is equipped with timing belts, ask for details. | Total | See last page |

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650


| Invoice # | 222 | Make | Ferrari | Year | 1990 |
|-----------|--------------|-----------------|------------|---------|-------------------|
| Date | 5/5/2021 | Model | Testarossa | VIN | ZFFSG17A2L0087270 |
| Name | Brian | Alexander | | Assy. # | 4500 |
| Address | | | | Miles | 11022 |
| Phone | 281-804-0659 | | | License | None |
| Part # | | Description | | Qty. | Amount |
| 10265160 | | Drain plug seal | | 2 | \$5.00 |
| 10261860 | | Drain plug seal | | 2 | \$3.00 |
| 154401 | | Timing belt | | 2 | \$68.00 |
| 518 | Permatex | Sealant | | 1 | \$15.00 |
| 114808 | | O ring | | 4 | \$19.96 |
| 109640 | | O ring | | 1 | \$12.24 |
| 10300740 | | Plug | | 2 | \$37.00 |
| 123263 | | O ring | | 1 | \$6.35 |
| 121769 | | Check valve | | 2 | \$120.00 |
| 10977711 | | Screw | | 1 | \$0.90 |
| 146450 | | Washer | | 6 | \$1.80 |
| 12601471 | | Washer | 5 - 5 | | \$0.90 |
| C12 | | Large round ha | rness plug | 1 | \$48.00 |
| 10516670 | | Washer | ACT ! | 6 | \$3.00 |
| 109466 | | Shim | -117 | 6 | \$4.50 |
| 11197774 | | Washer | 0.000 | 6 | \$5.40 |
| 106850 | | Washer | | 3 | \$0.75 |
| 126919 | | Hose | UNUU / | 4 | \$12.00 |
| 125032 | Aeroquip | Hose | - 5 k | I | \$25.00 |
| 120469 | Aeroquip | Hose | / // | Y | \$55.00 |
| R134a | | Freon | / 0 | 1 | \$85.80 |
| NPN | | AC O ring | | 2 | \$2.00 |
| NPN | | Schrader valve | | 2 2 | \$2.00 |
| 40720a | Bosch | Wiper arm | | 2 | \$21.00 |

I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

| left in vehicle in case of fire or theft or any other cause beyond our control. | Parts | \$554.60 |
|---|--------|---------------|
| Signed X | Sublet | |
| | Labor | |
| Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement | Tax | |
| intervals for timing belts. If your car is equipped with timing belts, ask for details. | Total | See last page |

2105 RR620 S #105 Lakeway Texas 78734 512-294-9650

| Invoice # | 222 | Make | Ferrari | Year | 1990 |
|-------------|--------------|----------------|------------|---------|-------------------|
| Date | 5/5/2021 | Model | Testarossa | VIN | ZFFSG17A2L0087270 |
| Name | Brian | Alexander | | Assy. # | 4500 |
| Address | | | | Miles | 11022 |
| Phone | 281-804-0659 | | | License | None |
| Part # | | Description | | Qty. | Amount |
| 75w90 | Mobile 1 | Gear oil | | 20 | \$150.00 |
| 10261860 | | Oil drain seal | | 2 | \$3.00 |
| 125924 | | Exhaust bolt | | 1 | \$1.00 |
| 114748 | | Exhaust nut | | 1 | \$8.00 |
| Rotella ELC | NF | Coolant | | 6 | \$88.80 |
| DOT 4+ | Pentosin | Brake fluid | | 1 | \$20.00 |
| 12644401 | | Washer | | 4 | \$1.00 |
| 106850 | | Washer | | 4 | \$1.00 |
| 14496401 | | Washer | | 4 | \$2.00 |
| | | | | | |



I hearby authorize the above work to be done along with the necessary material and hereby grant you and or your employees permission to operate the vehicle herein described fot the purpose of testing and or inspection. An express mechanics lien is hereby acnowledged on this vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to the vehicle or items

| left in vehicle in case of fire or theft or any other cause beyond our control. | rarts | \$2,010.00 |
|---|--------|-------------|
| Signed X | Sublet | \$17.00 |
| | Labor | \$10,575.00 |
| Ferrari technical service bulletins # 1003, 1003/A and # 1215 dictate replacement | Tax | \$166.52 |
| intervals for timing belts. If your car is equipped with timing belts, ask for details. | Total | \$12,776.90 |

Donto

60 M10 90



SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|----------------|
| 05/09/25 | 6000552/1 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | lvisor / Tag # |
| | |

DEAN SPEDALE

| Work Phone | Vehicle Ident | Vehicle Identification Number ZFFSG17A2L0087270 | | |
|------------|---------------|---|--|--|
| | ZFFSG17A | | | |
| Home Phone | Delivery Date | In-Service Date | | |
| | 00/00/00 | 00/00/00 | | |
| Body | Color | License Number | | |
| | | | | |

Year Make Model Body Color License Number

1990 FERRARI TESTAROSSA RED

P087270C

| DESCRIPTION OF SERVICE AND PARTS | | AMOUNT |
|--|----------|--|
| | | |
| | | |
| #1 - MR FERMAJOR: PERFORM FERRARI MAJOR SERVICE | | |
| Perform Ferrari Major Service | | |
| Caused by | | |
| Requested Major Service. | | 15050 00 |
| Tech: RYAN FIELD(126) | | 17850.00 |
| Tech: VS(121) Installed PEN5W40 : PENNZOIL 5W40 | 9@15.00 | 150.00 135.00 |
| Installed MOB75W90 :MOBIL 1 75W90 GEAR OIL 1 QUART | 11@27.40 | |
| Installed 601458 :SYNTHETIC DOT 3 AND 4 BRAKE FL | 2@28.65 | |
| Installed 67546400 :FERRARI 20 IN BOSCH WIPER BLAD | 2@73.68 | |
| Installed PT512TR :CAM BELT PULLEY | 2@167.50 | |
| Installed FCCG014 :CAM COVER SET | 1@165.15 | A CONTRACTOR OF THE PROPERTY. |
| Installed 154401 :FERRARI TIMING BELT TESTAROSSA | 2@71.99 | Www.comeseeconstructures and the company of the com |
| Installed 150198 :FERRARI DISTRIBUTOR BASE GASKE | 3@39.76 | |
| Installed 105661 :O-RING | 1@3.50 | |
| Installed 114639 :SEAL RING | 4@46.23 | |
| Installed 114808 : FERRARI CAM BOLT O-RING 348/35 | 4@8.25 | 33.00 |
| Installed 117036 :O-RING | 4@13.00 | 52.00 |
| Installed 117792 :FERRARI FUEL FILTER 308/328/35 | 2@99.25 | 198.50 |
| Installed 119409 :FERRARI DISTRIBUTOR CAP CORK G | 2@17.30 | 34.60 |
| Installed 122973 :BELT, AC | 1@182.85 | 1 |
| Installed 124228 : TESTAROSSA OIL FILTER | 1@199.15 | |
| Installed 125772 :FERRARI TESTAROSSA AIR PUMP BE | 1@60.00 | |
| Installed 127649 :FERRARI CAM COVER SPARK PLUG S | 12@20.00 | 170000000000000000000000000000000000000 |
| Installed 132452 :CAM SEAL | 2@49.05 | |
| Installed 146694 :EXH GASKET | 6@22.00 | |
| Installed 146695 :EXH GASKET | 6@18.00 | 108.00 |
| | | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not | | |
| PARTS | | |

work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

| LABOR | |
|-----------------------|--|
| PARTS | |
| DEDUCTIBLE | |
| SUBLET | |
| SHOP SUPPLIES | |
| HAZARDOUS MATERIALS | |
| SALES TAX OR TAX I.D. | |
| SPECIAL ORDER DEPOSIT | |
| DISCOUNTS | |
| TOTAL DUE | |

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.



Ph: (770) 457-2699 | www.merlinautogroup.com

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

SERVICE DEPARTMENT HOURS

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/2 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

Work Phone Vehicle Identification Number

Year Make Model Body Color License Number
1990 FERRARI TESTAROSSA RED

P087270C

| DESCRIPTION OF SERVICE AND PARTS | | AMOUNT |
|---|------------------------------------|--------|
| Installed 146698 :EXH GASKET | 4@37.20 | |
| Installed 150075 :FERRARI END PLATE GASKET308/34 | 1@56.10 | 56.10 |
| Installed 150180 :NGK PLUG DR8EIX 6681 | 12@19.50 | |
| Installed 137176 :AIR FILTER | 1@191.20 | 191.20 |
| Freight: DHL | AND PRODUCTION AND AN ARCHITECTURE | 147.50 |
| Installed HARDWARE : HARDWARE1 | 8@1.25 | 10.00 |
| Installed DP16X1.5HBRS :BRASS PLUG | 2@12.00 | 24.00 |
| Freight: FEDEX | | 17.07 |
| Installed 4601622 :WINZER COPPER WASHER 16X22 460 | 3@3.05 | 9.15 |
| Installed 4601624 :WINZER COPPER WASHER 16X24 | 2@4.25 | 8.50 |
| Installed 4603541 :WINZER COPPER WASHER 35X41 | 2@4.15 | 8.30 |
| Installed 10261860 : COPPER WASHER M22 X 29 4602229 | 2@5.25 | 10.50 |
| Installed WIN0109 :WINZER BRAKE PARTS CLEANER - O | 2@10.25 | 20.50 |
| Installed 199822 :FERRARI ALTERNATOR BELT 348 | 1@49.96 | 49.96 |
| Installed 150192 :GASKET | 2@10.00 | 20.00 |
| Installed 150194 :VAC PUMP GSKT | 1@36.75 | 36.75 |
| Installed 5391625 :HOSE CLAMP NORMA M16 X 25 | 2@4.50 | 9.00 |
| Installed TB1211 :THREE BOND ENGINE SILCONE GASK | 1@47.68 | 47.68 |
| Installed H153 :5/8 INCH HEATER HOSE BULK PER | 1@3.75 | |
| Installed 12604274 :FERRARI/MASERATI CAM COVER/CLU | 8@1.10 | |
| Installed 5392032 :HOSE CLAMP M20X32 | 2@4.50 | 9.00 |
| Installed 53971627 :HOSE CLAMP | 1@3.50 | 3.50 |
| Installed ZEREXG48 :BLUE COOLANT 50/50 | 2@44.99 | |
| Installed 460610 :WINZER COPPER WASHER 6X10 | 1@1.50 | 1.50 |
| Installed 124792 :FERRARI SPARK PLUG EXTENSION T | 2@24.98 | 49.96 |
| Sub Total: Labor: 18000.00 Parts: 4146.59 Total: | 22146.59 | |
| Performed Testarossa Major Service: Removed | | |
| engine/transmission assembly. Performed oil and | | |
| filter service, gearbox/differential oil service, | | |
| | | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair LABOR | | |

work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

| LABOR | |
|-----------------------|--|
| PARTS | |
| DEDUCTIBLE | |
| SUBLET | |
| SHOP SUPPLIES | |
| HAZARDOUS MATERIALS | |
| SALES TAX OR TAX I.D. | |
| SPECIAL ORDER DEPOSIT | |
| DISCOUNTS | |
| TOTAL DUE | |

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.



SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/3 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

| Work Phone | | Vehicle Identification Number | | |
|------------|------------|-------------------------------|-----------------|--|
| | | ZFFSG17A | 2L0087270 | |
| | Home Phone | Delivery Date | In-Service Date | |
| | | 00/00/00 | 00/00/00 | |
| | Body | Color | License Number | |

Year Make Model Body Color License Number
1990 FERRARI TESTAROSSA RED
P087270C

| DESCRIPTION OF SERVICE AND PARTS | | AMO | TNUC |
|---|-----------------------|------|----------|
| brake fluid service, removed the timing covers, | | | |
| head covers and all associated fittings to access | | | |
| the camshafts and timing belts. Adjusted valve | | | |
| backlash for the camshafts. Cleaned all old | | | |
| sealant and residue from head surfaces. Replaced | | | |
| timing belts, timing belt tensioner roller | | | |
| bearings, ancillary drive belts, | | | |
| timing via degree wheel, replaced | d valve cover | | |
| gaskets, cam seal O-rings and sea | | | |
| gaskets, distributor seals and ga | | | |
| head covers. Cleaned all residue | | | |
| engine assembly. Replaced spark p | | | |
| extension with high resistance. F | | | |
| engine/transmission assembly to d | | | |
| exhaust manifold gaskets, any rus | | | |
| hardware, engine air filters, fue | | | |
| performed coolant system service. | . Tuned engine | | |
| | | | |
| #2 - MR MPI: PERFORM FULL VEHICLE MULT | II-POINT INSPECTION | | |
| Caused by | | | |
| Requested Inspection. | | anı. | 201 7017 |
| Tech: RYAN FIELD(126) | | | POLICY |
| Performed inspection and noted findings to repair | | | |
| order. | | | |
| #3 - MR FUELSYS: FUELSYS | | | |
| POSSIBLE GAS LEAK. DRAIN TANKS, E | REPLACE HOSES. | | |
| AND INSPECT OUTLET | , | | |
| Caused by | | | |
| 1 | | | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair | LABOR | | |
| work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any | PARTS | | |
| other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to | DEDUCTIBLE | | |
| operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure | SUBLET | | |
| the amount of repairs thereto." | SHOP SUPPLIES | | |
| DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by | HAZARDOUS MATERIALS | | |
| the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller | SALES TAX OR TAX I.D. | | |
| neither assumes nor authorizes any other person to assume for it any liability in connection with the | SPECIAL ORDER DEPOSIT | | |
| sale of said products. Any limitation contained herein does not apply where prohibited by law. | DISCOUNTS | | |
| | TOTAL DUE | L | |
| | | | |
| | | | |



SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/4 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

| | Work Phone | Vehicle Identi | fication Number |
|-----|------------|----------------|-----------------|
| | | ZFFSG17A | 2L0087270 |
| 0.0 | Home Phone | Delivery Date | In-Service Date |
| | | 00/00/00 | 00/00/00 |
| | Body Body | Color | License Number |
| | | RED | |

1990 FERRARI TESTAROSSA

P087270C

| Found lower gasoline pump and in leaking. Tech: RYAN FIELD(126) Installed HARDWARE: HARDWARE1 Installed BR4X10YLW: 4X10MM BOLT Installed WSIS4CLZ: SERRATED WASH Installed RHM145: BRAIDED HOSE Sub Total: Labor: 1350.00 Part Drained both fuel tanks, replaced hoses to pumps and cleaned corross and fittings. Filled with fuel an leakage. Complete. | 1@1.25 10@1.25 HER 10@0.99 4@15.10 ts: 84.05 Total: 1434.05 d interconnecting sion from outlets | 1350.00 1.25 12.50 9.90 60.40 |
|---|---|---|
| #4 - MR COOLING: CHECK AND ADVISE REMOVE AND REBUILD WATER PUMP Caused by Found evidence or coolant leakage at the water pump assembly. Tech: RYAN FIELD(126) Installed 100434 : FERRARI WATER PUMP ACORN NUT L 1@16.59 Installed 100436 : NUT 1@20.00 Installed 101023 : FERRARI WATER PUMP COVER O-RIN 1@12.56 Installed 121165 : FERRARI TESTAROSSA SEALING RIN 1@29.54 Installed 183759 : SEALING RING 1@56.32 Sub Total: Labor: 1800.00 Parts: 135.01 Total: 1935.01 During replacement of the timing belts: Removed funnel for water pump, inner impeller, water pump seal and shaft and oil seal. Cleaned all surfaces of old sealant and corrosion. Replaced the water | | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto." DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. | LABOR PARTS DEDUCTIBLE SUBLET SHOP SUPPLIES HAZARDOUS MATERIALS SALES TAX OR TAX I.D. SPECIAL ORDER DEPOSIT DISCOUNTS | |

DISCOUNTS TOTAL DUE

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

© 2016 DEALERTRACK TECHNOLOGIES - Dealership Application Group



SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/5 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

| Work Phone | | Vehicle Identification Number | | |
|------------|------------|-------------------------------|-----------------|--|
| | | ZFFSG17A | 2L0087270 | |
| | Home Phone | Delivery Date | In-Service Date | |
| | | 00/00/00 | 00/00/00 | |
| 16 据性 | Body | Color | License Number | |
| | | | | |

YearMakeModelBodyColorLicense Number1990FERRARITESTAROSSAREDP087270C

| DESCRIPTION OF SERVICE AND PARTS | | AMOUNT | |
|---|--|-----------------|--|
| pump seal, inner oil seal, refit | | | |
| and funnel with new O-ring. Teste operation. Complete. | ed system | | |
| operation. complete. | | | |
| #5 - MR PTIRE4: MOUNT AND BALANCE 4 PI | ERFORMANCE TIRES | | |
| Caused by | | | |
| Requested tire replacement. | | | |
| Tech: RYAN FIELD(126) | | 900.00 | |
| 3-4 TIRE DISPOSAL & WEIGHTS | | 100.00 | |
| Installed 24386 :225/50R16 MICH 1 | | 660.00 | |
| Installed 85852 :255/50R16 MICH I | PS 2@465.00 | 930.00 | |
| Freight: FEDEX Sub Total: Labor: 900.00 Parts | s: 1733.00 Total: 2633.00 | 43.00 | |
| Replaced all four tires, cleaned | | | |
| and performed road force balance | | | |
| wheel assemblies. Complete. | on all tile and | | |
| | | | |
| #6 - MR EXHAUST: EXHAUST | | | |
| INSTALL EXHAUST TEST PIPE | | | |
| Caused by | | | |
| Found exhaust test pipe for the | e right hand bank | | |
| rusted and coming apart. | | | |
| Tech: RYAN FIELD(126) | 18500 00 | 300.00 | |
| Installed 125899 :ANALYZING PIPE Freight: DHL | 1@500.00 | 500.00 30.85 | |
| Sub Total: Labor: 300.00 Parts | s: 530.85 Total: 830.85 | 30.65 | |
| Replaced test piping and tested | [10] 전 경제 [20] 전 경제()(전 20) - (20) 전 20) 전 20 전 20 전 20 전 20 전 20 전 20 | | |
| Complete. | 101 Icanago. | | |
| | | | |
| | | | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair | LABOR | | |
| work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any | PARTS | | |
| other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to | DEDUCTIBLE | | |
| operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure | SUBLET | | |
| the amount of repairs thereto." | SHOP SUPPLIES | | |
| DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by | HAZARDOUS MATERIALS | | |
| the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller | SALES TAX OR TAX I.D. SPECIAL ORDER DEPOSIT | | |
| neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. | DISCOUNTS | | |
| | TOTAL DUE | | |
| | | | |
| | | | |
| | | | |



SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/6 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

| Work Phone | | Vehicle Identification Number | | |
|------------|------------|-------------------------------|-----------------|--|
| | | ZFFSG17A2L0087270 | | |
| | Home Phone | Delivery Date | In-Service Date | |
| | | 00/00/00 | 00/00/00 | |
| | Body | Color | License Number | |
| | | | | |

Year Make Model Body Color License Number
1990 FERRARI TESTAROSSA RED
P087270C

| DESCRIPTION OF SERVICE AND PARTS | | | AMOUNT |
|---|---|----------|---------|
| #7 - MR DIAG: DIAGNOSE | | | |
| VEHICLE IS OVERHEATING, CHECK AND ADVISE | | | |
| Caused by | | | |
| During final inspection found | engine overheating. | | |
| Tech: RYAN FIELD(126) | | | 900.00 |
| Sub Total: Labor: 900.00 Part | | | |
| Performed infrared testing of the | | | |
| and found thermostats opening correctly. Found | | | |
| radiator fans not working. Elect | | | |
| the thermo-switch for the fans as | | | |
| switch work. Found that the sign | | | |
| is not there. Electrically tested the relay and fuse board and four | | | |
| resistance and damage to the fuse | | | |
| resistance and damage to the rus | e paner. | | |
| #8 - MR ELECTRICAL: ELECTRICAL | | | |
| REMOVE FUSE BOARD, HARNESS AND S. | END OUT FOR | | |
| REPAIRS | | | |
| Caused by | | | |
| Sublet for fuse panel repair. | | | |
| Tech: RYAN FIELD(126) | | | 3150.00 |
| Work performed by G.T.001 : 2467 | 32218 () Labor: | | |
| | Work performed by G.T.001 : 246732218 () Parts: | | 1722.00 |
| Installed 12278744 :TERMINAL 6@10.66 | | | |
| Freight: UPS NDA | | 37.00 | |
| Freight: FEDEX | | | 16.25 |
| Installed 0332014113 :BOSCH 30A | | 11@17.05 | |
| Installed 0332204101 :BOSCH RELA | Y | 7@16.75 | |
| Installed 6311155 : RELAY | | 1@48.45 | 48.45 |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair | LABOR | | |
| work hereinafter to be done along with the necessary material and agree that you are not | PARTS | | |
| responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in | DEDUCTIBLE | | |
| parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing | SUBLET | | |
| and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto." | SHOP SUPPLIES | | |
| DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by | HAZARDOUS MATERIALS | | |
| the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, | SALES TAX OR TAX I.D. | | |
| including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the | SPECIAL ORDER DEPOSIT | | |
| sale of said products. Any limitation contained herein does not apply where prohibited by law. | DISCOUNTS | | |
| | TOTAL DUE | | |
| | | | |
| | | | |
| NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS. | | | |



P087270C

9:00 a.m. to 6:00 p.m.

Monday - Friday
Closed Saturday & Sunday

| R/O Open Date | R/O Number |
|----------------|---------------|
| 05/09/25 | 6000552/7 |
| R/O Close Date | Status |
| 09/22/25 | Reprint |
| Mileage In | Mileage Out |
| 11208 | 11208 |
| Service Ad | visor / Tag # |

DEAN SPEDALE

| | | | Work Phone | Vehicle Identification Number ZFFSG17A2L0087270 | |
|------|---------|------------|------------|---|-----------------|
| | | | | | |
| | | | Home Phone | Delivery Date | In-Service Date |
| | | | | 00/00/00 | 00/00/00 |
| Year | Make | Model | Body | Color | License Number |
| 1990 | FERRARI | TESTAROSSA | | RED | |

DESCRIPTION OF SERVICE AND PARTS Freight: UPS 37.00 Sub Total: Labor: 3150.00 Parts: 507.46 Sublet: 1722.00 Total: 5379 Removed the fuse panel assembly and all fuses and relays to be repaired. Refit updated and repaired fuse panel. Installed fuses and relays. #9 - MR DIAG: DIAGNOSE Passenger window does not work, check and advise Caused by Inspected the window operation and found the regulator has too much play and is keeping the motor from being able to raise the window properly. Tech: RYAN FIELD (126) 900.00 Sub Total: Labor: 900.00 Parts: .00 Total: 900.00 Client has declined repair at this time for the window regulator. Complete. #10 -MR COOLING: CHECK AND ADVISE Complete replay replacement Caused by During extended test drive the fuse for the left hand radiator will randomly blow. Tech: VS(121) 600.00 Sub Total: Labor: 600.00 Parts: .00 Total: 600.00 Found that the old metal relays are retaining too much heat and will overheat the fuse panel popping the fuse for the left hand fan. Replaced all relays with updated plastic units that will TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair LABOR work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to **DEDUCTIBLE** operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing SUBLET and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure SHOP SUPPLIES the amount of repairs thereto. HAZARDOUS MATERIALS DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the SALES TAX OR TAX I.D. SPECIAL ORDER DEPOSIT sale of said products. Any limitation contained herein does not apply where prohibited by law. DISCOUNTS TOTAL DUE



© 2016 DEALERTRACK TECHNOLOGIES - Dealership Application Group

SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday

| R/O Open Date | R/O Number 6000552/8 | | |
|----------------|----------------------|--|--|
| 05/09/25 | | | |
| R/O Close Date | Status | | |
| 09/22/25 | Reprint | | |
| Mileage In | Mileage Out | | |
| 11208 | 11208 | | |
| Service Ad | visor / Tag # | | |

| | | | | DEAN SPEDA | LE |
|-----------|---------|---------------|------------|-------------------------------|-----------------|
| BULOT, AJ | | | Work Phone | Vehicle Identification Number | |
| 1 | | | | ZFFSG17A2L0087270 | |
| | | | Home Phone | Delivery Date | In-Service Date |
| | | | | 00/00/00 | 00/00/00 |
| Year | Make | Model I Model | Body | Color | License Number |
| 1990 | FERRARI | TESTAROSSA | | RED | |
| P0872 | 70C | | | | |

| DESCRIPTION OF SERVICE AND PARTS not overheat the system. Complete | e. | AMOUNT |
|---|--|----------|
| #11 -MR DIAG: DIAGNOSE During quality checks, noted that were inop, check and advise Caused by Found fuse panel overheating at light fuse. Tech: VS(121) Tech: RYAN FIELD(126) Sub Total: Labor: 900.00 Part Replaced old relays with updated not overheat the system. Complete | 300.00 | |
| #12 -MR INTERIOR: INTERIOR Repair driver door window seal, and replace necessary hardware. Caused by Found door panel assembly hardware has damaged the door trim seal Tech: RYAN FIELD(126) Installed EAP1447709 :LH & RH UP: Freight: FEDEX Removed door panel and frame mountrim channel seal for upper part Machined and fabricated correct hardware for the frame. Refit all and tested operation. Complete. | SRV POLICY SRV POLICY SRV POLICY | |
| TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair | Total Fees Amount | 28800.00 |
| work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any | PARTS | 7036.96 |
| other cause beyond your control or for any delays caused by unavailability of parts or delays in | DEDUCTIBLE | .00 |
| parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing | SUBLET | 1722.00 |
| and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto." | SHOP SUPPLIES | 500.00 |
| the amount of repairs thereto. | HAZARDOUS MATERIALS | .00 |
| DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, | SALES TAX OR TAX I.D. | 632.12 |
| including any implied warranty of merchantability or fitness for a particular purpose, and the seller | SPECIAL ORDER DEPOSIT | .00 |
| neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law. | DISCOUNTS | .00 |
| | TOTAL DUE | 38791.08 |
| | CUST DEPOSIT 3220/6000552 | 10000.00 |
| NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS. | CREDIT CARD 866720 | 28791.08 |
| | 1 | |