REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/1
Home Phone	**R/O Close Date**	**Receipt No.**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

			C
#1 - FUELSYS: FUELSYS 32602 FUELSYS REMOVE OLD HOSES, DISCONNECT ALL F UEL HOSES AT ENGINE TO BLOW THROUGH ALL HARD LINES -FUEL SYSTEM WAS OPEN TO ATMOSPHERE AND ANYTHING E LSE THAT WANTED TO MAKE A HOME, REMOVE IN/TANK FIL TER-CLEAN, REPLACE IN LINE FILTER, INSTALL REGULAR HOSE			
Work performed by Tech 116* 0.00hrs		4341.50	
@539812 : HOSE CLAMP M8 X 12 9MM	6@2.64	15.84	
@539812 : HOSE CLAMP M8 X 12 9MM	2@10.37	20.74	
CD6420R : O-RING	2@5.69	11.38	
CD6429R : A/C PRESSURE SW	1@136.24	136.24	
CD6429R : A/C PRESSURE SW	2@4.16	8.32	
CD6831R : O-RING	2@3.25	6.50	
HARDWARE : HARDWARE1	50@0.33	16.50	
HARDWARE : HARDWARE1	5@0.33	1.65	
HARDWARE : HARDWARE1	5@0.33	1.65	
H176 : NAPA 5/16 FUEL HOSE	2@3.24	6.48	
H177 : NAPA 3/8" FUEL LINE	8@3.50	28.00	
H348A : 1/4" FUEL INJECTION HOSE	10@9.09	90.90	
H351A : 1/2" FUEL INJECTION HOSE	15@12.34	185.10	
H351A : 1/2" FUEL INJECTION HOSE	1@3.63	3.63	
MIC0306 : HEAVY DUTY BLACK 1" ELASTIC MA	3@1.56	4.68	
MINUS20 : WASHER FLUID -20	1@6.36	6.36	
MT34 : INTERSTATE BATTERY MT34	1@163.74	163.74	
RH13682R : A/C COMP	1@557.43	557.43	
RH13682R : A/C COMP	1@487.73	487.73	
R134A : R134A REFRIGERANT	2@12.53	25.06	
R134A : R134A REFRIGERANT	1@312.87	312.87	
R134A : R134A REFRIGERANT	2@31.84	63.68	
R134A : R134A REFRIGERANT	1@273.90	273.90	
R134A : R134A REFRIGERANT	1@454.99	454.99	
R134A : R134A REFRIGERANT	1@292.55	292.55	
UR70293U : A/C HOSE ASM	1@362.17	362.17	
UR70317R : A/C REC/DRYER	1@117.00	117.00	
UR70317R : A/C REC/DRYER	1@9.14	9.14	
WHT002909 : BENTLEY/ROLLS ROYCE OIL DRAIN	1@8.33	8.33	
WIN0109 : WINZER BRAKE PARTS CLEANER - O	2@6.24	12.48	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)845-1028

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/2
Home Phone	**R/O Close Date**	**Receipt No.**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

WIN3533 : WINZER COPPER WASHER 12X16 460	2@0.56	1.12		
WIN3534 : WINZER COPPER WASHER 10X16	2@0.40	.80		
WIN3535 : WINZER COPPER WASHER 12X18 460	2@0.52	1.04		
WIN3536 : WINZER COPPER WASHER 14X18	2@0.65	1.30		
0004760421 : FUEL ACCUM	1@207.10	207.10		
07V121717A : BENTLEY OIL FILTER CORNICHE/B	1@50.00	50.00		
1156 : 1156 LIGHT BULB	1@0.43	.43		
117792 : FERRARI FUEL FILTER 308/328/35	1@68.19	68.19		
36805 : M5 X 80 ZY NYL LK NUT	1@0.34	.34		
5391220 : WINZER HOSE CLAMP M12X20	18@2.29	41.22		
5391220 : WINZER HOSE CLAMP M12X20	4@406.64	1626.56		

#2 - UCI: PERFORM USED VEHICLE INSPECTION 32602 DID USED CAR INSPECTION, RESULTS IN TRELL O. XTRA TIME INCLUDED FOR MOVING CARS TO ACCESS LA RGE LIFT — C
Work performed by Tech 116* 0.00hrs 450.00

#3 - FUELSYS: FUELSYS 32602 INSTALL FUEL LINE, Y PIPE, AND TANK FILTE R ACCESS SEAL. THESE ARE PARTS THAT WERE ORDERED F ROM ROLLS, ADDED FUEL, STARTED CAR, CHECKED AC-DOE SNT WORK-NO FREON. ADDED MINERAL OIL TO HYDRAULIC SYSTEM, CAR CAME UP TO RIDE HEIGHT, CAR GOES INTO GEAR. — C
Work performed by Tech 116* 0.00hrs 2181.12

#4 - MISC: MISC 32602 REAR WINDOWS BARELY MOVED, REMOVE PANELS FOR ACCESS, FOUND REWIRED WINDOW MOTOR HARNESS (WI RING EXTENSIONS USED TOO LITTLE WIRES-MAKING WIRIN G RED HOT WHEN RUNNING MOTORS, LOOSE CABLES ON WIN DOW UP ASSIST, GEAR DRIVE FOR CHAINS VERY SLOW, RE BUILT — C
Work performed by Tech 116* 0.00hrs 1041.48

#5 - INTERIOR: INTERIOR 32602 BOTH REAR WINDOWS INCREDIBLY SLOW, RT REA R DOOR INNER PANEL BROKEN, LEFT REAR DOOR SIDE IMP ACT BEAM BROKEN/RATTLING, ALL WIRING REDONE BY LIM O BUILDERS,WIRING TOO SMALL, RELAYS — C

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)945-1028

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/3
Home Phone	**R/O Close Date**	**Receipt No.**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

REMOVED CAUSIN G SLOW WINDOWS, REWIRED BOTH DOORS
REDONE BY LIM O BUILDERS,WIRING TOO SMALL, RELAYS
REMOVED CAUSIN G SLOW WINDOWS, REWIRED BOTH DOORS
WITH PROPER SIZ E WIR
Work performed by Tech 116* 0.00hrs 1350.00

#6 - INTERIOR: INTERIOR 32602 FOUND SEATS WOULD NOT MOVE, C
CHECKED FUSES -GOOD, CHECKED CONNECTIONS UNDER
SEATS, GOOD, TAPP ED ON MOTORS I COULD REACH-SEATS
IN LOWER POSITION HINDERING ACCESS TO MECHANISMS.
GOT DRIVERS SEAT TO MOVE IN 3 OF 4 DIRECTIONS,
GAINED ACCESS TO MEC HANIS
Work performed by Tech 116* 0.00hrs 1575.00

#7 - LIGHTS: CHECK AND ADVISE 32602 FOUND 1 HESADLIGHT (RT C
SIDE) OUT, RT SIDE MARKER LIGHT OUT, REMOVE AIR
CLEANER ASSEMBLY FOR ACCESS TO BULBS, HEADLIGHT
BULB REPLACED, FOUND M ARKER LIGHT SOCKET
DEFECTIVE DUE TO AGE, WATER ING RESS, CORROSION,
REMOVED HEADLIGHT ASSEMBLY FOR AC CESS,
Work performed by Tech 116* 0.00hrs 633.63

#8 - MISC: MISC 32602 FOUND WASHER PUMP INOP, CHECKED C
FUSE-GOOD , CHECKED VOLTAGE-GOOD, REMOVED PUMP-NOT
TURNING, LUBED PUMP MOTOR, GOT IT WORKING, CLEARED
MUNG FRO M WASHER HOSES AND SQUIRTERS, WORKS AS
NEW, REFAST ENED LOOSE WIPER ARM
Work performed by Tech 116* 0.00hrs 1131.36

#9 - HVAC: HVAC 32602 A/C FOUND COMPRESSOR LOCKED UP, C
REMOVE OLD COMPRESSOR AND FILTER/DRIER, MODIFY
DRIER MOUNTIN G POINTS TO FIT IN FACTORY LOCATION,
HAD TO UNBOLT LARGE FRONT MOUNT THAT COMPRESSOR
BOLTS TO TO ALI GN MOUNTING BOLTS, VACUUM AND
CHARGE WITH 2 3/4 PO UNDS
Work performed by Tech 116* 0.00hrs 2438.58

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)945-1028

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/4
Home Phone	**R/O Close Date**	**Receipt No**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

#10 -INTERIOR: INTERIOR 32602 TRIED TO REMOVE CLOCK, AFTER MARKET CLOCK . TRIED TO REMOVE PANEL ITS MOUNTED TO, HELD IN BY MIDDLE SEAT/TV BOX ASSEMBLY, WOULD REQUIRE REMOVA L OF SEATS AND BOX TO BEGIN TO GAIN ACCESS. C

Work performed by Tech 116* 0.00hrs 225.00

#11 -DIAG: DIAGNOSE 32602 FOUND BRAKE PAD LOW WARNING INDICATOR LIG HT ON, CHECKED PADS-OK, PULLED EACH SENSOR WIRE AT HARNESS CONNECTION TO SEE IF SENSOR WAS BAD, LIGH T STAYS ON, STILL GROUNDED SOMEWHERE IN HARNESS, C HECKED HARNESS FROM WHEELS TO DASHBOARD FOR SHORT TO GR C

Work performed by Tech 116* 0.00hrs 1350.00

#12 -LOF: OIL AND FILTER CHANGE SERVICE, TOP OFF ALL NECESSA RY FLUIDS, ADJUST TIRE PRESSURES 32602 DO OIL CHANGE, HAD TO JACK FRONT OF CAR O N LIFT FOR SUSP TO DROP FAR ENOUGH TO REMOVE AND R EPLACE FILTER, HAD TO CHARGE BATTERY(SOMEONE LEFT SWITCH ON) TO START CAR TO CHECK OIL LEVEL--9QTS 2 0W50 C

Work performed by Tech 116* 0.00hrs 508.33

#13 -BRKFSH: PERFORM BRAKE FLUID EXCHANGE 32602 PEDAL FEEL BLED REAR CALIPERS-LOTS OF AIR, BLED BOTH FORWARD CALIPERS ON FT WHEELS FROM INSI DE, FRONT CALIPERS ON REAR OF UPRIGHT HAVE TO BE B LED WITH FRONT WHEELS OFF, SEARCHED FOR HUBCAP KEY IN GLOVE BOX, TRUNK JACK AREA, MANUAL/PAPER WORK PACKE C

Work performed by Tech 116* 0.00hrs 675.00

#14 -HVAC: HVAC 32620 A/C NOT COLD. EVACUATED CHARGE, LOST 1.9L BS FROM 3.0 CHARGE. CHECKED FOR LEAKS AND FOUND CO NDENSER FITTING HAD VERY SMALL LEAK AT 'O' RING. F OUND MINOR LEAKS AT OLD FLEXIBLE LINES CAUSED FROM AGE. SENT OUT BOTH LOW SIDE AND HIGH SIDE FLEX HO SES O C

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)045-1028

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/5
Home Phone	**R/O Close Date**	**Receipt No.**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

Work performed by Tech 116* 0.00hrs	2362.50		
#15 -WHEELS: WHEELS 32602 DRILL OUT KEY LOCKS IN 4 HUBCAPS, WE DON' T HAVE KEYS, SO WE CAN'T TAKE WHEELS OFF. TODD HAS ORDERED NEW LOCKS-TO BE INSTALLED.		C	
Work performed by Tech 116* 0.00hrs	787.73		
#16 -TIRE4: MOUNT AND BALANCE 4 NEW TIRES 32602 MOUNTED AND BALANCED FOUR NEW WHITEWALL T IRES.		C	
#16 -9997: MOUNT AND BALANCE 4 NEW TIRES 32602 MOUNTED AND BALANCED FOUR NEW WHITEWALL T IRES.		C	
#16 -9997: MOUNT AND BALANCE 4 NEW TIRES 32602 MOUNTED AND BALANCED FOUR NEW WHITEWALL T IRES.		C	
Work performed by Tech 114* 0.00hrs	1926.56		
Work performed by Tech 101* 0.00hrs	30.00		
Work performed by Tech 102* 0.00hrs	14.00		
#17 -HVAC: HVAC 32602 I (TECH 101) WELDED THE AC PIPE. I WELDED THE BRACKET BACK TO THE PIPE, WELDED BOTH ENDS OF THE BRACKET. I DIDN'T SEE A CRACK AS I WAS WELDIN G. WE MAY WANT TO PRESSURIZE THE ASSEMBLY TO BE SU RE IT ALL SEALS. THE HOSE IS VERY HARD AND MAY NOT BE S		C	
#17 -9999: HVAC 32602 I (TECH 101) WELDED THE AC PIPE. I WELDED THE BRACKET BACK TO THE PIPE, WELDED BOTH ENDS OF THE BRACKET. I DIDN'T SEE A CRACK AS I WAS WELDIN G. WE MAY WANT TO PRESSURIZE THE ASSEMBLY TO BE SU RE IT ALL SEALS. THE HOSE IS VERY HARD AND MAY NOT BE S		C	
#17 -9999: HVAC 32602 I (TECH 101) WELDED THE AC PIPE. I WELDED THE BRACKET BACK TO THE PIPE, WELDED BOTH ENDS OF THE BRACKET. I DIDN'T SEE A CRACK AS I WAS		C	

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)945-1028

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	11/02/21	11017/6
Home Phone	**R/O Close Date**	**Receipt No.**
	8/31/23	Original
Body	**Mileage In**	**Mileage Out**
	32676	32676

Year	Make	Model	License Number	Service Advisor
1989	ROLL	SILVER SPIRIT		MARK MCDANIEL

Vehicle Identification Number	Color	Account No.	Delivery Date	In-Service Date
SCAZS00A0KCH24843	BLUE			

INVENTORY VEHICLE

WELDIN G. WE MAY WANT TO PRESSURIZE THE ASSEMBLY
WELDIN G. WE MAY WANT TO PRESSURIZE THE ASSEMBLY
TO BE SU RE IT ALL SEALS. THE HOSE IS VERY HARD
AND MAY NOT BE S

#18 -LIGHTS: CHECK AND ADVISE 32676 LEFT FRONT TURN SIGNAL C
BULB OUT REPLACED L EFT FRONT TURN SIGNAL BULB
TO CORRECT.

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

(C) 2009 DEALERTRACK SYSTEMS, Inc. - Dealership Application Group (800)045-1028