

**Sports Car Service, LLC**  
 3875 Stephens Ct Ste A  
 Tucker, GA 30084  
 (404) 435-6760  
 sportscarservice@gmail.com



# ESTIMATE

**ESTIMATE # 1058**  
**DATE 03/09/2018**

DATE	ACTIVITY	QTY	RATE	AMOUNT
03/05/2018	<b>Vehicle Towed to shop</b> Vehicle Towed to shop By owner	1	0.00	0.00
03/06/2018	<b>General vehicle Inspection</b> General Vehicle Inspection and condition report, Timing belts, H2O pump. H2O hoses, shocks & bushings, Fuel hose.	1	0.00	0.00
03/09/2018	<b>Compression/leakdown Replace spark plugs</b> Replace spark plugs, Compression readings. Cyl #1 130, 130,130, 130 100, 90, 90, 140 Numbers are uneven possible causes, rings or valves not fully seated due to lack of use. Suggest retesting after considerable driving or if running issue developes.	1	0.00	0.00
03/07/2018	<b>5yr Belt Service 308/328</b> 5yr belt service 308/328 R&R timing belts, Tensioner bearings, accessory belts. Inspect Hydraulic Belt Tensioners, recharge ac drain compressor oil refill with ester oil, check driver's controls, lights, battery, brakes, and tires.	1	1,050.00	1,050.00
03/07/2018	<b>108224 Frt Crank seal 308/328</b> Front crankshaft seal 308/328	1	73.02	73.02T
03/07/2018	<b>107833 Timing Belt 2V</b>	2	39.95	79.90T

DATE	ACTIVITY	QTY	RATE	AMOUNT
03/07/2018	107833 Timing Belt 2V <b>105206 T-belt bearing Hill</b> T-belt bearing Hill	2	119.95	239.90T
03/07/2018	<b>107971 H2o belt early singal</b> H2o belt early singal	1	32.95	32.95T
03/07/2018	<b>105046 Ac belt 308/328</b> Ac belt 308/328	1	38.50	38.50T
03/09/2018	<b>Other parts</b> Spark plug NGK BPR7ES	8	4.56	36.48T
03/28/2018	<b>Ac refrigerant Oil</b> Ac refrigerant Oil (Ester)	1	15.24	15.24T
03/28/2018	<b>Other parts</b> Compressor bolts 10x50x1.50	2	1.65	3.30T
03/28/2018	<b>Misc Hardware &amp; supplies</b> Hardware, Paint, Cleaners, Etc JB weld (Repair Ac compressor mounting cracked)	1	6.99	6.99T
03/28/2018	<b>Freon 134A</b> Freon 134A	2	8.96	17.92T
				Subtotal: 1,594.20
03/08/2018	<b>Labor charges</b> Labor charges Alternator warning light on. check charging, remove alternator for repair.	2	125.00	250.00
03/08/2018	<b>shipping</b> Shipping	1	19.01	19.01
03/08/2018	<b>Sublet Charges</b> Sublet charges	1	228.51	228.51T
				Subtotal: 497.52
03/09/2018	<b>Labor charges</b> Labor charges Replace H2O pump & gaskets, test thermostat, replace water hoses in valley behind H2O pump. Replace water hose to & from radiator, flush cooling system. Replace coolant reservoir cap Send reservoir out for cleaning. (rusty)	6	125.00	750.00
03/09/2018	<b>121255 H2O pump rebuilt 308/328</b> H2O pump rebuilt 308/328	1	255.43	255.43T
03/09/2018	<b>105192 Seal thermostat 308/328</b> Thermostat gskt 308/328	1	6.82	6.82T
03/09/2018	<b>101499 0.9 bar coolant cap</b> Coolant cap 0.9bar four ear	1	29.95	29.95T
03/09/2018	<b>Radiator flush</b> Radiator flush	1	14.52	14.52T
03/09/2018	<b>40Mmm bulk silicone hose</b> Bulk 40mm silicone Coolant hose	1	45.96	45.96T
03/09/2018	<b>Clamps</b> Clamps smooth surface	20	1.27	25.40T

DATE	ACTIVITY	QTY	RATE	AMOUNT
03/13/2018	<b>Sublet Charges</b> Sublet charges Expansion tank repair (Sim radiator)	1	93.75	93.75T
03/09/2018	<b>Antifreeze</b> Antifreeze/coolant	2	14.25	28.50T
				Subtotal: 1,250.33
03/12/2018	<b>Labor charges</b> Labor charges Flush engine oil and gear box with lite weight oils	1	125.00	125.00
03/12/2018	<b>Mobil one 0W30</b> Synthetic 5W30	7	7.61	53.27T
03/12/2018	<b>Gear oil 75W90</b> Synthetic gear oil75/90	3	11.34	34.02T
				Subtotal: 212.29
03/23/2018	<b>Change Oil &amp; Filter</b> Change oil, filter set tire pressures, inspect lites, check fluids and top up as required, general inspection Drain gear oil & refill	1	75.00	75.00
03/23/2018	<b>Valvoline 20/w50 racing oil</b> 20w50 Valvoline racing engine oil	9	9.98	89.82T
03/23/2018	<b>191993 oil filter 308/328</b> Oil filter 308/328	2	29.85	59.70T
03/23/2018	<b>Royal purple 75W90</b> Royal purple 75w90 syntheic gear oil	5	22.90	114.50T
03/23/2018	<b>Sealing washers</b> Sealing washer	4	1.25	5.00T
				Subtotal: 344.02
03/13/2018	<b>Axle boot service inner/outer 355/348/308/328</b> Axle boot service inner/outer, Replace final drive flange seals	4.50	125.00	562.50
03/13/2018	<b>95860404K Cv boot 380/328</b> Cv joint boot 308/325	4	21.82	87.28T
03/13/2018	<b>125078 Diff seal 308/328/Mondial 45/62/10</b> Diff seal 308/328/Mondial	2	29.42	58.84T
				Subtotal: 708.62
03/19/2018	<b>Labor charges</b> Labor charges replace fuel tank vent hoses. Replace vacuum hose to evaporative system.	4	125.00	500.00
03/20/2018	<b>Bulk Fuel hose 8mm- 3/8</b> Fuel hose 8mm- 3/8	7	2.63	18.41T
03/20/2018	<b>Bulk Fuel hose 6mm 1/4</b> Fuel hose 6mm 1/4	4	2.53	10.12T
03/20/2018	<b>16mm Blue vent hose</b> Fuel vent hose Blue 16mm	1	8.00	8.00T

DATE	ACTIVITY	QTY	RATE	AMOUNT
03/20/2018	<b>Clamps</b> Clamps smooth surface	37	1.20	44.40T
				Subtotal: 580.93
03/26/2018	<b>Diagnose</b> Diagnose left cooling fan inoperative, found relay has open circuit. Replace relay. Check battery not secure repair hold down bracket and repair loose battery ground cables at disconnect switch, test battery ok, install cover.	1	125.00	125.00
03/26/2018	<b>Other parts</b> Relay (used)	1	5.25	5.25T
03/15/2018	<b>Labor charges</b> Labor charges Install new ignition wires in distributor caps & replace one damaged distributor cap.	1	125.00	125.00
03/15/2018	<b>Other parts</b> owner supplied ign wires & dist cap	1	0.00	0.00T
03/23/2018	<b>108333 Spark plug wire boot late</b> Spark plug wire boot late	3	13.68	41.04T
03/23/2018	<b>Labor charges</b> Labor charges clean points, adjust ignition timing, check carburetors linkage clean & grease ball sockets, adjust fuel mixture, synchronize carburetors. Replace air cleaner	6.50	125.00	812.50
04/02/2018	<b>103925 Air cleaner box spacer Carb car</b> Air cleaner box spacer Carb car	1	0.00	0.00T
03/23/2018	<b>108948/114432 Air filter Carb 308</b> Air filter Carb 308	1	92.97	92.97T
				Subtotal: 1,201.76
04/04/2018	<b>Environmental disposal</b> Environmental disposal	1	5.00	5.00

Your estimate is attached please review and contact me with any questions.  
Thank You  
Ron Reineke  
404-435-6760

SUBTOTAL	6,394.67
TAX (7%)	139.70
DISCOUNT 10%	-639.47
<b>TOTAL</b>	<b>\$5,894.90</b>

Accepted By

Accepted Date

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/16/24	6000025/1
R/O Close Date	Status
09/30/24	Reprint
Mileage In	Mileage Out
17919	17919
Service Advisor / Tag #	
MEAGAN LEWELLYN/26215	

MERLIN AUTO GROUP 2882 AMWILER RD ATLANTA, GA 30360			Work Phone	Vehicle Identification Number		
				26215		
			Home Phone	Delivery Date	In-Service Date	
				00/00/00	00/00/00	
Year	Make	Model	Body	Color	License Number	
1978	FERRARI	308				
P26215B						

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Email: service@merlinautogroup.com AR#:	
#1 - MR P3: PERFORM DETAILED MECHANICAL INSPECTION PERFORM DETAILED MECHANICAL INSPECTION Tech: RYAN FIELD(126) Installed DAP1699 :GENRAL PURPOSE GRAY PRIMER PERFORMED MECHANICAL INSPECTION AND NOTED NEEDED REPAIRS TO THE ESTIMATE. COMPLETE.	Internal Internal
#2 - MR COMPRESSIO: PERFORM COMPRESSION TEST PERFORM COMPRESSION TEST Tech: RYAN FIELD(126) PERFORMED ENGINE COMPRESSION TEST AND ADDED ALL READINGS TO THE MULTI-POINT INSPECTION. COMPLETE.	Internal
#3 - MR CARB: TUNE CARBURETOR REBUILD AND TUNE CARBS Tech: RYAN FIELD(126) Tech: RYAN FIELD(126) Tech: RYAN FIELD(126) Tech: RYAN FIELD(126) Installed 74405060 :IDLE JET .060 Freight: FEDEX Installed 100015 :FERRARI O RING DISTRIBUTOR DRI Installed 100015 :FERRARI O RING DISTRIBUTOR DRI Installed 108009 :FERRARI DISTRIBUTOR OIL SEAL 3 Installed 108009 :FERRARI DISTRIBUTOR OIL SEAL 3 Installed 147642 :GASKET Installed 99005036 :CARB GASKET	Internal Internal Internal Internal Internal Internal Internal Internal Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/16/24	6000025/2
R/O Close Date	Status
09/30/24	Reprint
Mileage In	Mileage Out
17919	17919
Service Advisor / Tag #	
MEAGAN LEWELLYN/26215	

MERLIN AUTO GROUP 2882 AMWILER RD ATLANTA, GA 30360			Work Phone	Vehicle Identification Number	
				26215	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1978	FERRARI	308			
P26215B					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Installed 99005125 :INSULATOR	Internal
Installed BP7ES :FERRARI 308/328 NGK 1034 SPARK	Internal
Installed H176 :NAPA 5/16 FUEL HOSE	Internal
Installed 7051226 :HOSE CLAMP	Internal
Installed 90576A825 :M5X.8X8MM NYLOC	Internal
Installed 31716220U :CARB TOP	Internal
CONTINUED ON RO 6000089	
-----	
#4 - MR BATT: REPLACE 12V BATTERY REPLACE BATTERY Caused by Found battery is flat and will no longer hold a charge. Found the negative battery terminal ill fitting and corroded. Tech: RYAN FIELD(126) Installed MTZ34R :INTERSTATE BATTERY MTZ34R Replaced vehicle battery and reset electrical connection. Removed the negative terminal and disassembled to remove corrosion. Refit connection and tested systems for proper operation. Complete.	Internal Internal
-----	
#5 * MR IGNITION: IGNITION Rebuild distributors. Tech: RYAN FIELD(126) Tech: RYAN FIELD(126) Tech: RYAN FIELD(126) CONTINUED ON RO 6000089	Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	xxxxxx6801
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X



# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/27/24	6000089/2
R/O Close Date	Status
01/23/25	
Mileage In	Mileage Out
17920	17920
Service Advisor / Tag #	
MARK MCDANIEL	
Vehicle Identification Number	
26215	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number

<b>MERLIN AUTO GROUP</b> 2882 AMWILER RD Atlanta, GA 30360		
Year	Make	Model
1978	FERRARI	308
INVENTORY: P26215B		

Work Phone	Home Phone
Body	

Vehicle Identification Number	
26215	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Installed 36808 :ZY NYL LK NUT M8X1.25 SW13	Internal
Installed 107786 :SEAL	Internal
Installed 5392032 :HOSE CLAMP M20X32	Internal
Installed 10261860 :COPPER WASHER M22 X 29 4602229	Internal
Installed 5393250 :HOSE CLAMP M32X50	Internal
Installed H187 :3/4" FUEL HOSE	Internal
Sub Total: Labor: .00 Parts: .00 Total: .00	
Full major service was performed: Cam belts & tensioner bearings, cam seals, valve adjustment, spark plugs, accessory belts, full fluid exchange. The cam covers had been on for some time. It still had the old style black gasket. It took some time to scrape all of the old hard black gasket from the heads and covers.	
-----	
#2 - MR CARB: TUNE CARBURETOR REBUILD & TUNE CARBS, CONTD FROM 6000025 Caused by Car needed to be tuned. Tech: RYAN FIELD(126) Tech: WADE WILLIAMS(101) Tech: RYAN FIELD(126) Installed 104550 :FERRARI NUT FLAT KNURLED AIR F Installed HARDWARE :HARDWARE1 Sub Total: Labor: .00 Parts: .00 Total: .00 Found clogged accelerator squirters & screws. Cleaned the squirters & screws. This helped. Set the timing only to find the distributors were advancing at idle when they should not. Will need	Internal Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/27/24	6000089/3
R/O Close Date	Status
01/23/25	
Mileage In	Mileage Out
17920	17920
Service Advisor / Tag #	
MARK MCDANIEL	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
				26215	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1978	FERRARI	308			
INVENTORY: P26215B					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
to fix the distributors next. This is a removal situation & it is scheduled for a major service. Will do the distributors during the major while they are off.	
-----	
#3 - MR IGNITION: IGNITION REBUILD & ADJUST DISTRIBUTORS, CONTD FROM 6000025 Caused by Bad Advance Curve and Point Set Up Tech: RYAN FIELD(126) Tech: WADE WILLIAMS(101) Tech: WADE WILLIAMS(101) Tech: WADE WILLIAMS(101) Tech: WADE WILLIAMS(101) Tech: WADE WILLIAMS(101) Tech: WADE WILLIAMS(101) Sub Total: Labor: .00 Parts: .00 Total: .00 I ran both distributors and tested for proper timing and advance curve. I also tested the retard point set up this car still has. The advance set up was typical of the old cars and was very late. Both 1-4 & 5-8 were late. I recurved both to have all the curve in by 4000 engine RPM. I then reset both sets of retard points to proper numbers. 1-4 retard points did not have an isolator and would not allow the retard points to fire. I was able to put in and isolating washer to make function. While I don't prefer points and retard points, this set up is original and working very well.	Internal Internal Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X



# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/27/24	6000089/5
R/O Close Date	Status
01/23/25	
Mileage In	Mileage Out
17920	17920
Service Advisor / Tag #	
MARK MCDANIEL	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
				26215	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1978	FERRARI	308			
INVENTORY: P26215B					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
better.	
-----	
#5 - MR CARB: TUNE CARBURETOR REMOVE CARBS AND REPLACE FUEL ACCELERATOR NOZZLES Caused by Clogged Acceleration Nozzles / Fuel Pump Tech: WADE WILLIAMS (101) Tech: WADE WILLIAMS (101) Tech: WADE WILLIAMS (101) FUEL Installed HARDWARE :HARDWARE1 Installed 76215055 :ACC PUMP JETS Freight: FEDEX Installed 107103 :AIR INTAKE HOSE Freight: FEDEX Installed H176 :NAPA 5/16 FUEL HOSE Sub Total: Labor: .00 Parts: .00 Total: .00 Inspection found the accelerator pump squirters were not squirting fuel. I removed the carbs and wire cleaned the passages & nozzles. It appears there is some corrosion and is causing issues. After a couple days, the nozzles were not squirting again. I removed and replace all four and then tuned the carbs. After a couple test drives, the fuel pump began to fail. See line 7.	Internal Internal Internal Internal Internal Internal Internal Internal Internal Internal
-----	
#6 - MR COOLING: CHECK AND ADVISE REMOVE BROKEN BLEED SCREW ON THERMOSTAT HOUSING.	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.**

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/27/24	6000089/6
R/O Close Date	Status
01/23/25	
Mileage In	Mileage Out
17920	17920
Service Advisor / Tag #	
MARK MCDANIEL	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	26215	
Year	Make	Model	Delivery Date	In-Service Date	
1978	FERRARI	308	00/00/00	00/00/00	
INVENTORY: P26215B			Color	License Number	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>Caused by Broken Bolt Tech: WADE WILLIAMS (101) Sub Total: Labor: .00 Parts: .00 Total: .00 During the coolant fill procedure, I started to unscrew the thermostat bleeder and it came off. It had been broken and I think epoxied back together. I removed the thermostat housing and drilled the left over threaded part out of the housing. I then replaced the bleeder screw with a bolt modified to work as a bleeder. I then pressure tested the system and had no issues.</p>	Internal
-----	
<p>#7 - MR FUELSYS: FUELSYS POWER LOSS Caused by Bad Fuel Pump Tech: WADE WILLIAMS (101) Installed 610-1075 :ELECT FUEL PUMP Installed 9907 :5/16 CONNECTOR Sub Total: Labor: .00 Parts: .00 Total: .00 Symptoms indicated no fuel. Diagnostic found the fuel pump was running but not moving fuel. I removed the pump and checked the internal filter and it was very clean. It appears the pump just failed. The fuel pump plumbing still had the diverter valve and resistor. I removed the riveter valve and rerouted the hoses to have full flow. The valve is no longer needed with a modern</p>	Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
09/27/24	6000089/7
R/O Close Date	Status
01/23/25	
Mileage In	Mileage Out
17920	17920
Service Advisor / Tag #	
MARK MCDANIEL	

<b>MERLIN AUTO GROUP</b> 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
				26215	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1978	FERRARI	308			
INVENTORY: P26215B					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
pump. Same with the resister in the power wire. I removed it. Fuel flow was restored and the engine is running well.	
-----	
#8 - MR QC: QUALITY CHECK Tech: WADE WILLIAMS (101) Sub Total: Labor: .00    Parts: .00    Total: .00	Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."	LABOR	.00
	PARTS	.00
	DEDUCTIBLE	.00
	SUBLET	.00
	SHOP SUPPLIES	.00
	HAZARDOUS MATERIALS	.00
	SALES TAX OR TAX I.D.	.00
	SPECIAL ORDER DEPOSIT	.00
	DISCOUNTS	.00
	TOTAL DUE	.00

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.**

X