



**2234 S. Barry Ave.**  
**West Los Angeles, CA 90064**  
**(310) 478-5855**  
**Bar No. 8K128425**  
**Tax ID# 74-30036017**

Name: **Pete Nobell** Date: \_\_\_\_\_  
 Address: **218 CATHERINE PARK**  
 Business Phone: **626/808-7919** Home Phone: **pnorell@cruscapital.com**  
 Year: **71** Mileage: \_\_\_\_\_ Model: \_\_\_\_\_ Color: \_\_\_\_\_ License: \_\_\_\_\_ VIN: \_\_\_\_\_

Written By: \_\_\_\_\_  
 Received: \_\_\_\_\_ AM/PM  
 Promised: \_\_\_\_\_ AM/PM  
 Ins. Co.: \_\_\_\_\_  
 Ins. Phone: \_\_\_\_\_  
 Claim No.: \_\_\_\_\_  
 Adjuster: \_\_\_\_\_  
 Odometer In: \_\_\_\_\_  
 Odometer Out: \_\_\_\_\_

HOURS	AMOUNT
10	15,000.00
11	
12	
13	
14	
15	
16	
17	

Repair as Per Estimate Form

**STRIP TO METAL  
 PREPARE POINT & REFINISH  
 WILL ADVISE IF ANY MORE RUST-FOUND**

**Deposit \$7,500**  
**CHECK # 1332** open items

DESCRIPTION & PARTS NUMBER	AMOUNT
<b>LABOR</b>	<b>14,875.00</b>
<b>FRAME</b>	<b>900.00</b>
<b>PAINT MAT.</b>	<b>1,600.00</b>
<b>BODY MAT.</b>	<b>900.00</b>
<b>TOWING</b>	
<b>STORAGE</b>	
<b>SUBLET</b>	<b>1,500.00</b>
<b>SUBTOTAL</b>	<b>27,775.00</b>
<b>TAX</b>	<b>225.00</b>
<b>EPA/WASTE DISPOSAL</b>	
<b>GRAND TOTAL</b>	<b>29,000.00</b>

**POWER OF ATTORNEY**

The undersigned hereinafter called "insured", for the consideration of repairs made to insured's automobile, does hereby grant to said Century Custom Coach, Inc. insured's Power of Attorney to sign or endorse any checks and/or drafts made payable to insured and any releases thereto, as settlement for insured's claim for damages to the above described automobile.

Insured's Signature: \_\_\_\_\_ Date: \_\_\_\_\_

I hereby authorize repair work to be done as described above, with necessary parts to be listed at your regular prices. I agree to pay cash on delivery of car on terms satisfactory to you, and until paid in full, you shall have a lien on this car for the unpaid balance. In the event of default by me in the payment of any installment as may be agreed, you are hereby specifically authorized to take possession of the said vehicle without notice and without process of law, and said possession shall invest you with all the rights of a possessory lien holder under the law of the State of California. I further agree that you will not be held responsible for the car or articles left in the car in case of fire, theft, accidents or other causes beyond your control.

My car may be driven by your employees for road tests at my risk. Storage will be charged 48 hours after notice to me that repairs have been completed. If you are forced to take any action for collection of any balance owing by me to you by lawsuit or otherwise, I further agree to pay interest on the amount owing until paid also collection costs, including a reasonable attorney's fee, and I hereby waive all rights to claim exemption under State law. The provisions herein set forth shall become part of any independent agreement for payment made between us in connection with the work authorized by this order.

SIGNED: \_\_\_\_\_ Dated: \_\_\_\_\_



Peter Norell  
 218 Catherine Park  
 Glendora  
 CA  
 91741  
 United States

Longstone Tyres  
 Hudson's Yard, Doncaster Road, Bawtry, Doncaster DN10 6NX  
 Tel: 0044(0) 1302 711 123 | Fax: 0044(0) 1302 710 113  
 www.longstonetyres.co.uk | sales@longstonetyres.co.uk  
 Director: Dougal Cawley  
 VAT: 182 6293 47 | Reg: 1221249

**Invoice**            **0000025828**  
**Account**          **NORE02**  
**30 September 2016**  
**Amounts in Pound Sterling**

For Order    0000024419  
 Order Date   30/09/2016  
 Customer VAT Number   US  
 Customer Reference

Code	Description	Quantity	Unit Cost	Discount	Net
1174	205VR14 Michelin XWX	5	257.00		1,285.00
0001	Pack of 5 Classic Valve Caps	1	3.50		3.50
	CARR 4-5 FOC Carriage Free of Charge	1	.00		0.00
5	Paid by SagePay (AMEX)	1	.00		0.00

**VAT Analysis**

Code %	Net	VAT
9    0.00 Export (Outside)	1288.50	0.00

<b>Goods</b>	<b>1288.50</b>
<b>VAT</b>	<b>0.00</b>
<b>Invoice</b>	<b>1288.50</b>

Our Bank Details:  
 GBP Natwest Sort 60-02-50 Acc 71590579  
 Please Quote Reference:    NORE02

Terms 30 days from end of month



**AVON Lucas**

**Firestone**



**PIRELLI**





**OFFICINA SPECIALIZZATA  
MASERATI**

Peter Norell  
Crux Classiche  
218 Catherine Park  
Glendora, California, USA 91741

Fattura proforma del 08/11/2016

02	Vignale emblem (stemma Vignale)	euro	96,00
01	oval bonnet emblem (stemma ovale)	euro	91,00
01	written Maserati (scritta Maserati)	euro	80,00
01	written Indy america (scritta Indy America)	euro	104,00
02	flags emblem (stemma bandierine)	euro	96,00
	shipping	euro	81,00
	customs charges	euro	20,00
	bank charges	euro	20,00
		-----	
	import	euro	588,00
	vat ES08	euro	0,00
		-----	
	total proforma invoice	euro	588,00

DATI BANCA:

BANCO POPOLARE - AG. '2' DI MODENA

COD.SWIFT(bic): BAPPIT21412

COD.IBAN :

IT18-Y-05034-12902-000000010600

CANDINI CLASSICHE SRL

Società Unipersonale

---

**Candini Classiche srl società unipersonale**  
**Via Tito Livio 19 41123 Modena PI 01781800360 Tel 059.828280 Fax 059.820653**  
**[www.candinimodena.net](http://www.candinimodena.net)**



**MASERATI SPA**

A SOCIO UNICO

CAPITALE SOCIALE € 40.000.000,00 I.V.

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

Società soggetta ad attività di direzione e coordinamento di Fiat Chrysler Automobiles N.V.

Postal Address/Consignee  
CRUX CAPITAL PARTNERS LLC

218 CATHERINE PARK

91741 GLENDORA  
USA

Delivery Address/Place of Destination  
CRUX CAPITAL PARTNERS LLC  
218 CATHERINE PARK

91741 GLENDORA

N. Fattura/Invoice n°	Data/Date	Cod. Cliente/Client	Pag.
16092365	08-11-2016	095505	1
Descriz. Documento/Doc. description		Vs. Partita Iva/V.A.T. Registration n°	
Invoice			
Modalità di Spedizione/Shipping Company		Porto/Shipment terms	
D.H.L. VIA GERMANIA 16		DDp	
Condizioni di Pagamento/Payment Terms		Banca d'Appoggio/Bank references	
30 GG D.F.F.M.		BANCA POPOLARE DELL'EMILIA ROMAGNA IT310 05387 12916 000000000188	

Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva TVA	Orig.
	Internal num.:VA3/33306269 Via aerea/By air			Your Group Code		: 00	Your Group Code	:	0
	Delivery Note Nr: 401660767 Df 08-11-2016 .								
	Shipping Company: D.H.L. VIA GERMANIA 16 MODENA 41122								
	(Sales Order : 30238936- )								
	MASERATI INDY								
	CHASSIS AM116/49*1208*								
910040285	True copy of the original order	NR	1	65,00		65,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.9900.00								
910040287	True copy of the original Final Test Data Sheet, 2	NR	1	130,00		130,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.9900.00								
910040288	-True copy of the original - End of line - Data Sh	NR	1	65,00		65,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.9900.00								
910040289	True copy of the original Delivery Note	NR	1	65,00		65,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.9900.00								
910040291	Car Technical and Aesthetic characteristics docume	NR	1	156,00		156,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.1090.00								
910040293	Certificate of Origin	NR	1	325,00		325,00		NS9B	IT
	Net Weight : 0,000 Kg.								
	Customs Code EU : 4911.9900.00								

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount



**MASERATI SPA**

A SOCIO UNICO

CAPITALE SOCIALE € 40.000.000,00 I.V.

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

Società soggetta ad attività di direzione e coordinamento di Fiat Chrysler Automobiles N.V.

Postal Address/Consignee  
CRUX CAPITAL PARTNERS LLC

218 CATHERINE PARK

91741 GLENDORA  
USA

Delivery Address/Place of Destination  
CRUX CAPITAL PARTNERS LLC  
218 CATHERINE PARK

91741 GLENDORA

N. Fattura/Invoice n°	Data/Date	Cod. Cliente/Client	Pag.
16092365	08-11-2016	095505	2
Descriz. Documento/Doc. description		Vs. Partita Iva/V.A.T. Registration n°	
Invoice			
Modalità di Spedizione/Shipping Company		Porto/Shipment terms	
D.H.L. VIA GERMANIA 16 MODENA 41122		DDp	
Condizioni di Pagamento/Payment Terms		Banca d'Appoggio/Bank references	
30 GG D.F.F.M.		BANCA POPOLARE DELL'EMILIA ROMAGNA IT310 05387 12916 000000000188	

Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva TVA	Orig.
	N.package : 0 IMBALLO ENVELOPE CM 35X27X0.1								
	N. packages : 1 Gross Weight: 0,2000 Net Weight: 0,1900								
	THE WOODEN PALLETS, WOODEN CRATES OR WOODEN BOXES IN THIS SHIPMENT ARE FREE FROM BARK AND ARE APPARENTLY FREE FROM LIVE PLANT PESTS								
	<p>DOGANA DI COMPETENZA</p> <p>Si dichiara che la merce descritta in questa fattura non è stata confezionata con parti di pelle di specie animali elencate, o comunque citate, nella Convenzione sul commercio internazionale delle specie animali e vegetali in via di estinzione, firmata a Washington il 3 marzo 1973 e ratificata in Italia con Legge nr.874 del 19/12/1975, e successive modificazioni.</p> <p>in fede</p> <p>TO THE COMPETENT CUSTOMS</p> <p>We declare that the goods indicated in this invoice are not made of leather parts of animal species listed, or however indicated, in this Convention on International Trade in Endangered Species of Wild Fauna and Flora, done at Washington on March 3, 1973, and ratified in Italy by the Law nr.874 Of 19/12/1975, and following amendments.</p> <p>in faith</p>								

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount



**MASERATI SPA**

A SOCIO UNICO

CAPITALE SOCIALE € 40.000.000,00 I.V.

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

Società soggetta ad attività di direzione e coordinamento di Fiat Chrysler Automobiles N.V.

Postal Address/Consignee  
CRUX CAPITAL PARTNERS LLC

218 CATHERINE PARK

91741 GLENDORA  
USA

Delivery Address/Place of Destination  
CRUX CAPITAL PARTNERS LLC  
218 CATHERINE PARK

91741 GLENDORA

N. Fattura/Invoice n°	Data/Date	Cod. Cliente/Client	Pag.
16092365	08-11-2016	095505	3
Descriz. Documento/Doc. description		Vs. Partita Iva/V.A.T. Registration n°	
Invoice			
Modalità di Spedizione/Shipping Company		Porto/Shipment terms	
D.H.L. VIA GERMANIA 16		DDp	
Condizioni di Pagamento/Payment Terms		Banca d'Appoggio/Bank references	
30 GG D.F.F.M.		BANCA POPOLARE DELL'EMILIA ROMAGNA IT310 05387 12916 000000000188	

Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva TVA	Orig.
	<p>THE EXPORTER OF THE PRODUCTS COVERED BY THIS DOCUMENT (CUSTOMS AUTHORIZATION IT/028/MD/13) DECLARES THAT, EXCEPT WHERE OTHERWISE CLEARLY INDICATED, THESE PRODUCTS ARE OF THE EUROPEAN COMMUNITY PREFERENTIAL ORIGIN.</p> <p>Z1: Preferential Origin Zone 1 Z2: Preferential Origin Zone 2 NO: No Preferential Origin</p>								
	Total weight Gross/Net Kg.		0,2000/	0,1900					

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount
Goods total	806,00	806,00	NSart da7a7sept D		(USD) 806,00



**MASERATI SPA**

A SOCIO UNICO

CAPITALE SOCIALE € 40.000.000,00 I.V.

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

Società soggetta ad attività di direzione e coordinamento di Fiat Chrysler Automobiles N.V.

Postal Address/Consignee

91741 GLENDORA USA  
CALIFORNIA  
Delivery Address/Place of Destin.

91741 GLENDORA USA  
CALIFORNIA

N. Fattura/Invoice n°	Data/Date	Cod. Cliente/Client	Pag.
00000082	16-11-2016	095505	1
Descriz. Documento/Doc. description		Vs. Partita Iva/V.A.T. Registration n°	
Proforma invoice			
Modalità di Spedizione/Shipping Company		Porto/Shipment terms	
DHL - BY AIR		DDP	
Condizioni di Pagamento/Payment Terms		Banca d'Appoggio/Bank references	
RIMESSA DIRETTA		BANCA POPOLARE DELL'EMILIA ROMAGNA IT310 05387 12916 000000000188	

Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Net Unit Price Currency:	Iva TVA	Orig.
910040291	<p>Internal num. :PRV/44001997</p> <p>Our Group Code : 0 Your Group Code : 0</p> <p>MASERATI INDY</p> <p>CHASSIS AM116/49*1208*</p> <p>Car Technical and Aesthetic characteristics docume</p> <p>1 ENVELOPE CM 35X27X0.1</p> <p>GROSS WEIGHT KG 0.110</p> <p>Custom code :4911.1090.00</p> <p>THE WOODEN PALLETS, WOODEN CRATES OR WOODEN BOXES IN THIS SHIPMENT ARE FREE FROM BARK AND ARE APPARENTLY FREE FROM LIVE PLANT PESTS</p> <p>DOGANA DI COMPETENZA</p> <p>Si dichiara che la merce descritta in questa fattura non è stata confezionata con parti di pelle di specie animali elencate, o comunque citate, nella Convenzione sul commercio internazionale delle specie animali e vegetali in via di estinzione, firmata a Washington il 3 marzo 1973 e ratificata in Italia con Legge nr.874 del 19/12/1975, e successive modificazioni.</p> <p>in fede</p>	NR	1	156,00	0	156,00			I

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount
-------------------	----------------	----------------	-----------------------------	------------	-----------------------------



**MASERATI SPA**

A SOCIO UNICO

CAPITALE SOCIALE € 40.000.000,00 I.V.

VIALE CIRO MENOTTI, 322 - 41100 MODENA

PART. IVA - COD. FISC. - NR. REG. IMPRESE MODENA 08245890010

TEL. 059 590511 - FAX 059 226765

Società soggetta ad attività di direzione e coordinamento di Fiat Chrysler Automobiles N.V.

Postal Address/Consignee

91741 GLENDORA USA  
CALIFORNIA

Delivery Address/Place of Destin.

91741 GLENDORA USA  
CALIFORNIA

N. Fattura/Invoice n°	Data/Date	Cod. Cliente/Client	Pag.
00000082	16-11-2016	095505	2
Descriz. Documento/Doc. description		Vs. Partita Iva/V.A.T. Registration n°	
Proforma invoice			
Modalità di Spedizione/Shipping Company		Porto/Shipment terms	
DHL - BY AIR		DDP	
Condizioni di Pagamento/Payment Terms		Banca d'Appoggio/Bank references	
RIMESSA DIRETTA		BANCA POPOLARE DELL'EMILIA ROMAGNA	

IT310 05387 12916 000000000188

Cod. Art. Art. N.	Descrizione Description	U.M. U.M.	Quantità Quantity	Prez. List. Unit. Unit Price List	Sconto Discount	Importo Netto Net Amount	Unit Price Currency:	Iva TVA	Orig.
	TO THE COMPETENT CUSTOMS								
	We declare that the goods indicated in this invoice are not made of leather parts of animal species listed, or however indicated, in this Convention on International Trade in Endangered Species of Wild Fauna and Flora, done at Washington on March 3, 1973, and ratified in Italy by the Law nr.874 Of 19/12/1975, and following amendments.								
	in faith								

Voce/Various Cost	Importo/Import	Imponibile/Net	Descriz. Assog. V.A.T. rate	IVA/V.A.T.	Totale Fattura/Total Amount
Goods total	156,00	156,00	Fuori ambito IVA		(USD) 156,00



1884 S SEPULVEDA BLVD  
LOS ANGELES, CA 90025 US  
(818) 653-5821  
gfcusimano@gmail.com

**BILL TO**

Peter Norell  
Indy 4900

**INVOICE # 7**

**DATE** 02/06/2017  
**DUE DATE** 03/08/2017  
**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT
<b>Interior Insulation</b> Paid to upholstery guy in cash	1	50.00	50.00T
<b>Foot Pads Maserati</b> NEED TO ORDER	1	0.00	0.00T
<b>Sandblasting/Powder coating</b> Sandblasting and powder coating T brackets, oil filter housing, fan shroud, i plate , knuckles (engine)	1	166.00	166.00T
<b>Spark Plug</b>	8	4.77	38.16T
<b>Hose Clamp Mini 11mm</b>	10	0.95	9.50T
<b>fuel Hose 7.5 X 12.5 mm - Outside Cloth Braided</b>	5	7.60	38.00T
<b>Fuel Hose - 9.5 X 15.5 mm - (Smooth Rubber)</b>	3	8.60	25.80T
<b>Hose Clamp Mini 12</b>	10	0.95	9.50T
<b>Hose Clamp Mini 13mm</b>	10	1.60	16.00T
<b>Hose Clamp Mini 14mm</b>	1	7.68	7.68T
<b>Machine Shop</b> Machine Shop Surface of Pulley for Water Pump	1	48.00	48.00T
<b>U Channel</b> Rubber For Front Windows- 10 Feet	10	5.95	59.50T
<b>shipping</b>	1	43.09	43.09T
<b>Tow</b> Towing 11/9/16 and 12/6/16	2	110.00	220.00T
<b>Interstate Battery MTP 27</b>	1	128.00	128.00T
<b>HVL Mousehair Maserati</b>	1	600.00	600.00T
<b>Window Brush Wide Wide Trim</b>	4	60.42	241.68T
<b>Instrument Bulb 3796</b>	12	2.90	34.80T
<b>Hose Clamp 40-60</b>	5	1.56	7.80T
<b>Hose Clamp 25-40</b>	5	1.36	6.80T
<b>Hose Clamp 30-45</b>	5	1.40	7.00T

ACTIVITY	QTY	RATE	AMOUNT
<b>Instrument Bulb 3796</b> Instrument Cluster Bulb	10	2.90	29.00T
<b>Hose Clamp Mini 10mm</b> 10 pack	1	9.00	9.00T
<b>bulb 1157</b>	2	1.90	3.80T
<b>bulb 1073</b>	2	1.79	3.58T
<b>Driver Seat ReFoam</b>	1	350.00	350.00
<b>Super 90 Adhesive</b>	6	22.12	132.72T
<b>Upper Coolant Hose Indy</b>	1	100.00	100.00T
<b>Labor:Italian Exotics</b> AC SYstem Time Actual- 1.5 ac hose prefit,	1	125.00	125.00
<b>Labor:Italian Exotics</b> Glass Actual- 4.0 cut rubber for rear glass, install quarter glass, 1.25 install rear glass, 7 hours clean qtr glass and all sealant polish trim on qtr glass, cut pieces for rear glass to shape and sizemore qtr glass 2.5hours,	1	125.00	125.00
<b>Labor:Italian Exotics</b> Electrical Actual-1.0 alternator rewire cut off old jacket and solder wires, 4 hours -rewire light wires front and rear and sides insualte and rejacket all wires, add new connectors where needed and insualte wires, 1.25 finish rewire rear lights install rear side lights,	1	125.00	125.00
<b>Labor:Italian Exotics</b> modify bumper bracket to fit bumper .25, assemble center console restore shift plackard, install ash tray with chrome bezel, install center console door and hinge ( clean hinge to original silver from painted beige color) 1, install trim .25, indy trim .25,cut upper radiator hose to shape and install driver side trim after removing embedded screw and installing double sided tape to trim 1.5 and clean and paint new power steering hose for install,	1	125.00	125.00
<b>Labor:Italian Exotics</b> interior not upholstery	1	125.00	125.00
<b>Labor:Italian Exotics</b> paint hubs with satin black paint and activator x4 1 hour, fasten water pump to ac clhompson, tighten drive belts for ac and drive belt for alternator install rear spoiler with new hardware, 2 hours,	1	125.00	125.00
<b>Remanufacture Power Steering Hose</b> Outside Service- Remanufacture High Pressure hose for Power Steering pump to steering box.	1	185.00	185.00T
<b>Chrome</b>	1	140.00	140.00T
<b>Antenna Electric</b>	1	34.39	34.39T
<b>Drive Belt 10x710</b>	1	16.18	16.18T
<b>Grommet 1/4 inch</b>	1	4.19	4.19T
<b>Grommet 3/8 inch</b>	1	4.19	4.19T
<b>Fuel Hose - 9.5 X 15.5 mm - (Smooth Rubber)</b>	1	8.60	8.60T
<b>Misc.</b> fender washers	1	41.00	41.00T
<b>Wiper Post Base Gasket</b>	1	7.99	7.99T

ACTIVITY	QTY	RATE	AMOUNT
<b>Hose Clamp Mini 10mm</b> 10 pack	1	9.00	9.00T
<b>bulb 1157</b>	2	1.90	3.80T
<b>bulb 1073</b>	2	1.79	3.58T
<b>Driver Seat ReFoam</b>	1	350.00	350.00
<b>Super 90 Adhesive</b>	6	22.12	132.72T
<b>Upper Coolant Hose Indy</b>	1	100.00	100.00T
<b>Labor:Italian Exotics</b> AC SYstem Time Actual- 1.5 ac hose prefit,	1	125.00	125.00
<b>Labor:Italian Exotics</b> Glass Actual- 4.0 cut rubber for rear glass, install quarter glass, 1.25 install rear glass, 7 hours clean qtr glass and all sealant polish trim on qtr glass, cut pieces for rear glass to shape and sizemore qtr glass 2.5hours,	1	125.00	125.00
<b>Labor:Italian Exotics</b> Electrical Actual-1.0 alternator rewire cut off old jacket and solder wires, 4 hours -rewire light wires front and rear and sides insualte and rejacket all wires, add new connectors where needed and insualte wires, 1.25 finish rewire rear lights install rear side lights,	1	125.00	125.00
<b>Labor:Italian Exotics</b> modify bumper bracket to fit bumper .25, assemble center console restore shift plackard, install ash tray with chrome bezel, install center console door and hinge ( clean hinge to original silver from painted beige color) 1, install trim .25, indy trim .25,cut upper radiator hose to shape and install driver side trim after removing embedded screw and installing double sided tape to trim 1.5 and clean and paint new power steering hose for install,	1	125.00	125.00
<b>Labor:Italian Exotics</b> interior not upholstery	1	125.00	125.00
<b>Labor:Italian Exotics</b> paint hubs with satin black paint and activator x4 1 hour, fasten water pump to ac cl\ompressor, tighten drive belts for ac and drive belt for alternator install rear spoiler with new hardware, 2 hours,	1	125.00	125.00
<b>Remanufacture Power Steering Hose</b> Outside Service- Remanufacture High Pressure hose for Power Steering pump to steering box.	1	185.00	185.00T
<b>Chrome</b>	1	140.00	140.00T
<b>Antenna Electric</b>	1	34.39	34.39T
<b>Drive Belt 10x710</b>	1	16.18	16.18T
<b>Grommet 1/4 Inch</b>	1	4.19	4.19T
<b>Grommet 3/8 inch</b>	1	4.19	4.19T
<b>Fuel Hose - 9.5 X 15.5 mm - (Smooth Rubber)</b>	1	8.60	8.60T
<b>Misc.</b> fender washers	1	41.00	41.00T
<b>Wiper Post Base Gasket</b>	1	7.99	7.99T
<b>Fuel Pump Cylindrical</b>	2	135.10	270.20T
<b>AC Compressor</b>	1	375.00	375.00T
<b>Speaker</b> Pioneer speakers New	2	49.99	99.98T
<b>Release Lever</b> Trunk	1	151.00	151.00T

ACTIVITY	QTY	RATE	AMOUNT
<b>Exhaust hangers</b>	5	14.40	72.00T
<b>Silicone RTV Gray</b> used on valve cover gasket	2	4.49	8.98T
<b>Outside Labor</b> deposit for steering wheel-200.00 cash	1	450.00	450.00T
<b>Shift Knob Indy</b> Outside Labor- Repair and Stain	1	150.00	150.00
<b>Door Seal BR48</b> per foot-	30	10.00	300.00T
<b>bulb socket Italian 2 Prong</b> bulb socket for reflectors	4	16.99	67.96T
<b>Carburetor KIT DCNF 40, 42, 44</b>	4	32.95	131.80T
<b>Chrome</b> center lock cylinder and gas tank door, rear trunk hinge, door light bezel,	1	160.00	160.00T
<b>heater Valve Maserati</b> 40\$ discount	1	160.00	160.00T
<b>Fuel Neck Grommet Maserati</b>	2	39.00	78.00T
<b>door Lamp Assembly Indy</b> for doors	2	95.00	190.00T
<b>Indy 4900 Script</b>	1	130.21	130.21T
<b>door guide maserati</b>	2	26.00	52.00T
<b>Rubber window sweep</b>	1	32.90	32.90T
<b>Acorn Nut Windshield Wipers Maserati</b> To purchase	2	5.30	10.60T
<b>Antenna Extension</b>	1	22.152	22.15T
<b>Ashtray</b>	1	105.00	105.00T
<b>Engine Compartment lens</b>	1	60.00	60.00T
<b>Hood buffer</b>	8	15.00	120.00T
<b>door lock knobs</b>	2	10.00	20.00T
<b>Lock rod</b>	2	25.00	50.00T
<b>shipping</b>	1	15.00	15.00
<b>Hazard light switch</b>	1	179.00	179.00T
<b>Heater valve gasket Maserati</b> Rubber not fiber gasket	1	7.85	7.85T
<b>Brake Pad Retainer set Girling</b>	1	23.20	23.20T

larry- ashtray, heater valve 130, 6inch lock thing x2,  
hazard switch, ashtray knob, bump stops hood, engine  
compartment lens  
, lock knobs and locking latch for door, 6inch door latch  
things,  
hood pads, oil cap

SUBTOTAL	7,069.78
TAX (9%)	483.81
TOTAL	7,553.59
DEPOSIT	3,500.00
PAYMENT	4,053.59
<b>BALANCE DUE</b>	<b>\$0.00</b>

ACTIVITY	QTY	RATE	AMOUNT
<b>Fuel Pump Cylindrical</b>	2	135.10	270.20T
<b>AC Compressor</b>	1	375.00	375.00T
<b>Speaker</b> Pioneer speakers New	2	49.99	99.98T
<b>Release Lever</b> Trunk	1	151.00	151.00T
<b>Exhaust hangers</b>	5	14.40	72.00T
<b>Silicone RTV Gray</b> used on valve cover gasket	2	4.49	8.98T
<b>Outside Labor</b> deposit for steering wheel-200.00 cash	1	450.00	450.00T
<b>Shift Knob Indy</b> Outside Labor- Repair and Stain	1	150.00	150.00
<b>Door Seal BR48</b> per foot-	30	10.00	300.00T
<b>bulb socket Italian 2 Prong</b> bulb socket for reflectors	4	16.99	67.96T
<b>Carburetor KIT DCNF 40, 42, 44</b>	4	32.95	131.80T
<b>Chrome</b> center lock cylinder and gas tank door, rear trunk hinge, door light bezel,	1	160.00	160.00T
<b>heater Valve Maserati</b> 40\$ discount	1	160.00	160.00T
<b>Fuel Neck Grommet Maserati</b>	2	39.00	78.00T
<b>door Lamp Assembly Indy</b> for doors	2	95.00	190.00T
<b>Indy 4900 Script</b>	1	130.21	130.21T
<b>door guide maserati</b>	2	26.00	52.00T
<b>Rubber window sweep</b>	1	32.90	32.90T
<b>Acorn Nut Windshield Wipers Maserati</b> To purchase	2	5.30	10.60T
<b>Antenna Extension</b>	1	22.15	22.15T
<b>Ashtray</b>	1	105.00	105.00T
<b>Engine Compartment lens</b>	1	60.00	60.00T
<b>Hood buffer</b>	8	15.00	120.00T
<b>door lock knobs</b>	2	10.00	20.00T
<b>Lock rod</b>	2	25.00	50.00T
<b>shipping</b>	1	15.00	15.00
<b>Hazard light switch</b>	1	179.00	179.00T
<b>Heater valve gasket Maserati</b> Rubber not fiber gasket	1	7.85	7.85T
<b>Brake Pad Retainer set Girling</b>	1	23.20	23.20T

larry- ashtray, heater valve 130, 6inch lock thing x2,  
hazard switch, ashtray knob, bump stops hood, engine  
compartment lens  
, lock knobs and locking latch for door, 6inch door latch  
things,  
hood pads, oil cap

---

SUBTOTAL	7,069.78
TAX (9%)	483.81
TOTAL	7,553.59
DEPOSIT	3,500.00
BALANCE DUE	<b>\$4,053.59</b>



1884 S SEPULVEDA BLVD  
LOS ANGELES, CA 90025 US  
(818) 653-5821  
gfcusimano@gmail.com

**BILL TO**

Peter Norell  
Testarossa

**INVOICE # 1**

**DATE** 02/16/2017  
**DUE DATE** 03/18/2017  
**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT
Recondition Rims	4	200.00	800.00T
Labor:Italian Exotics	1	680.00	680.00
Mount balance And Tires Goodrich 225/50 -16, and 255/50-16			
SUB TOTAL			1,480.00
TAX (9%)			72.00
TOTAL			1,552.00
PAYMENT			1,552.00
BALANCE DUE			<b>\$0.00</b>

PAID



1884 S SEPULVEDA BLVD  
LOS ANGELES, CA 90025 US  
(818) 653-5821  
gfcusimano@gmail.com

**BILL TO**

Peter Norell  
Maserati Indy 4.9  
odometer 37349

**INVOICE # 122**

**DATE** 06/05/2017  
**DUE DATE** 07/05/2017  
**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT
<b>Copper washer 7/16</b> for brake hoses- Specialty Copper Washer	2	6.99	13.98T
<b>Acorn Nuts Windshiel Wiper Indy</b>	2	4.99	9.98T
<b>Outside Labor</b> Fuel Tank- Acid Dip- Rust in Tank	2	160.0 0	320.00T
<b>fuel Hose 7.5 X 12.5 mm - Outside Cloth Braided</b>	1	7.60	7.60T
<b>Hose Clamp Mini 12</b>	10	0.95	9.50T
<b>fuel</b>	1	138.9 6	138.96
<b>Diamond Vinyl Hood Insulation</b>	1	295.0 0	295.00T
<b>Outside Labor</b> Remove/Install Chromed Pieces, make mock up of old seat belts, remake new seat belt in red material- material included	1	325.0 0	325.00T
<b>Lock</b> lock cylinders for center console and gas tank	1	100.0 0	100.00T
<b>Caliper repair kit</b>	1	44.50	44.50T
<b>AC retrofit parts</b> Ac Bottle and Various Fittings for Hoses	1	138.8 1	138.81T
<b>Rubber Carpet Heel Pad</b> Rubber Heel Pad	2	85.00	170.00T
<b>shipping</b>	1	29.00	29.00
<b>detail</b>	1	250.0 0	250.00T
<b>Radiator Cap Alfa Fiat</b>	1	14.95	14.95T
<b>Wheel balance</b> wheel balance	4	20.00	80.00
<b>Labor:Italian Exotics</b> becker radio pick up and delivery, etc	1	125.0 0	125.00
<b>door lock knobs</b>	1	10.00	10.00T

ACTIVITY	QTY	RATE	AMOUNT
<b>Outside Labor</b> radio repair becker,	1	375.00	375.00T
<b>lock washer 7/16</b>	20	0.332	6.64T
<b>Flat washer 7/16</b>	20	0.46	9.20T
<b>Edge Trim</b> Engine Compartment	16	3.95	63.20T
<b>Schrader Valve</b> for ac system	2	7.00	14.00T
<b>high Side Charging adapter</b> AC System	1	13.69	13.69T
<b>Air cleaner box sticker Fiam Maserati</b>	1	34.00	34.00T
<b>Outside Labor</b> Repair Leak in Evaporator Tube	1	85.00	85.00T
<b>fuel</b> 06/05/2017	1	55.00	55.00
<b>alignment</b>	1	250.00	250.00T
<b>Labor:Italian Exotics</b> Closing Balance of all final repairs and assembly. Upholstery not included on this balance	1	10,000.00	10,000.00
<b>Refrigerant</b>	3.50	15.00	52.50T

These are repairs carried out on a used classic automobile that wasn't completely restored. There Are many components that are still original and may fail during use. Gran Turismo of Los Angeles is not responsible for the vehicles reliability. many Components from the manufacturer where known to be unreliable and may fail.

SUBTOTAL	13,040.51
TAX (9%)	235.13
TOTAL	13,275.64
<b>BALANCE DUE</b>	<b>\$13,275.64</b>



1884 S SEPULVEDA BLVD  
 LOS ANGELES, CA 90025 US  
 (818) 653-5821  
 gfcusimano@gmail.com

**BILL TO**

Peter Norell  
 1971 Maserati Indy

**INVOICE #** 143

**DATE** 06/24/2017

**DUE DATE** 07/24/2017

**TERMS** Net 30

ACTIVITY	QTY	RATE	AMOUNT
Digital Points Rush	1	185.00	185.00T
Capacitive Discharge Ignition Coll	1	115.00	115.00T
Spark Plug cable set insulated	1	105.00	105.00T
Digital ignition Box	1	275.00	275.00T
Spark Plug boots	8	3.99	31.92T
Spark Plug terminal straight	8	3.99	31.92T
Materials	1	74.56	74.56T
fuel hose, clamps, heat shrink tubing and connectors			
Fuel filter 3/8 fitting	1	17.86	17.86T
shipping	1	34.93	34.93
Fuel Pump Switch early Maserati	1	159.07	159.07T
includes shipping			
fuel	1	70.00	70.00
Uber	1	46.39	46.39T
tee connector 5/16	1	12.58	12.58T
silicon insulation 8mm	0.25	89.99	22.50T
per foot for wiring to ignition box			
oil temperature switch maserati	1	57.80	57.80T
fuel pressure regulator 0-5 psi	1	59.99	59.99T
ester oil	1	10.92	10.92T
for compressor			
Labor:Italian Exotics	7	125.00	875.00
Replace Digital Ignition box, Rewire new Ignition Box in passenger wheel well, Paint and Install Digital Points to Distributor, Custom make Set of spark PLug Cables, insualte wires. Adust Hood			
Labor:Italian Exotics	0	125.00	0.00
Insatll Fuel Pressure Regualtor and reroute fuel lines to make both tanks usable at same time, Replace Fuel Pump Switch, Install Oil Temperature Sensor . NO CHARGE- 4 Hours			

SUBTOTAL

2,185.44

TAX (9%)

108.50

TOTAL

2,293.94

BALANCE DUE

**\$2,293.94**

# Gran Turismo of Los Angeles

# Repair Order

1884 S Sepulveda Blvd Los Angeles, CA 90025 424-256-6867		Repair Order.
Bill To		Odometer:
Address		VIN:
Date Received		
Date Wanted	Phone	
Call Customer If Repair Exceeds \$	Type of Equipment Received	
Shop Rate/Hr	Customer Request, Complaint	

Service Description	Qty.	Price	Total
Replace All Large Diameter Cooling Hoses, Replace Thermostat and Seal, Replace Heater Hoses(in Cabin and Engine Comp) and Add Coolant			\$375.00
REplace Air Filter Element, Fuel Filter			\$62.50
Oil Change With Castrol 20w50			\$100.00
Change All Fuel Hoses			\$250.00
Change All Transmission Lines and Remanufacture High Pressure Line(175.00)			\$550.00
Replace Cam Cover Gaskets, Clean and Paint Can Covers In Wrinkle Black Paint and Reseal			\$375.00
Finish Install Glass			\$350.00
			\$0.00
Clean And Detail Engine Compartment- Replace Necessary Components and Insulate electrical			\$500.00
REplace Front Brake Pad, Machine Rotor, Repack Bearings			\$250.00
Replace Rear Brake Pad, Machine Rotor, Repack Bearings, Change Seals and Change Hand Brake Pad			\$375.00
		Other Service May Be Listed On Back	\$3,187.50

Parts Description	Qty.	Price	Total
Cam Cover gasket Right	2	\$25.50	\$51.00
Cam Cover gasket Left Intake	1	\$25.50	\$25.50
Cam Cover gasket Left Exhaust	1	\$25.50	\$25.50
Cam Cover gasket Half Moon	7	\$3.25	\$22.75
Air Filter Element	1	\$39.00	\$39.00
Thermostat (Late GT V8)	1	\$59.85	\$59.85
Thermostat Cover Ring	1	\$5.56	\$5.56
Fuel Filter (Late Type)	1	\$16.40	\$16.40
Oil Filter (V8 Spin-on)	1	\$16.76	\$16.76
Front Brake Line	2	\$51.00	\$102.00
Redline Heavy Duty hsock Proof Gear Oil	2.5	\$20.99	\$52.48
Axle Limitng Strap	2	\$33.13	\$66.26
		Other Parts May Be Listed On Back	\$483.06

I fully understand the purpose of the safety devices on this equipment and specifically request that they not be repaired or replaced, and I assume responsibility for and hold you harmless from any injury to anyone that may result therefrom.

**Pickup And Delivery**

**Total From Back**      **Total Parts**      \$483.06

**AGREED TO And AUTHORIZED BY**

While the manufacturer may warrant the goods sold to the customer, we make no warranties, express or implied, including any implied warranties of merchantability or fitness, with respect to such goods.	Subtotal	\$1,824.74
	Tax	\$43.85
	<b>Total</b>	<b>\$1,868.59</b>

Not responsible for loss or damage in case of fire, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the unit as necessary for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above item to secure the amount of repairs thereto.

X

AGREED TO And AUTHORIZED BY

Make all checks payable to: [Giovanni Cusimano]

**Thanks for Your Business**

# Gran Turismo of Los Angeles

# Repair Order

1884 S Sepulveda Blvd Los Angeles, CA 90025 424-256-6867	Repair Order.	Maserati Indy
	Bill To	
	Peter Norell	Odometer:
	Address	VIN:

Date Received	
Date Wanted	Phone
Call Customer If Repair Exceeds \$	Type of Equipment Received
Shop Rate/Hr	Customer Request, Complaint

Service Description	Qty.	Price	Total
Remove Install Compressor for AC			\$0.00
Clean Condenser For AC			\$0.00
Rebuild AC Lines	2	\$120.00	\$0.00
Charge AC			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
		Other Service May Be Listed On Back	\$0.00

Parts Description	Qty.	Price	Total
Brake Caliper Piston #58456	4	\$33.97	\$135.88
Brake Caliper Piston #58450	2	\$44.97	\$89.94
Shipping	1	\$10.03	\$10.03
Rubberized Under Coating	4	\$10.49	\$41.96
AC Compressor Rebuild			\$492.95
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
		Other Parts May Be Listed On Back	\$770.76

I fully understand the purpose of the safety devices on this equipment and specifically request that they not be repaired or replaced, and I assume responsibility for and hold you harmless from any injury to anyone that may result therefrom.	<b>Pickup And Delivery</b>
<input checked="" type="checkbox"/>	<b>Total From Back</b>
X	<b>Total Parts</b>
AGREED TO And AUTHORIZED BY	\$770.76

While the manufacturer may warrant the goods sold to the customer, we make no warranties, express or implied, including any implied warranties of merchantability or fitness, with respect to such goods.	<b>Subtotal</b>	\$5,065.54
	<b>Tax</b>	\$181.39
	<b>Total</b>	\$5,246.93

Not responsible for loss or damage in case of fire, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with if necessary material and hereby grant you and/or your employees permission to operate the unit as necessary for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above item to secure the amount of repairs thereto.

# Gran Turismo of Los Angeles

# Repair Order

1884 S Sepulveda Blvd Los Angeles, CA 90025 424-256-6867	Repair Order. <span style="float:right">Maserati Indy</span>	
	<b>Bill To</b>	
	Peter Norell	Odometer:
	<b>Address</b>	VIN:
<b>Date Received</b>		
<b>Date Wanted</b>	<b>Phone</b>	
<b>Call Customer If Repair Exceeds \$</b>	<b>Type of Equipment Received</b>	
<b>Shop Rate/Hr</b>	<b>Customer Request, Complaint</b>	

Service Description	Qty.	Price	Total
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
			\$0.00
		Other Service May Be Listed On Back	\$0.00

Parts Description	Qty.	Price	Total
Upholstery Glue	1	\$125.00	\$125.00
Front Brake Caliper Kit		\$0.00	\$65.00
Lower Rad Hose	5	\$3.57	\$17.85
Parking Brake Pads (Pin Back)	1	\$105.00	\$105.00
ID Hose - Cloth Braid Heater Hose	1	\$28.93	\$28.93
Rear Brake Caliper Kit			\$65.00
Hydraulic Line - Braided S/S	2	\$51.00	\$102.00
Brake/Clutch Hose	1	\$28.33	\$28.33
Coolant Hose	1	\$16.40	\$16.40
Wheel Bearing Grease	0	\$0.00	\$15.99
Brake Caliper Piston #58694	4	\$33.97	\$135.88
Brake Caliper Piston #58697	2	\$44.97	\$89.94
		Other Parts May Be Listed On Back	\$795.32

I fully understand the purpose of the safety devices on this equipment and specifically request that they not be repaired or replaced, and I assume responsibility for and hold you harmless from any injury to anyone that may result therefrom.	<b>Pickup And Delivery</b>
<b>X</b>	<b>Total From Back</b>
AGREED TO And AUTHORIZED BY	<b>Total Parts</b>
	\$795.32

While the manufacturer may warrant the goods sold to the customer, we make no warranties, express or implied, including any implied warranties of merchantability or fitness, with respect to such goods.	<b>Subtotal</b>	\$5,065.54
	<b>Tax</b>	\$181.39
	<b>Total</b>	\$5,246.93

Not responsible for loss or damage in case of fire, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the unit as necessary for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above item to secure the amount of repairs thereto.

# Gran Turismo of Los Angeles

# Repair Order

1884 S Sepulveda Blvd Los Angeles, CA 90025 424-256-6867		Repair Order.	Maserati Indy
		Bill To	
		Peter Norell	Odometer:
		Address	VIN:
Date Received			
Date Wanted	Phone		
Call Customer If Repair Exceeds \$	Type of Equipment Received		
Shop Rate/Hr	Customer Request, Complaint		

Service Description	Qty.	Price	Total
Change Brake Hoses			\$250.00
Outside Labor- Rotor Turning			\$60.00
Paint Under Carriage- Cover car in Plastic, Wash/Scrub Front Subframe, Degrease, Rinse w/ Gasoline, Paint Floor Flat Black, Repair	18.75		\$1,300.00
Remove rear calipers, Disassemble Calipers for Rebuild, rebuild rear calipers	4	\$125.00	\$500.00
Outside Labor: Mount 5 tires	5	\$20.00	\$100.00
Drop off Brake Hoses, Pickup Front Grills from Powder Coating	2.5	\$65.00	\$162.50
Begin Dismantle, Order Additional Parts, Extract Rear Hubs, Remove Fr Calipers & Rotors, Rear Calipers, Rear Stab Bar,	5.75	\$125.00	\$718.75
Install rear Stabilizer bar, valve cover, prep shocks for install, install left shock, install fr stab bar, front end	4	\$125.00	\$500.00
Ceramic Coatings- Exhaust- Outside Labor			\$400.00
			\$0.00
			\$0.00
		Other Service May Be Listed On Back	\$3,991.25

Parts Description	Qty.	Price	Total
Front Brake Pad Set	1	\$115.00	\$115.00
Rear Brake Pad Set	1	\$102.00	\$102.00
Brake Fluid Reservoir	2	\$130.00	\$260.00
Front Windscreen Gasket*	1	\$543.06	\$543.06
Rear W/S Rub Linear*	1	\$273.16	\$273.16
Quarter Glass Seal - Right	1	\$214.15	\$214.15
Quarter Glass Seal - Left	1	\$214.15	\$214.15
1 5/8 inch Hose	5	\$8.99	\$44.95
Thermostat Bypass Hose	1	\$27.56	\$27.56
14mm id Cloth Braid	1.3	\$38.99	\$50.69
Coolant	3	\$18.00	\$54.00
14oz Body Repair Kit	1	\$16.99	\$16.99
Hardware			\$100.00
		Other Parts May Be Listed On Back	\$2,015.71

I fully understand the purpose of the safety devices on this equipment and specifically request that they not be repaired or replaced, and I assume responsibility for and hold you harmless from any injury to anyone that may result therefrom.

**Pickup And Delivery**

	<b>Total From Back</b>	<b>Total Parts</b>	
<input checked="" type="checkbox"/> X			\$2,015.71
AGREED TO And AUTHORIZED BY			

While the manufacturer may warrant the goods sold to the customer, we make no warranties, express or implied, including any implied warranties of merchantability or fitness, with respect to such goods.	<b>Subtotal</b>	<b>\$5,065.54</b>
	<b>Tax</b>	<b>\$181.39</b>
	<b>Total</b>	<b>\$5,246.93</b>

Not responsible for loss or damage in case of fire, theft, or any other cause beyond our control.

# Gran Turismo of Los Angeles

# Repair Order

1884 S Sepulveda Blvd Los Angeles, CA 90025 424-256-6867		Repair Order. <b>Maserati Indy</b>
paid 2500.00		
<b>Bill To</b>		Odometer:
Peter Norell	<b>Address</b>	VIN:
<b>Date Received</b>		
11/9/2015		
<b>Date Wanted</b>	<b>Phone</b>	
<b>Call Customer If Repair Exceeds \$</b>	<b>Type of Equipment Received</b>	quoted 6500 for upholstery
<b>Shop Rate/Hr</b>	<b>Customer Request, Complaint</b>	Total Labor 11/01/2016- 13272.75 Total parts 11/01/2016- 5532.83

Service Description	Qty.	Price	Total
Remove/Install All Surrounding Components For Paint and Most Major Exterior Pieces Hinges and Decals			\$1,800.00
Disassemble bumper parts and other parts for plating and chrome			\$350.00
Assemble Leaf springs, Assemble Front Rotors, Repack Bearings, Install Leaf Springs & Front Shocks, Smoke test exhaust for leaks,			\$1,218.75
Check Gauges, Remove Dashboard and Gauges, Clean Dash Lights	4.75	\$125.00	\$593.75
Weld muffler, Press Work For Leaf Spring Busing (Outside Labor)			\$128.00
Polish Lights/Tail, Install Taillights with new Hardware, Sand Down door to fit door handle (excess paint), New Hardware for handles	2.5	\$125.00	\$250.00
*Raymond Auto Glass (removal / Paid \$350)			\$700.00
Powder Coat- wheels, air scoops hood, air filter assembly, fender liner, front grills, ashtray slide and misc			\$912.00
Clean & Degrease Suspension Parts			\$65.00
Outside Labor: Chrome Plating (front rear and bumpers)			\$1,386.00
Stainless repair and polish - (outside work)		\$1,878.00	\$1,878.00
	Other Service May Be Listed On Back		\$9,281.50

Parts Description	Qty.	Price	Total
Green Pill Bulb For Dash	3	\$12.99	\$38.97
Engine Oil	10	\$6.99	\$69.90
Stabilizer bar Bushings	4	\$22.95	\$91.80
Bushing Silent Block	4	\$29.00	\$116.00
Bushing Leaf Spring End	4	\$44.00	\$176.00
Stabilizer Bar Bushing 18mm	2	\$22.95	\$45.90
Shock Absorber Rear	1	\$225.00	\$225.00
Shock Absorber Front	2	\$176.00	\$352.00
Axle Rod Support Mount (14mm)	1	\$135.50	\$135.50
Bushing - SilentBloc	1	\$32.91	\$32.91
Clamps- Various Sizes			\$34.00
Transmission Lines, Fuel Hose, Vacuum Hose			\$150.00
	Other Parts May Be Listed On Back	\$3,294.08	\$1,467.98

I fully understand the purpose of the safety devices on this equipment and specifically request that they not be repaired or replaced, and I assume responsibility for and hold you harmless from any injury to anyone that may result therefrom.

**Pickup And Delivery**


<b>Total From Back</b>	<b>Total Parts</b>	\$4,762.06
------------------------	--------------------	------------

**AGREED TO And AUTHORIZED BY**

<b>While the manufacturer may warrant the goods sold to the customer, we make no warranties, express or implied, including any implied warranties of merchantability or fitness, with respect to such goods.</b>	<b>Subtotal</b>	\$10,749.48
	<b>Tax</b>	\$132.11
	<b>Total</b>	<b>\$10,881.59</b>

Not responsible for loss or damage in case of fire, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with necessary material and hereby grant you and/or your employees permission to operate the unit as necessary for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above item to secure the amount of repairs thereto.



# ODD PARTS

18853 Orange  
Avenue  
Sonoma, CA 95476


# Invoice

DATE	Invoice
12/20/2018	5442

BILL TO	SHIP TO		
	Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292		
Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292	P.O. NO.	TERMS	SHIP VIA
	Eddie	PREPAID	UPS overnite

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Received Description	<p>DATE OF ARRIVAL: 12.21.2018 Via OVERNIGHT delivery.</p> <p>ITEM : This is a Infamous 3 pod "Square" Vitaloni switch from a 1971 Maserati Indy</p> <p>1. This switch assembly is complete without steering column surround cowling, with wiring harness and harness sheath, and with wiring harness cast plastic gang plugs.</p> <p>2. Item on switch that are clearly damaged or compromised include: Typical plastic shrinkage that has caused loss of several parts and damage to others- SEE missing parts below.</p> <p>3. Missing items from this switch that may need replacement are: SEE PHOTOS "as received" Missing wiper stalk arm Knob Missing both metal; headlamp and turn signal stalk arms, knobs and associated wiring.</p> <p>4. Additional notes and/or requirements: Conversations with Eddie on 12.20.2018 in brief include: Restored switch that we offer is \$3500.00 on an exchange basis. We currently do not have a completely restored switch on hand. We have all the extra used parts that are missing from your customer's switch available to include in you customer's core switch, together, to restore a complete assembly. The missing parts from your core switch we value at an additional \$2000.00. Alternately, we will accept in exchange a "Round Bodied Vitaloni switch" in exchange at \$2000.00 credit towards missing parts. Thus your total for resale will be \$3500.00 plus \$2000.00 and shipping and handling, less \$2000.00 if an exchange round body switch is offered.</p> <p>12.22.2018 Emailed Eddie with this progress report and a request for a signed CA resale card.</p>		0.00 0.00	0.00 0.00
			0.00	0.00

Please pay from this invoice-		<b>Total</b>	
Web Site		<b>Sales Tax (8.5%)</b>	
Phone #		<b>Subtotal</b>	
707 738 9661	oddparts.net	<b>Payments/Credits</b>	
		<b>Customer Total Balance</b>	



# ODD PARTS

18853 Orange  
Avenue  
Sonoma, CA 95476


# Invoice

DATE	Invoice
12/20/2018	5442

BILL TO	SHIP TO		
	Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292		
Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292	P.O. NO.	TERMS	SHIP VIA
	Eddie	PREPAID	UPS overnite

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Switch Labor 1	<p>Recommended Repairs include:</p> <ol style="list-style-type: none"> <li>1. Disassemble, clean, and detail all switch components.</li> <li>2. Remove all shrinkage cracked plastic at all switch stalk arms where the original plastic was cast around non-shrinking metal arms.</li> <li>3. Spot Weld two reinforcing steel wire loops to column end of metal switch arms that extends around the stalk arm pivot axis on switch body, and/ or replace stalk arm plastic sweep arm components with new SLS Nylon 3d engineered parts. as per ODD Parts discretion. and affix, adjust , detail and test.</li> <li>4. Re Solder loose connections, and Immerse these reinforcing wires in non-shrinking acrylic plastic, to stabilize and reinforce former loose contacts and spade terminals.</li> <li>5. Final finish reinforced stalk arms covered in plastic in hard shell UV proof glossy black urethane coating that is better detailed than original.</li> <li>6. Strip and re-electroplate original steel stalk arms in silver Zinc, and coat with clear lacquer where necessary.</li> <li>7. Remove mold-parting-seams from original thumb paddles and control knobs, and buff to high luster.</li> <li>8. Reinforce cracked twist-switch contact holder(s) using thin wall bronze sleeve pinned to stalk arm shaft, and backfill with non-shrinking acrylic plastic.</li> <li>9. Reinforce weak plastic "Clam Shell " housings using stainless steel wire and covered in acrylic plastic- and replace original copper grommets with suitable machine screws.</li> <li>10. Test and adjust turn signal mechanical cancelation mechanism. Test all electric contacts at 12 volts, 8 amps.</li> <li>11. Etch this invoice number into body of switch for future identification.</li> <li>12. All three component pods will be restored internally using specific and custom repair techniques that we have garnered on over 25 previous similar unit repairs. Some will be custom specific and unique to this switch only. a video of its final test will be offered to customer via Email testifying to restored functions of this specific switch- prior to payment.</li> </ol>	29	95.00	2,755.00
Shop Supplies (R...	Materials and Supplies: Abrasives, adhesives, solvents, mold materials, casting plastics, hardware, shop supplies.	1	500.00	500.00
Parts Sales (Resale)	Parts, Resale Custom 3D engineered headlamp, and Wiper nylon parts	1	245.00	245.00
Parts Sales (Resale)	Parts, Resale Core value- to be refunded upon exchange for complete ROUND body Maserati switch	1	2000.00	2,000.00

Please pay from this invoice-		<b>Total</b>	
Web Site		<b>Sales Tax (8.5%)</b>	
Phone #		<b>Subtotal</b>	
707 738 9661	oddparts.net	<b>Payments/Credits</b>	
		<b>Customer Total Balance</b>	



# ODD PARTS

18853 Orange  
Avenue  
Sonoma, CA 95476

# Invoice

DATE	Invoice
12/20/2018	5442

BILL TO	SHIP TO		
	Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292		
Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292	P.O. NO.	TERMS	SHIP VIA
	Eddie	PREPAID	UPS overnite

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
Switch Labor 1	<p>Recommended Repairs include:</p> <ol style="list-style-type: none"> <li>1. Disassemble, clean, and detail all switch components.</li> <li>2. Remove all shrinkage cracked plastic at all switch stalk arms where the original plastic was cast around non-shrinking metal arms.</li> <li>3. Spot Weld two reinforcing steel wire loops to column end of metal switch arms that extends around the stalk arm pivot axis on switch body, and/ or replace stalk arm plastic sweep arm components with new SLS Nylon 3d engineered parts. as per ODD Parts discretion. and affix, adjust, detail and test.</li> <li>4. Re Solder loose connections, and Immerse these reinforcing wires in non-shrinking acrylic plastic, to stabilize and reinforce former loose contacts and spade terminals.</li> <li>5. Final finish reinforced stalk arms covered in plastic in hard shell UV proof glossy black urethane coating that is better detailed than original.</li> <li>6. Strip and re-electroplate original steel stalk arms in silver Zinc, and coat with clear lacquer where necessary.</li> <li>7. Remove mold-parting-seams from original thumb paddles and control knobs, and buff to high luster.</li> <li>8. Reinforce cracked twist-switch contact holder(s) using thin wall bronze sleeve pinned to stalk arm shaft, and backfill with non-shrinking acrylic plastic.</li> <li>9. Reinforce weak plastic "Clam Shell" housings using stainless steel wire and covered in acrylic plastic- and replace original copper grommets with suitable machine screws.</li> <li>10. Test and adjust turn signal mechanical cancelation mechanism. Test all electric contacts at 12 volts, 8 amps.</li> <li>11. Etch this invoice number into body of switch for future identification.</li> <li>12. All three component pods will be restored internally using specific and custom repair techniques that we have garnered on over 25 previous similar unit repairs. Some will be custom specific and unique to this switch only. a video of its final test will be offered to customer via Email testifying to restored functions of this specific switch- prior to payment.</li> </ol>	29	95.00	2,755.00
Shop Supplies (R...	Materials and Supplies: Abrasives, adhesives, solvents, mold materials, casting plastics, hardware, shop supplies.	1	500.00	500.00
Parts Sales (Resale)	Parts, Resale Custom 3D engineered headlamp, and Wiper nylon parts	1	245.00	245.00
Parts Sales (Resale)	Parts, Resale Core value- to be refunded upon exchange for complete ROUND body Maserati switch	1	2000.00	2,000.00

Please pay from this invoice-		<b>Total</b>	
Web Site		<b>Sales Tax (8.5%)</b>	
Phone #		<b>Subtotal</b>	
707 738 9661		Payments/Credits	
oddparts.net		<b>Customer Total Balance</b>	



# ODD PARTS

18853 Orange  
Avenue  
Sonoma, CA 95476

# Invoice

DATE	Invoice
12/20/2018	5442

BILL TO	SHIP TO		
	Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292		
Chequered flag International 4128 Lincoln Avenue Marina Del Ray, CA 90292	P.O. NO.	TERMS	SHIP VIA
	Eddie	PREPAID	UPS overnite

ITEM	DESCRIPTION	QTY	RATE	AMOUNT
SHIPPING & HA...	SHIPPING AND HANDLING 01.02.2018 Changed to UPS Overnight arrival by 10:30 am shipping- can be changed back to ground if desired (two day)	1	135.33	135.33
ESTIMATE	Authorization to Repair (No Charge) 1. Photograph switch as received for communication and archiving. 2. Enlarge photos to display areas of concern and needed repairs. 3. Email these photos and illustration to customer for examination and authorization to proceed with restoration. 4. RECEIVED AUTHORIZATION to proceed with repairs : By whom <u>Eddie</u> Via <u>Email</u> Date <u>12.23.2018</u>		0.00	0.00
Estimated cost	Cost of credit card use-- CAN BE REMOVED if alternate payment is chosen	1	275.00	275.00

Please pay from this invoice-		<b>Total</b>	\$5,910.33
Web Site		<b>Sales Tax (8.5%)</b>	\$0.00
Phone #	707 738 9661	<b>Subtotal</b>	
oddparts.net		<b>Payments/Credits</b>	\$0.00
		<b>Customer Total Balance</b>	\$5,910.33

<b>MIAMI BENZ</b> 5844 COMMERCE LN Miami, FL. 33143 Phone: 305-740-3440 Fax: 305-740-9667	<b>FLORIDA REGISTRATION:</b> <b>MV-100472 MVR78008</b> _____ month/ _____ mile warranty on all <b>parts and labor unless otherwise specified.</b>
<b>ESTIMATE FOR SERVICES</b> Number: <b>019598</b>	<b>PROPOSED COMPLETION DATE:</b> <b>2/11/2019</b> Estimate Date / Time : <b>03/06/2019 3:35 PM</b>
<b>TYRRELL61 - ALFONSO REY</b> 4500 NW 36 STREET Miami, FL 33166 CELLULAR: 305-934-1004 Alfon Home: 786-271-5909	YMM : 1971 MASERATI - INDY - Lic # : - FL Odometer In: 0 Odometer Out: 0 VIN # : AM116491208

\*U/Used R/Rebuilt RC/Reconditioned NC/No Chg/Warranty RD/Reduced

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
ANTI FREEZE Q-1-03-0004	1.00	25.00	25.00	FULL INSPECTION ENGINE IS LEAKING MINOR OIL FROM ENGINE.	0.00
HEATER VALVE 5688	1.00	460.00	460.00	CHECK FAN AND COOLING SYSTEM REPAIR ELECTRICAL FANS AND WIRING.	820.00
OIL PRESSURE SENSOR SWITCH 8966488	1.00	180.00	180.00	INSTALLED NEW HEATER VALVE. REPAIR A/C LOW PRESSURE VALVE RECOVER AND RECHARGE A/C SYSTEM	
ENGINE OIL 15W 40	10.00	6.00	60.00	CHECK TACHOMETER AND OIL PRESSURE REPAIR WIRING SYSTEM TO TACH AND REPL OIL PRESSURE SENSOR.	480.00
OIL FILTER 1592	1.00	29.00	29.00	CHECK FOR SERVICE CHANGE ENGINE OIL AND FILTER.	920.00
Spark Plug BPR6ES NGK 7131	8.00	5.00	40.00	REPL ENGINE SPARK PLUGS AND ADJUST CARBURATORS. CLEAN UNDER VEHICLE AND TORQUE FRONT END SUSPENSION.	
FITTING 100000XX	1.00	20.00	20.00	TORQUE ENGINE OIL PAN. TORQUE VALVE COVERS	
ADAPTER MT0432	1.00	10.00	10.00	ADJST CARBURATORS REPL A/C COMPRESSOR FITTING TO BE ABLE TO	480.00
FITTING FT313C	1.00	3.00	3.00	RECHARGE SYSTEM WITH R134 FREON. CHECK BATTERY AND ALTERNATOR	960.00
Shop Supplies			15.00	REMOVE ALTERNATOR TO BE REPAIR. REPAIR ELECTRICAL WIRING TO VOLTAGE REGULATOR AND AMP METER.	
				Hazardous Materials	10.00

A storage fee of \$ \_\_\_\_\_ per day may be applied to vehicles which are not claimed within 3 working days of notification of completion

Parts/Supplies: 842.00

Labor: 3,660.00

Total : \$ 4,512.00

ESTIMATE/DIAGNOSTIC FEE: \$ \_\_\_\_\_ /OR HOURLY AT \$ \_\_\_\_\_ PER HOUR

Save old parts <input checked="" type="checkbox"/> Y <input type="checkbox"/> N (Core may apply)	Charges based on <input type="checkbox"/> Flat rate <input type="checkbox"/> Hourly rate <input type="checkbox"/> Both Payment Method <input type="checkbox"/> Cash <input type="checkbox"/> Check <input type="checkbox"/> Charge	ESTIMATE/DIAGNOSTIC FEE: \$ _____ /OR HOURLY AT \$ _____ PER HOUR. I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the vehicle described for testing and/or inspection. A storage fee of \$ _____ per day may be applied to vehicles which are not claimed within 3 working days of notification of completion. 3 month/4,000 mile warranty on all parts and labor unless otherwise specified. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.**/(s599.905(i)(h)
<p><b>PLEASE READ CAREFULLY,CHECK ONE OF THE STATEMENTS BELOW, AND SIGN:</b></p> <p>I UNDERSTAND THAT, UNDER STATE LAW, I AM ENTITLED TO A WRITTEN ESTIMATE IF MY FINAL BILL WILL EXCEED \$100.</p> <p>____ I REQUEST A WRITTEN ESTIMATE.</p> <p>____ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$ _____.</p> <p>THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.</p> <p>____ I DO NOT REQUEST A WRITTEN ESTIMATE.</p> <p>SIGNED _____ DATE _____</p>		<p>**This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. ***FS403.718 mandates a \$1.00 fee for each new tire sold in the State of Florida. ***FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.</p>
<p>AUTHORIZE SERVICE TO BE PERFORMED, INCLUDING SUBLET WORK. I HAVE READ AND UNDERSTAND THE ABOVE ITEMS.</p> <p>SIGNED: _____ DATE _____ TIME _____ am _____ pm _____</p> <p>ALTERNATE PERSON TO AUTHORIZE SERVICE TO BE PERFORMED, INCLUDING SUBLET WORK:</p> <p>Name _____ Phone _____</p>		

Auto A/C World Inc.

MV 29909 MVR 06444  
7920 NW 67th Street  
Miami, FL 33166

Invoice

Date Invoice #  
10/25/2019 19-1497

Bill To

TYRRELL 61  
305-934-1004  
JONATHAN

MAZERATI 197  
INDY

Attention

Description	VIN #	P.O. No.	Terms	Mileage
Description	Quantity	Rate	Amount	
MAZERATI 197 INDY SILVER REPLACE SEALS AT CONNECTIONS VACUUM AND RECHARGER SYSTEM TOTAL LABOR			115.00	115.00T

Thank you for your business. BUCKLE UP IT'S THE LAW.

<b>Subtotal</b>	\$115.00
<b>Sales Tax (7.0%)</b>	\$8.05
<b>Total</b>	\$123.05

Phone # 305-468-8387 Fax # 305-468-8239

Web Site  
www.autoacworld.com





# Invoice

02/04/2020

## MIE Corp

615 ST HELENS AVENUE  
TACOMA, WA. 98402 USA  
Phone: 253-833-2598  
Fax: 253-735-0946  
Email: mie@maseratinet.com

*MASERATI  
ZNOI*

S11969



### Bill To:

Jonathan Rey  
PO Box 025486  
Miami, FL 33166  
UNITED STATES  
Phone: 305-934-1004

### Ship To:

Jonathan Rey  
600 Wren Ave  
Miami Springs, FL 33166  
UNITED STATES  
Phone: 305-934-1004

Customer: Jonathan Rey

Contact: Jonathan Rey

Seller	Payment Terms	Carrier	Account #	Invoice Date
Stuart	Credit Card	FedEx GROUND	Rey001	02/06/2020

Item #	Number / Description	List Price	Sell Price	Qty	Total
1	66523 - OIL FILTER V8 (Spin-on) OEM FIAAM	\$ 29.00	\$ 29.00	1 ea	\$ 29.00
2	71163 - FRONT BRAKE PADS SET	\$ 79.00	\$ 79.00	1 set	\$ 79.00
3	SHIPPING - Shipping & Handling Charges Tracking: 478617342829	\$ 0.00	\$ 16.70	1 ea	\$ 16.70

<b>Subtotal:</b>	<b>\$ 124.70</b>
<b>Sales Tax:</b>	<b>\$ 0.00</b>
<b>Total:</b>	<b>\$ 124.70</b>

**VANTAGE MOTOR WORKS, INC.**  
 1898 N.E. 151St  
 North Miami, FL 33162  
 Ph (305)940-1161 Fax (305)949-7481  
 info@vantagemotorworks.com  
 www.vantagemotorworks.com

**INVOICE**  
**52584**  
 Written by  
 Victor

**TYRRELL 61 LLC**  
 7323 NW 44TH ST  
 MIAMI, FL 33166  
 Home: 305-934-1004  
 Cell: 305-934-1004

Florida Motor Vehicle Repair Registration Certificate MV5085  
 Miami-Dade County Registration 01619 MVR

Parts and Labor are guaranteed for 90 Days or 1000 miles, whichever comes first. Seller does not guarantee that the work performed in accordance with this Repair Order will correct any problem specified on the description of the complaint.

Color	Year	Make	Model	VIN	License	Hat		
SILVER	71	MASERATI	INDY 4900	AM 116 49 1208	NO TAG	2553		
Warr.Expires	Mileage IN	Mileage OUT	Payment	Date IN	Promised	Date OUT		
	38324	38324		15:06 07/16/20	17:00	11:13 08/24/20		
LINE * OPCODE TECH	DESCRIPTION		Wty / NC	HRS	List	LABOR Frgt	PARTS	TOTAL

**A TOWED IN TO VANTAGE MOTORWORKS**

3774	REPLACE ANTENNA (REAR MOUNT)	1.0 CP	230.00	230.00	200.00	430.00
1 44-PW22	UNIVERSAL FULLY AUTO POWER ANTENNA		200.00		200.00	

**B INSTALL CUSTOMER SUPPLIED WINDSHIELD**

5226 109	REPLACE WINDSHIELD & SEAL	10.0 CP	230.00	2300.00	0.00	2300.00
----------	---------------------------	---------	--------	---------	------	---------

**C CHECK PAINT WORK & REPAIR AS NECESSARY**

0127	BODY REPAIR, PREPARE PAINT & REFINISH	48.0 BD	150.00	7200.00	1603.63	8803.63
1 PPGDBCH-G	PPG DBC CODE H; GALLON; VOC-5.25		546.48		546.48	
1 MAT PBS	PAINT SHOP SUPPLIES		39.25		39.25	
1 PPGDC4000-G	VELOCITY PREMIUM CLEARCOAT GALLON;		354.85		354.85	
1 PPGDCH3095-QT	VOC-4.58 VELOCITY CLEARCOAT ACT. SLOW		115.70		115.70	
2 PPGDP402LF-QT	LF EPOXY PRIMER CATALYST; QUART		85.30		170.60	
1 PPGDP50LF-G	EPOXY PRIMER LF LIGHT GRAY; GAL 4.16-VOC		285.80		285.80	
1 PPGDT895-G	URETHAN HOT TEM REDUCER; GAL 7.00-VOC		90.95		90.95	

**CREDIT APPLIED**

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Returned checks are subject to a service charge of \$35.00 or the maximum allowed by the law. Other costs of collections and all penalties as permitted by law will also be assessed.

**MATERIALS CHARGE:** A material charge of 12.5% of the parts, labor and gas, oil & lube totals of your repair order, up to a maximum of \$39.00, will be added as a misc. charge to your invoice. This charge represents costs and profits to the motor vehicle repair facility for items such as miscellaneous shop supplies and/or waste disposal.

I UNDERSTAND THAT ALL PARTS AND ACCESSORIES SOLD OR USED ARE SUBJECT TO THE FEDERAL MAGNUSON-MOSS ACT AND THE CONSUMER MERCHANDISE PURCHASED IS UNDER LIMITED WARRANTY BY THE MANUFACTURER AND THE WRITTEN TERMS AND CONDITIONS THEREOF ARE AVAILABLE FOR MY INSPECTION.

CUSTOMER HEREBY ACKNOWLEDGES RECEIPT OF ABOVE MENTIONED VEHICLE AND RECEIPT OF INVOICE COPY HEREBY.


X

Labor Amount	9730.00
Parts Amount	1803.63
Sublet Amount	
Shop Supply Fees	39.00
<b>SUB-TOTAL</b>	<b>11572.63</b>
Sales Tax	EXEMPT
<b>TOTAL Invoice:</b>	<b>\$11,572.63</b>

MIAMI 01/09/20.

MASERATI  
INDY

## INSTALACION ELECTRICA VENTILADOR. RADIADOR AGUA



NOTA: ESTA INSTALACION FUE ECUIVADA  
POR ESTA RAZON DEJARON EL A/A  
PERMANENTE, PARA QUE FUNCIONE EL  
VENTILADOR.

AL REALIZAR LAS DOS INSTALACIONES  
CREO QUE ESTARA SOLUCIONADO EL  
PROBLEMA DE LA TAPA DE AGUA,  
Y AL UTILIZAR EL A/A FUNCIONARA LOS  
DOS VENTILADORES.

### IMPORTANTE

- 1) NECESITO SABER VALOR DE AVANCE DISTRIBUIDOR PARA LA PUESTA A PUNTO.
- 2) REMEN DE MARCHA LENTA RPM = ?


NO

MIAMI 01/09/20

MASERATI INDY

1

INSTALACION ELECTRICAS R/A



MASERATI  
INDY


01/10/20



COMPRESION MASERATI.  
FRENTE

PSI	150	□ 5	1	□ <del>120</del> 140	PSI
PSI	155	□ 6	2	□ <del>138</del> 140	PSI
PSI	165	□ 7	3	□ <del>131</del> 140	PSI
PSI	159	□ 8	4	□ <del>130</del> 140	PSI

CONEXIONADO ELECTRICO  
EVAPORADOR, BORLETTI  
CAMBIOGHINI




DEPARTMENT OF MOTOR VEHICLES

P.O. Box 942869

Sacramento, California 94269-0069

**INDY**  
FIRST CLASS MAIL ENCLOSED



3

**IMPORTANT DOCUMENT(S) ENCLOSED**

**A SMOG DEVICE INSPECTION MAY BE REQUIRED  
BEFORE THIS VEHICLE CAN BE TRANSFERRED**

**Saves  
Lives**




**Saves  
Fuel**

REG. 270 (REV. 6-86)

EDOARDO WEBER

# manuale di servizio

SERVIZIO MANUTENZIONE



SERIE DCOE

# 41

..... THE .....  
**SCOTTSDALE**  
..... *Auction* .....

## **1971 MASERATI INDY 4900**

Coachwork by Vignale

Chassis no. AM116/49\*1208\*  
Engine no. AM107/49\*1208\*

4,930cc DOHC V8 Engine  
4 Weber Carburetors  
320bhp at 5,500rpm  
5-Speed Manual Transmission  
Independent Front Suspension – Live Rear Axle  
4-Wheel Disc Brakes

- ★ *One of only 300 Indy 4900s produced*
- ★ *Numbers matching engine*
- ★ *Desirable ZF 5-Speed Manual Gearbox – 1 of only 39 sent to the US*
- ★ *Exceptional Candidate for Tours and Classic Rallies*
- ★ *Giovanni Michelotti-Designed Coachwork by Vignale*

**\$90,000 - 110,000**  
**WITHOUT RESERVE**

---

# Bonhams

11393

INVOICE

MERLIN AUTO GROUP 28 82 A M W I L E R R D ATLANTA, GA 30 3 6 0

(770) 457-2699 www.merlincargroup.com

S E R V I C E A D V I S O R : 113 ERIC CHIARELLI

BUS: CELL:

Table with 6 columns: GREY, 71, MASERATI INDY 4.9, AM116491208, 38598/38598, T393

Table with 6 columns: 12OCT22 DD, 18:00 01APR22, 200.00, CASH, 15OCT22, OPTIONS: SOLD-STK:P491208

Table with 2 columns: 15:47 01APR22, 13:04 15OCT22

Table with 4 columns: LINE, OPCODE, TECH TYPE, HOURS. Includes rows for A PERFORM USED VEHICLE INSPECTION and PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

Table with 4 columns: LINE, OPCODE, TECH TYPE, HOURS. Includes row for B CUSTOMER STATES THE VEHICLE HAS AN ENGINE MISFIRE and PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

Table with 4 columns: LINE, OPCODE, TECH TYPE, HOURS. Includes row for C\*\* BRAKE LIGHTS ARE NOT WORKING and PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

Table with 4 columns: LINE, OPCODE, TECH TYPE, HOURS. Includes row for D\*\* CUSTOMER STATES WIPERS RUN CONSTANTLY and PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE \*SHOP SUPPLY C... Includes signature lines for DATE, CUSTOMER SIGNATURE, AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE, and PLEASE PAY THIS AMOUNT.

CUSTOMER #: 10656

11393

MERLIN AUTO GROUP 28 82 A M W I L E R R D ATLANTA, GA 30 3 60

INVOICE

(770) 457-2699 www.merlincar.com

S E R V I C E A D V I S O R : 113 ERIC CHIARELLI

BUS: CELL:

Table with 6 columns: GREY, 71, MASERATI INDY 4.9, AM116491208, 38598/38598, T393

Table with 6 columns: 12OCT22 DD, 18:00 01APR22, 200.00, CASH, 15OCT22

OPTIONS: SOLD-STK:P491208

15:47 01APR22 13:04 15OCT22

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

38598 ADJUSTED STEERING COLUMN AND REROUTED WIRING. ISSUE RESOLVED.

\*\*\*\*\*

E\*\* PERFORM PRE-DELIVERY INSPECTION CAUSE: PERFORM PRE-DELIVERY INSPECTION PDI PERFORM PRE-DELIVERY INSPECTION 102 IUC

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00 (N/C)

38598 PERFORMED GENERAL INSPECTION. COMPETE.

\*\*\*\*\*

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE \*SHOP SUPPLY C... LABOR AMOUNT 0.00 PARTS AMOUNT 0.00... ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED. PLEASE PAY THIS AMOUNT

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
08/25/25	6000729/1
R/O Close Date	Status
10/22/25	
Mileage In	Mileage Out
40225	40225
Service Advisor / Tag #	
LAUREL BAKER	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	AM116491208	
Year	Make	Model	Body	Delivery Date	In-Service Date
1971	MASERATI	INDY 4.9		00/00/00	00/00/00
INVENTORY: P491208				Color	License Number
				GRAY	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>#1 - MR P3: PERFORM DETAILED MECHANICAL INSPECTION Tech: VS(121) FUEL Sub Total: Labor: .00 Parts: .00 Total: .00</p>	Internal Internal
<p>#2 - MR DIAG: DIAGNOSE Turn signals are not working, check and advise. Caused by Poor contact at front turn signal bulbs, flasher relay not working at left side bulbs and open circuit at turn signal stalk. Tech: MALCOLM BARNETT(102) Installed HLA961553161 :FLASHER Sub Total: Labor: .00 Parts: .00 Total: .00 Performed multiple wiring and component tests. Replaced flasher relay and cleaned bulb housings at front turn signals. R&amp;R turn signal stalk to clean contacts and contact wheel. Verified correct operation after repairs.</p>	Internal Internal
<p>#3 - MR DIAG: DIAGNOSE The driver's door will not lock, check and Caused by LOCK CYLINDER TIE ROD DETACHED AND NOT POSITIONED CORRECTLY. Tech: VS(121) Sub Total: Labor: .00 Parts: .00 Total: .00 LOCK CYLINDER TIE ROD ADJUSTED PROPERLY AND REINSTALLED. DOOR PANEL REASSEMBLED AND DOOR NOW</p>	Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

**NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.**

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
08/25/25	6000729/2
R/O Close Date	Status
10/22/25	
Mileage In	Mileage Out
40225	40225
Service Advisor / Tag #	
LAUREL BAKER	
Vehicle Identification Number	
AM116491208	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
GRAY	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	AM116491208	
Year	Make	Model	Body	Color	License Number
1971	MASERATI	INDY 4.9		GRAY	
INVENTORY: P491208					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
LOCKING FROM THE OUTSIDE.	
-----	
#4 - MR DIAG: DIAGNOSE Windshield washer jets do not work, check and advise Caused by Corrected poor contact at wiring connectors. R&R both spray screws to clean and re-position. Re-attached left sprayer tube that had fallen off. Verified correct operation after repairs. Tech: VS(121) Sub Total: Labor: .00 Parts: .00 Total: .00	Internal
-----	
#5 - MR DIAG: DIAGNOSE A/C is not blowing cold, check and advise. Caused by RECOVERED REFRIGERANT FROM A/C SYSTEM AND MEASURED 2OZ OF FREON MOST LIKELY INDICATING A LEAK. PULLED A VACUUM ON SYSTEM AND IT PASSED THE LEAK TEST. MOST LIKELY CAUSE OF LEAK ARE WEAK SHRADER VALVES. Tech: VS(121) Installed NPA3507 :NAPA A/C SCHRADER VALVE Installed R134A :R134A REFRIGERANT Installed SUM0463 :A/C ADAPTER HIGH SIDE Sub Total: Labor: .00 Parts: .00 Total: .00 SCHRADER VALVES WERE REPLACED, SYSTEM WAS TESTED FOR VACUUM, AND GIVEN THE PROPER CHARGE. SYSTEM NOW BLOWING COLD AIR AND BOTH HIGH AND LOW SIDE	Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
08/25/25	6000729/3
R/O Close Date	Status
10/22/25	
Mileage In	Mileage Out
40225	40225
Service Advisor / Tag #	
LAUREL BAKER	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	AM116491208	
Year	Make	Model	Body	Delivery Date	In-Service Date
1971	MASERATI	INDY 4.9		00/00/00	00/00/00
INVENTORY: P491208				Color	License Number
				GRAY	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>DESCRIPTION OF SERVICE AND PARTS PRESSURES WERE GOOD.</p> <hr/> <p>#6 - MR LOF: OIL AND FILTER CHANGE SERVICE, TOP OFF ALL NECESSA Caused by Service due Tech: VS(121) Tech: MALCOLM BARNETT(102) Installed ML66523 :OIL FILTER Installed WIN0109 :WINZER BRAKE PARTS CLEANER - O Installed CAS20W50 :CONV OIL Sub Total: Labor: .00 Parts: .00 Total: .00 Performed oil and filter service. Complete.</p> <hr/> <p>#7 - MR SUSP: DIAG SUSP ISSUE AND ADVISE Remove and replace failing engine mounts Caused by Left motor mount rubber cushion pad worn. Tech: MALCOLM BARNETT(102) Installed 1310N15 :RUBBER SHEET Sub Total: Labor: .00 Parts: .00 Total: .00 Hand made new rubber disc due to not being able to find original replacement.</p> <hr/> <p>#8 - MR BATT: REPLACE 12V BATTERY Caused by 12V MEASURED VERY LOW AMPERAGE, SHOWED SIGNS OF CORROSION, AND WOULD NOT HOLD CHARGE. Tech: VS(121)</p>	<p>Internal Internal Internal Internal Internal</p> <p>Internal Internal</p> <p>Internal</p>

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
08/25/25	6000729/4
R/O Close Date	Status
10/22/25	
Mileage In	Mileage Out
40225	40225
Service Advisor / Tag #	
LAUREL BAKER	
Vehicle Identification Number	
AM116491208	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
GRAY	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	AM116491208	
Year	Make	Model	Body	Color	License Number
1971	MASERATI	INDY 4.9		GRAY	
INVENTORY: P491208					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Installed MT-27 :BATTERY Sub Total: Labor: .00 Parts: .00 Total: .00 12V BATTERY REPLACED.	Internal
-----	
#9 - MR TIRE4: MOUNT AND BALANCE 4 NEW TIRES Caused by All four tires are 10 years old. Tech: MALCOLM BARNETT(102) Tech: JOSH WILLIAMS(128) Tech: VS(121) Installed 43944 :205VR14 MICH XWX Freight: FEDEX Installed HARDWARE :HARDWARE1 Sub Total: Labor: .00 Parts: .00 Total: .00 Replaced all four tires due to age.	Internal Internal Internal Internal Internal Internal
-----	
#10 -MR BRKFSH: PERFORM BRAKE FLUID EXCHANGE Caused by Brake fluid dark and front bleed screws were sheered off. Tech: VS(121) Tech: MALCOLM BARNETT(102) Installed 601458 :SYNTHETIC DOT 3 AND 4 BRAKE FL Installed 6751565 :BLEEDER PLUG Installed WIN0109 :WINZER BRAKE PARTS CLEANER - O Installed 152955 :FERRARI/MASERATI/BENTLEY/PORSC Sub Total: Labor: .00 Parts: .00 Total: .00 The front brake calipers had damage to the bleed screws and were broken off. Drilled, re-threaded,	Internal Internal Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

# MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360  
Ph: (770) 457-2699 | www.merlinautogroup.com

**SERVICE DEPARTMENT HOURS**  
9:00 a.m. to 6:00 p.m.  
Monday - Friday  
Closed Saturday & Sunday

R/O Open Date	R/O Number
08/25/25	6000729/5
R/O Close Date	Status
10/22/25	
Mileage In	Mileage Out
40225	40225
Service Advisor / Tag #	
LAUREL BAKER	

MERLIN AUTO GROUP 2882 AMWILER RD Atlanta, GA 30360			Work Phone	Vehicle Identification Number	
			Home Phone	AM116491208	
Year	Make	Model	Body	Delivery Date	In-Service Date
1971	MASERATI	INDY 4.9		00/00/00	00/00/00
INVENTORY: P491208				Color	License Number
				GRAY	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
installed new bleed screws. Complete. After repairs flushed complete brake system.	
-----	
#11 -MR SPARK: REPLACE SPARK PLUGS Caused by All spark plugs carbon fouled. Tech: MALCOLM BARNETT(102) Installed BPR6ES :FERRARI 308 SPARK PLUG NGK 713 Sub Total: Labor: .00 Parts: .00 Total: .00 Replaced all spark plugs due to fouled condition.	Internal Internal
-----	
#12 -MR CARB: TUNE CARBURETOR Adjust and synchronize carburetors Caused by Carburetors were out of synchronization. Tech: MALCOLM BARNETT(102) Installed HARDWARE :HARDWARE1 R&R airbox and linkage to individually adjust all four carburetors. Performed full synchronization and adjusted linkage rod for throttle.	Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X