

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 3/29/2018 4:44 PM Technician: Roger (8)

Customer Information	
Merlin Auto Group	
2882 Amwiler Rd	(B) (770)457-2699
Atlanta GA	
30360	

Vehicle Information	
1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
Engine:	transmission
VIN: ZFFXA20A4H0067505	
License:	Color:
Mileage (mi) 26,854 / 26,854	
Vehicle #P3301	

Customer Signature

Thank You for choosing Merlin Auto Group!



Merlin Auto Group

2882 Amwiler Rd
 Atlanta GA 30360
 (B)(770) 457-2699

Invoice Date: 3/29/2018 3:29 PM Technician: Wade (11)

Customer Information		Vehicle Information	
Merlin Auto Group 2882 Amwiler Rd (B) (770)457-2699 Atlanta GA 30360		1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,921 / 26,921 Vehicle #P3301	

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
ELEC	REPLACE THE BATTERY	1.000	0.00	0.00	0.00	0.00
MTP48H6	INTERSTATE MTP48H6 BATTERY	1.000	134.95	0.00	0.00	134.95
	Electrical Subtotal:		134.95	0.00	0.00	134.95
					Parts	134.95
					Labor	0.00
					Subtotal	134.95
					Total Due	134.95

Payment:

Other 134.95

Customer Signature

Thank You for choosing Merlin Auto Group!

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 10/9/2017 5:38 PM Technician: Phillip (6), Jason (2)

Customer Information		Vehicle Information	
Merlin Auto Group		1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
2882 Amwiler Rd	(B) (770)457-2699	Engine: transmission	
Atlanta GA		VIN: ZFFXA20A4H0067505	
30360		License: Color:	
		Mileage (mi) 26,854 / 26,854	
		Vehicle #P3301	

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
CMT	BELT SERVICE DUE	1.000	0.00	0.00	0.00	0.00
CMT	VEHICLE DRIPPING OIL/NO REPAIRS PERFORMED AT THIS TIME	1.000	0.00	0.00	0.00	0.00
	Other Subtotal:		0.00	0.00	0.00	0.00
105046	OEM A/C BELT	1.000	30.00	0.00	0.00	30.00
105206	BELT TENSIONER	2.000	27.96	0.00	0.00	55.92
105206	WATER PUMP BELT	1.000	24.00	0.00	0.00	24.00
130493	ALTERNATOR BELT	1.000	8.26	0.00	0.00	8.26
	Belts Subtotal:		118.18	0.00	0.00	118.18
191993	OIL FILTER	1.000	13.30	0.00	0.00	13.30
	LOF Subtotal:		13.30	0.00	0.00	13.30
					Parts	131.48
					Labor	0.00
					Subtotal	131.48
					Total Due	131.48

Payment:

Other 131.48

Thank You for choosing Merlin Auto Group!

**MERLIN
AUTO GROUP**

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 10/9/2017 5:38 PM Technician: Phillip (6), Jason (2)

Customer Information	Vehicle Information
Merlin Auto Group 2882 Amwiler Rd (B) (770)457-2699 Atlanta GA 30360	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,854 / 26,854 Vehicle #P3301

Customer Signature

Thank You for choosing Merlin Auto Group!

MERLIN AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 9/29/2017 5:18 PM Technician: Roger (8)

Customer Information		Vehicle Information	
Merlin Auto Group		1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
2882 Amwiler Rd	(B) (770)457-2699	Engine: transmission	
Atlanta GA		VIN: ZFFXA20A4H0067505	
30360		License: Color:	
		Mileage (mi) 26,854 / 26,854	
		Vehicle #P3301	

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
EI	328 ENGINE MAJOR SERVICE KIT PERFORMED MAJOR SERVICE	1.000	637.50	0.00	0.00	637.50
	Engine Subtotal:		637.50	0.00	0.00	637.50
115776	A/C COMPRESSOR	1.000	725.00	0.00	0.00	725.00
107402	A/C DRYER FITTINGS NOTE-SHIPPING COST \$14.95	1.000	60.00	0.00	14.95	74.95
	Climate Control (HVAC) Subtotal:		785.00	0.00	14.95	799.95

Parts	1,422.50
Labor	0.00
Subtotal	1,422.50
Other Charges	14.95
Total Due	1,437.45

Payment:

Other 1,437.45

Customer Signature

Thank You for choosing Merlin Auto Group!



Merlin Auto Group

2882 Amwiler Rd
 Atlanta GA 30360
 (B)(770) 457-2699

Invoice Date: 1/18/2017 8:11 PM Technician: Carl (5)

Customer Information		Vehicle Information	
Merlin Auto Group		1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
2882 Amwiler Rd	(B) (770)457-2699	Engine: transmission	
Atlanta GA		VIN: ZFFXA20A4H0067505	
30360		License: Color:	
		Mileage (mi) 26,725 / 26,731	
		Vehicle #P3301	

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
CMT	COMPRESSION TEST	1.000	0.00	0.00	0.00	0.00
	PERFORMED COMPSSION TEST AND ALL CYLINDERS					
	CHECKED GOOD 150 PSI					
	Other Subtotal:		0.00	0.00	0.00	0.00
					Parts	0.00
					Labor	0.00
					Subtotal	0.00
					Total Due	0.00

Customer Signature

Thank You for choosing Merlin Auto Group!

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 7/12/2018 4:31 PM Technician: Vance (10)

Customer Information	Vehicle Information
	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,935 / 26,935 Vehicle #P3301

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
BSHOP	BODY SHOP SUBLET NEEDED SUBLET TO THE COLLISION COMPANY FOR CERAMIC COATING	1.000	0.00	0.00	850.00	850.00
	Body / Glass / Paint Subtotal:		0.00	0.00	850.00	850.00

Parts	0.00
Labor	0.00
Subtotal	0.00
Other Charges	850.00
Total Due	850.00

Payment:

Other 850.00

Customer Signature

Thank You for choosing Merlin Auto Group!

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 7/9/2018 10:56 AM Technician: Vance (10), Malcolm (12)

Customer Information	Vehicle Information
	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,935 / 26,935 Vehicle #P3301

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
W-L	INSTALL RIGHT REAR WHEEL CENTER CAP-CHARGE TO AFTERSALES INSTALLED CENTER CAP/AFTERSALES EXPENSE P3301	1.000	0.00	0.00	0.00	0.00
108947	OEM Ferrari Cavallino Wheel Center Cap	1.000	50.00	0.00	0.00	50.00
WR	ATLANTA WHEEL REPAIR REPAIRED RIGHT FRONT AND RIGHT REAR WHEELS INV#M76182/AFTERSALES EXPENSE	1.000	0.00	0.00	100.00	100.00
	Tires / Wheels Subtotal:		50.00	0.00	100.00	150.00
BSHOP	SUBLET TO THE COLLISION COMPANY PDR WORK PERFORMED/DETAIL AND DOOR REPAIR/AFTERSALES EXPENSE	1.000	0.00	0.00	407.00	407.00
	Body / Glass / Paint Subtotal:		0.00	0.00	407.00	407.00

Parts	50.00
Labor	0.00
Subtotal	50.00
Other Charges	507.00
Total Due	557.00

Payment:

Charge 557.00

Thank You for choosing Merlin Auto Group!

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 7/9/2018 10:56 AM Technician: Vance (10), Malcolm (12)

Customer Information	
Canyon Inc	
12712 Brubaker Court	(M) (732)580-9053
San Diego CA	
92130	

Vehicle Information	
1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
Engine:	transmission
VIN:	ZFFXA20A4H0067505
License:	Color:
Mileage (mi)	26,935 / 26,935
Vehicle #	P3301

Customer Signature

Thank You for choosing Merlin Auto Group!

MERLIN AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 6/28/2018 9:29 AM Technician: Wade (11)

Customer Information	Vehicle Information
	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,854 / 26,935 Location: Malcolm Top Priority Vehicle #P3301

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
119409	DISTRIBUTOR CAP GASKET CORK	2.000	3.98	0.00	0.00	7.96
150075	END PLATE GASKET	1.000	18.50	0.00	0.00	18.50
150078	CAM COVER GASKET DX OEM	1.000	34.22	0.00	0.00	34.22
150084	CAM COVER GASKET SX OEM	1.000	33.21	0.00	0.00	33.21
150198	DISTRIBUTOR BASE GASKET	2.000	12.94	0.00	0.00	25.88
151342	END COVER GASKET	1.000	3.00	0.00	0.00	3.00
114808	CAM BOLT O-RING	4.000	4.45	0.00	0.00	17.80
117275	CAM O-RING	4.000	4.78	0.00	0.00	19.12
132453	DISTRIBUTOR DRIVE OIL SEAL	2.000	13.63	0.00	0.00	27.26
163987	OIL SEAL CAMSHAFT	4.000	8.00	0.00	0.00	32.00
111334	308/328 TIMING BELT	2.000	17.29	0.00	0.00	34.58
EE-L	ENGINE IS LEAKING OIL INSPECTION FOUND THE CAM COVERS WERE LEAKING OIL. DISASSEMBLE FOUND THE GASKETS WERE OVER SILICONED AND THE O-RINGS HAD NOTCHES WORN IN THEM. EVERYTHING WAS CLEANED AND PREPARED FOR REINSTALL. NEW GASKETS AND SEALS WERE INSTALLED. TEST FOUND TWO BAD PLUG WIRES AND THEY WERE REPLACED. I ALSO FOUND WHILE PRESSURE TESTING THE COOLANT SYSTEM, HOSES THAT WERE REPLACED PREVIOUSLY WERE NOW LEAKING. THE INTAKE MANIFOLD WAS REMOVED AND THE VALLEY HOSES WERE REPLACED. THE WATER PUMP TENSIONER BEARING NEEDED TO BE CLEANED AND REGREASED. NEW BELTS AND HOSES WERE INSTALLED. ALT. BRACKET STUD WAS REPLACED. SPARK PLUG LOOMS ON THE CAM COVERS WERE REPLACED.	1.000	0.00	0.00	0.00	0.00
118216	OIL RETURN HOSE	1.000	59.30	0.00	0.00	59.30
102947	2X6MM STUD MOUNT	3.000	9.83	0.00	0.00	29.49
13546621	ADJUSTING STUD	1.000	4.13	0.00	0.00	4.13
	Engine Subtotal:		346.45	0.00	0.00	346.45
121788	4 WAY IGNITION WIRE CLIP	4.000	5.29	0.00	0.00	21.16
121789	3 WAY IGNITION WIRE CLIP	1.000	3.90	0.00	0.00	3.90
121790	2 WAY IGNITION WIRE CLIP	2.000	3.60	0.00	0.00	7.20

Thank You for choosing Merlin Auto Group!

MERLIN AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 6/28/2018 9:29 AM Technician: Wade (11)

Customer Information	Vehicle Information
	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,854 / 26,935 Location: Malcolm Top Priority Vehicle #P3301

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
WSP1306PW W	7MM BLACK PLUG WIRE BY THE FOOT	5.000	1.62	0.00	0.00	8.10
NAPACOOLAN T	NAPA CONCENTRATE GREEN ANTIFREEZE COOLANT 1 GALLON	2.000	7.79	0.00	0.00	15.58
12611407	6.4X18X0.4MM BLACK TRIM WASHER	4.000	0.15	0.00	0.00	0.60
	Tune Up / Scheduled Maintenance Subtotal:		56.54	0.00	0.00	56.54
MT2047	YORK 206 209 210 SHAFT SEAL KIT DURING THE SERVICE OF THE CAR IT BECAME APPARENT THAT THE A/C COMPRESSOR HAD LEAKED ITS OIL OUT. DUE TO THE CAM SEAL LEAKS IT WAS NOT CLEAR THAT THE COMPRESSOR WAS ALSO LEAKING. I REMOVED THE SEAL TO REPLACE IT AND FOUND THE BEARING WAS VERY DRY AND BEGINNING TO RUST. I CHECKED THE OIL AND FOUND ALMOST NO OIL. AT THIS POINT I DISASSEMBLED THE COMPRESSOR AND FOUND IT HAD NOT BEEN DAMAGED BUT WAS IN NEED OF CLEANING AND FRESHENING. I CLEANED ALL OF THE PARTS, POLISHED THE NEEDED SURFACES AND REASSEMBLED. FILLED WITH OIL AND WAITED TO PAINT THE COMPRESSOR THE PROPER COLOR. WHEN THE PAINT ARRIVED IS MOVED THE COMPRESSOR AND FOUND IT WAS STILL LEAKING. I DRAINED AND DISASSEMBLED AND FOUND THAT A BOLT FOR MOUNTING ON THE CAR HAD BEEN INSTALLED THAT WAS TOO LONG, IT BOTTOMED OUT AND CRACKED THE HOUSING. IT IS THE PROPER DATE CODED UNIT SO I STRIPPED IT DOWN AND WELDED THE CRACK. THE UNIT WAS REASSEMBLED AND NOW HAS NO LEAKS. A NEW DRYER WAS INSTALLED AND THE SYSTEM WAS CHARGED WITH 134a.	1.000	25.00	0.00	0.00	25.00
	Climate Control (HVAC) Subtotal:		25.00	0.00	0.00	25.00

Thank You for choosing Merlin Auto Group!

MERLIN
AUTO GROUP

Merlin Auto Group

2882 Amwiler Rd
Atlanta GA 30360
(B)(770) 457-2699

Invoice Date: 6/28/2018 9:29 AM Technician: Wade (11)

Customer Information	Vehicle Information
	1987 Ferrari 328 GTS 3.2L V8 DOHC 32V Engine: transmission VIN: ZFFXA20A4H0067505 License: Color: Mileage (mi) 26,854 / 26,935 Location: Malcolm Top Priority Vehicle #P3301

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
ELEC-L	POWER ANTENNA WILL NOT GO DOWN-CHECK AND ADVISE INSPECTION FOUND ANTENNA WAS FULLY FUNCTIONAL BUT THE SWITCH WOULD NOT WORK FOR THE DOWN POSITION. REPLACED THE SWITCH. FULLY FUNCTIONS NOW. WHILE INSPECTING, I FOUND THE ANTENNA MOTOR BRACKET HAD BROKEN FROM THE HOUSING. AS IT WAS PLASTIC, REPAIR WAS REALLY NOT AN OPTION. I WAS HOWEVER ABLE TO USE A BARB FITTING ON THE BOTTOM OF THE HOUSING, I MADE A BRACKET THAT USES A GROMMET FOR THE BARB TO FIT INTO. ANTENNA IS NOW FULLY SECURE & FUNCTIONING.	1.000	0.00	0.00	0.00	0.00
126819	ANTENNA SWITCH 328	1.000	50.00	0.00	0.00	50.00
	Electrical Subtotal:		50.00	0.00	0.00	50.00
						Parts 477.99
						Labor 0.00
						Subtotal 477.99
						Total Due 477.99

Payment:

Other 477.99

Customer Signature

Thank You for choosing Merlin Auto Group!



Merlin Auto Group

2882 Amwiler Rd
 Atlanta GA 30360
 (B)(770) 457-2699

Invoice Date: 3/29/2018 4:44 PM Technician: Roger (8)

Customer Information		Vehicle Information	
Merlin Auto Group		1987 Ferrari 328 GTS 3.2L V8 DOHC 32V	
2882 Amwiler Rd	(B) (770)457-2699	Engine: transmission	
Atlanta GA		VIN: ZFFXA20A4H0067505	
30360		License: Color:	
		Mileage (mi) 26,854 / 26,854	
		Vehicle #P3301	

Operation/Part	Description	Quantity	Part	Labor	Other	Amount
EI	ENGINE LEAKING OIL AND COOLANT-CHECK AND ADVISE	1.000	0.00	0.00	0.00	0.00
	Engine Subtotal:		0.00	0.00	0.00	0.00
INSP	INSPECTION FORM: COMPLETE PHASE 3	1.000	0.00	0.00	0.00	0.00
	Inspection Subtotal:		0.00	0.00	0.00	0.00
609	1 1/2" COOLANT HOSE	1.000	15.49	0.00	0.00	15.49
ZX001	ZEREX GREEN ANTIFREEZE	2.000	15.99	0.00	0.00	31.98
	Cooling System Subtotal:		47.47	0.00	0.00	47.47
PENN 5W40	PENNZOIL 5W40 SYNTHETIC OIL	1.000	8.00	0.00	0.00	8.00
	Tune Up / Scheduled Maintenance Subtotal:		8.00	0.00	0.00	8.00

Parts	55.47
Labor	0.00
Subtotal	55.47
Total Due	55.47

Payment:

Other 55.47

Thank You for choosing Merlin Auto Group!

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/01/24	6000105/1
R/O Close Date	Status
10/30/24	Reprint
Mileage In	Mileage Out
28995	28995
Service Advisor / Tag #	
MARK MCDANIEL/105	
Vehicle Identification Number	
ZFFXA20A4H0067505	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
RED	

CANYON INC.			Work Phone	Vehicle Identification Number	
			Home Phone	ZFFXA20A4H0067505	
Year	Make	Model	Body	Color	License Number
1987	MAKE	328		RED	
P067505C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Email: mlewellen@merlinautogroup.com	
<p>#1 - MR P3: PERFORM DETAILED MECHANICAL INSPECTION</p> <p>Caused by Phase Three Inspection Tech: WADE WILLIAMS (101) Inspection found the car in very nice condition. Minor issues. Reverse lights INOP Needs Tires Clutch pedal pad is broken Rear hood struts are weak Due for a major service by time Only active leaks noted at this time from CV boots, R Inner boot is broken The complete report is in the Fast Field Report</p>	Internal
<p>#2 - MR LIGHTS: CHECK AND ADVISE</p> <p>Reverse lights do not work, advise. Caused by Bad Reverse Switch Tech: WADE WILLIAMS (101) Tech: WADE WILLIAMS (101) Tech: WADE WILLIAMS (101)</p> <p>Inspection found the reverse lights were INOP. The shift gate was installed backwards. The shift rod has a hose clamp and rubber putty on the shaft in a failed attempt to make the reverse lights come on. I removed the console parts to</p>	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS

9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/01/24	6000105/2
R/O Close Date	Status
10/30/24	Reprint
Mileage In	Mileage Out
28995	28995
Service Advisor / Tag #	
MARK MCDANIEL/105	
Vehicle Identification Number	
ZFFXA20A4H0067505	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
RED	

CANYON INC.			Work Phone	Vehicle Identification Number	
			Home Phone	ZFFXA20A4H0067505	
Year	Make	Model	Body	Color	License Number
1987	MAKE	328		RED	
P067505C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>access the switch connection and jumped the connection. The reverse lights came on. It needs a new switch and clean off the clamp and rubber putty from the stick. The console will need to be lifted up and access the switch itself. Seats come out to do this.</p>	
<p>#3 - MR BODY: BODY Targa roof does not latch properly, advise. Caused by Rubber Bumper Dislodged Tech: WADE WILLIAMS (101)</p> <p>The top latch has a rubber bumper cushion that seats against the body. That bumper cushion had fallen off and was under the seat. It is a bit cracked but back on the latch. Recommend replacing.</p>	
<p>#4 - MR TRANS: TRANS Replace reverse light switch. Caused by Bad Reverse Light Switch Tech: WADE WILLIAMS (101) Installed 57935K16 :TAPERED PLUG PKG Installed 115980 :REVERSE SWITCH Sub Total: Labor: Inspection found the reverse light switch was not functioning. The center console and forward</p>	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/01/24	6000105/3
R/O Close Date	Status
10/30/24	Reprint
Mileage In	Mileage Out
28995	28995
Service Advisor / Tag #	
MARK MCDANIEL/105	
Vehicle Identification Number	
ZFFXA20A4H0067505	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
RED	

CANYON INC.			Work Phone	Vehicle Identification Number	
			Home Phone	ZFFXA20A4H0067505	
Year	Make	Model	Body	Color	License Number
1987	MAKE	328		RED	
P067505C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
console were removed to gain access to the switch. It was removed and a new switch installed. The switch installed worked couple times and stopped. I retested the circuit and found no issue. I bench tested the new switch and found it to be faulty. A second switch was ordered and that one works as it should. The newer switch was installed and full function was restored. The consoles were installed.	

#5 - MR BODY: BODY Replace windshield washer reservoir top. Caused by Missing Cap Tech: WADE WILLIAMS (101) ! During the inspection, it was noted that the cap for the washer fluid bottle was missing. We found a suitable replacement and will install that.	

#6 - MR BODY: BODY Replace targa roof latch. Caused by Bad Latch Tech: WADE WILLIAMS (101) Installed 60421500 :TARGA TOP LATCH Freight: UPS Sub Inspection found the latch tip which is rubber	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/01/24	6000105/4
R/O Close Date	Status
10/30/24	Reprint
Mileage In	Mileage Out
28995	28995
Service Advisor / Tag #	
MARK MCDANIEL/105	
Vehicle Identification Number	
ZFFXA20A4H0067505	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
RED	

CANYON INC.			Work Phone	Vehicle Identification Number	
			Home Phone	ZFFXA20A4H0067505	
Year	Make	Model	Body	Color	License Number
1987	MAKE	328		RED	
P067505C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
and keeps pressure on the top when latched had come off. A new latch assembly was ordered and it has been installed.	

#7 - MR WIRING: WIRING Correct mirror switch wiring. Caused by Switch was Installed Backwards Tech: WADE WILLIAMS (101) Inspection found the mirror switch operation was all wrong. I was able to remove the switch and turn it around and put it back in. This corrected the action orientation of the switch.	

#8 - MR BODY: BODY Replace decklid struts. Caused by Bad Struts Tech: WADE WILLIAMS (101) Installed 60592800 :FERRARI HOOD SHOCK/SUPPORT 308 S Inspection found the struts were not holding. Replaced both struts.	

#9 - MR ENGINE: ENGINE Replace missing exhaust nut. Caused by Nut Missing	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/01/24	6000105/5
R/O Close Date	Status
10/30/24	Reprint
Mileage In	Mileage Out
28995	28995
Service Advisor / Tag #	
MARK MCDANIEL/105	
Vehicle Identification Number	
ZFFXA20A4H0067505	
Delivery Date	In-Service Date
00/00/00	00/00/00
Color	License Number
RED	

CANYON INC.			Work Phone	Vehicle Identification Number	
			Home Phone	ZFFXA20A4H0067505	
Year	Make	Model	Body	Delivery Date	In-Service Date
1987	MAKE	328		00/00/00	00/00/00
P067505C				Color	License Number
				RED	

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Tech: WADE WILLIAMS (101) Installed 138392 :FERRARI/MASERATI EXHAUST MANIF Inspection found a nut missing from the exhaust header. A new nut was installed.	
#10 * MR INTERIOR: INTERIOR INSTALL NEW CLUTCH PEDAL PAD Tech: WADE WILLIAMS (101) Installed 106949 :FERRARI FOOT PEADAL PAD 308/32 Replaced clutch pedal pad.	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	
INVENTORY 2520/P067505C	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

REPAIR ORDER

MERLIN AUTO GROUP
2882 AMWILER RD
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
	5/29/25	6000574/1
Home Phone	R/O Close Date	Receipt No.
	Pre-Invoice	
Body	Mileage In	Mileage Out
	29016	29016
License Number	Service Advisor	
	LAUREL BAKER	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
1987	FERRARI	328
Vehicle Identification Number		Color
ZFFXA20A4H0067505		RED

INVENTORY: P067505C

#1 - FERMAJOR: PERFORM FERRARI MAJOR SERVICE
COMPLETE 328 MAJOR SERVICE
Caused by Time For Service
Work performed by Tech 101
WIN0109 :WINZER BRAKE PARTS CLEANER - O
MOB75W90 :MOBIL 1 75W90 GEAR OIL 1 QUART
PEN5W40 :PENNZOIL 5W40
WIN0109 :WINZER BRAKE PARTS CLEANER - O
1GAL :GREEN COOLANT
10261860 :COPPER WASHER M22 X 29 4602229
105046 :FERRARI A/C BELT 308/328
105206 :FERRARI TIMING BELT BEARING 30
111334 :FERRARI 308QV/328QV TIMING BEL
114808 :FERRARI CAM BOLT O-RING 348/35
117275 :FERRARI CAM O-RING 308/328/348
117792 :FERRARI FUEL FILTER 308/328/35
118006 :FERRARI AIR FILTER 308/328/MON
119409 :FERRARI DISTRIBUTOR CAP CORK G
121655 :FERRARI WATER PUMP BELT 308/32
130493 :FERRARI ACCESSORY BELT 308/328
132453 :FERRARI 328/412/MONDIAL DISTRI
150075 :FERRARI END PLATE GASKET308/34
150078 :FERRARI CAM COVER GASKET 308/3
150084 :FERRARI CAM COVER GASKET 308/3
150198 :FERRARI DISTRIBUTOR BASE GASKE
151342 :FERRARI END PLATE GASKET RR 30
163987 :FERRARI CAM SEAL CYLINDER HEAD
191993 :FERRARI UFI OIL FILTER 308/512
601458 :SYNTHETIC DOT 3 AND 4 BRAKE FL
150180 :NGK PLUG DR8EIX 6681
5391625 :HOSE CLAMP NORMA M16 X 25
Performed Major service: Cam & accessory belts,
valve adjustment, cam seals & o-rings, tension
bearings. All fluids. Full inspection. Post
service test drive found right turn cancelation
is not working. Right window is slow on the way
up. I recommend replacing the intake bellows.

I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR					
PARTS					
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES					
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					

REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP
 2882 AMWILER RD
 Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	6000574/1
Body	Pre-Invoice	Receipt No.
License Number	Mileage In	Mileage Out
Account No.	29016	29016
	Service Advisor	
	LAUREL BAKER	
	Delivery Date	In-Service Date

Year	Make	Model
1987	FERRARI	328
Vehicle Identification Number		Color
ZFFXA20A4H0067505		RED

INVENTORY: P067505C

Tires are old and have some minor cracks.

#2 - CVBOOT: REPLACE CV BOOTS
 REPLACE CV BOOTS DUE TO AGE, FRONT AND REAR
 Caused by Torn CV Boot
 Work performed by Tech 101
 95860404 :FERRARI CV JOINT BOOT 308/328/
 SL3174 :CV JNT GREASE
 During the service, the inner R CV boot was found
 torn. The axles were removed and disassembled,
 cleaned, inspected, & assembled with new boots,
 clamps, & grease. They were installed and

I

#3 - INTAKE: INTAKE
 REPLACE AIR INTAKE BELLOWS
 Caused by Broken Bellow
 Work performed by Tech 101
 114019 :INTAKE BOOT
 Purchase Order 7001623:EUROSPARES
 Freight:
 Installed new bellow.

I

	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR				
PARTS				
DEDUCTIBLE				
SUBLET				
SHOP SUPPLIES				
HAZARDOUS MATERIALS				
SALES TAX OR TAX I.D.				
SPECIAL ORDER DEPOSIT				
DISCOUNTS				