

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. I hereby authorize the repair work hereafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere; for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

#1 -

MR NOSTART: NO START, CHECK AND ADVISE

3869 FOUND SEVERAL GROUND WIRES NOT COMPLETELY

CONNECTED. THE BATTERY SWITCH IS BAD THE STARTER N

FEEDS TO BE REPLACED IT DOES NOT WANT TO ENGAGE.

Tech: MAT PERKIN(104)

Installed H156 :1/2 INCH HEATER HOSE

Installed HLY558495 :CABLE

Installed SNE550511BAX :SNIPER 2 KIT

Installed WIX51069 :OIL FILTER

Installed 17025 :OXYGEN SENSOR

Installed 2441601 :GM STARTER

Installed 399273 :GM SFI APPROVED FLEXPLATE

Installed 785600 :WIRE

Installed 785602 :WIRE

822347 :VALVETINE 20W50 VRI ENGINE OIL

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
----------------------------------	--------

MERTLIN AUTO GROUP 2882 Armwiler Rd. - Atlanta, GA 30360 Ph: (770) 457-2699 www.merlinautogroup.com		WORK PHONE HOME PHONE VEHICLE IDENTIFICATION NUMBER 124379N631049 DELIVERY DATE IN-SERVICE DATE 00/00/00 COLOR LICENSE NUMBER 00/00/00		YEAR 1969 MAKE CHEVROLET MODEL CAMARO	P631049 P631049
---	--	---	--	--	----------------------------------

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

MERLIN
AUTO GROUP
2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

TERMS: STRICTLY CASH WITHIN 30 DAYS OF DELIVERY. ALL WARRANTIES ARE MADE "AS IS". HEREBY GUARANTEEING THE DEPARTMENT OF MOTOR VEHICLES THAT THE VEHICLE IS IN COMPLIANCE WITH ALL APPLICABLE FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS. THE SELLER ASSUMES NO LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS. ANY LIMITATION CONTAINED HEREIN DOES NOT APPLY WHERE PROHIBITED BY LAW.

6 - MR HVAC: HVAC
3869 MISSING HOSE THE DRAIN HOSE WAS NOT INSTALLED AFTER CARPET. I INSTALLED THE DRAIN HOSE.
Tech: MADE WILLIAMS(101)

#5 - MR DIAG: DIAGNOSE
3869 POSSIBLE OIL CONTAMINATION FOUND THE OIL SM
ELTS HEAVILY OF GAS. I DRAINED THE OIL AND IT WAS
VERY RUNNY AND BLACK AND SMELT OF OIL. I REMOVED
THE FILTER AND CUT IT OPEN BUT FOUND NOTHING. I W
ITL CHANGE THE OIL AND FILTER AND REEVALUATE. AFTE
R THE
Tech: WADE WILLIAMS(101)

#4 - MR NOSTART: NO START, CHECK AND ADVISE
3869 BAD FUEL INJECTION UNIT INSPECTION FOUND TH
E VOLTAGE AT THE IGNITION WAS LOW. WILL REMIRE TO
GET MORE VOLTAGE. VOLTAGE IS GOOD. SYSTEM STILL WI
LT NOT SPARK WHEN TURNING OVER THE ENGINE. I HAVE
TESTED ALL OF THE WIRING WITH NO ISSUES FOUND. I H
AVE T
TECH: MADE WILLIAMS(101)

X PLATE AND STARTER. AFTER PUTTING THE CAR BACK TO
GETHER CAR WOULD NOT START JUST TURN OVER.
Tech: MAT PERRIN (104)

AMOUNT	DESCRIPTION OF SERVICE AND PARTS
100.00	REPAIR WORK ON ENGINE
50.00	REPAIR WORK ON TRANSMISSION
25.00	REPAIR WORK ON BRAKES
15.00	REPAIR WORK ON STEERING
10.00	REPAIR WORK ON ELECTRICAL
5.00	REPAIR WORK ON TIRE
2.00	REPAIR WORK ON LUBRICATION
1.00	REPAIR WORK ON WASH/WAX
0.50	REPAIR WORK ON INSPECTION
0.25	REPAIR WORK ON TUNE-UP
0.10	REPAIR WORK ON FLUIDS
0.05	REPAIR WORK ON BELT
0.02	REPAIR WORK ON BATTERY
0.01	REPAIR WORK ON LIGHTS
0.00	REPAIR WORK ON HORN
0.00	REPAIR WORK ON WIPERS
0.00	REPAIR WORK ON MIRRORS
0.00	REPAIR WORK ON SEATBELT
0.00	REPAIR WORK ON AIRBAG
0.00	REPAIR WORK ON SAFETY
0.00	REPAIR WORK ON EMISSIONS
0.00	REPAIR WORK ON NOISE
0.00	REPAIR WORK ON VIBRATION
0.00	REPAIR WORK ON SHOCK
0.00	REPAIR WORK ON SPRING
0.00	REPAIR WORK ON SUSPENSION
0.00	REPAIR WORK ON ALIGNMENT
0.00	REPAIR WORK ON BALANCE
0.00	REPAIR WORK ON ROTATION
0.00	REPAIR WORK ON TIRE
0.00	REPAIR WORK ON WHEEL
0.00	REPAIR WORK ON HUB
0.00	REPAIR WORK ON AXLE
0.00	REPAIR WORK ON DRIVE
0.00	REPAIR WORK ON SHAFT
0.00	REPAIR WORK ON CLUTCH
0.00	REPAIR WORK ON BRAKE
0.00	REPAIR WORK ON PEDAL
0.00	REPAIR WORK ON MASTER
0.00	REPAIR WORK ON SLAVE
0.00	REPAIR WORK ON CYLINDER
0.00	REPAIR WORK ON PISTON
0.00	REPAIR WORK ON RING
0.00	REPAIR WORK ON VALVE
0.00	REPAIR WORK ON CAM
0.00	REPAIR WORK ON TIE
0.00	REPAIR WORK ON ROD
0.00	REPAIR WORK ON CRANK
0.00	REPAIR WORK ON COIL
0.00	REPAIR WORK ON SPARK
0.00	REPAIR WORK ON PLUG
0.00	REPAIR WORK ON WIRE
0.00	REPAIR WORK ON BATTERY
0.00	REPAIR WORK ON ALTERNATOR
0.00	REPAIR WORK ON REGULATOR
0.00	REPAIR WORK ON BELT
0.00	REPAIR WORK ON WATER
0.00	REPAIR WORK ON PUMP
0.00	REPAIR WORK ON HOSE
0.00	REPAIR WORK ON FITTING
0.00	REPAIR WORK ON VALVE
0.00	REPAIR WORK ON PLUG
0.00	REPAIR WORK ON GASKET
0.00	REPAIR WORK ON OIL
0.00	REPAIR WORK ON FILTER
0.00	REPAIR WORK ON DRAIN
0.00	REPAIR WORK ON FILL
0.00	REPAIR WORK ON CAP
0.00	REPAIR WORK ON SCREW
0.00	REPAIR WORK ON NUT
0.00	REPAIR WORK ON BOLT
0.00	REPAIR WORK ON WASH
0.00	REPAIR WORK ON WAX
0.00	REPAIR WORK ON INSPECTION
0.00	REPAIR WORK ON TUNE-UP
0.00	REPAIR WORK ON FLUIDS
0.00	REPAIR WORK ON BELT
0.00	REPAIR WORK ON BATTERY
0.00	REPAIR WORK ON LIGHTS
0.00	REPAIR WORK ON HORN
0.00	REPAIR WORK ON WIPERS
0.00	REPAIR WORK ON MIRRORS
0.00	REPAIR WORK ON SEATBELT
0.00	REPAIR WORK ON AIRBAG
0.00	REPAIR WORK ON SAFETY
0.00	REPAIR WORK ON EMISSIONS
0.00	REPAIR WORK ON NOISE
0.00	REPAIR WORK ON VIBRATION
0.00	REPAIR WORK ON SHOCK
0.00	REPAIR WORK ON SPRING
0.00	REPAIR WORK ON SUSPENSION
0.00	REPAIR WORK ON ALIGNMENT
0.00	REPAIR WORK ON BALANCE
0.00	REPAIR WORK ON ROTATION
0.00	REPAIR WORK ON TIRE
0.00	REPAIR WORK ON WHEEL
0.00	REPAIR WORK ON HUB
0.00	REPAIR WORK ON AXLE
0.00	REPAIR WORK ON DRIVE
0.00	REPAIR WORK ON SHAFT
0.00	REPAIR WORK ON CLUTCH
0.00	REPAIR WORK ON BRAKE
0.00	REPAIR WORK ON PEDAL
0.00	REPAIR WORK ON MASTER
0.00	REPAIR WORK ON SLAVE
0.00	REPAIR WORK ON CYLINDER
0.00	REPAIR WORK ON PISTON
0.00	REPAIR WORK ON RING
0.00	REPAIR WORK ON VALVE
0.00	REPAIR WORK ON CAM
0.00	REPAIR WORK ON TIE
0.00	REPAIR WORK ON ROD
0.00	REPAIR WORK ON CRANK
0.00	REPAIR WORK ON COIL
0.00	REPAIR WORK ON SPARK
0.00	REPAIR WORK ON PLUG
0.00	REPAIR WORK ON WIRE
0.00	REPAIR WORK ON BATTERY
0.00	REPAIR WORK ON ALTERNATOR
0.00	REPAIR WORK ON REGULATOR
0.00	REPAIR WORK ON BELT
0.00	REPAIR WORK ON WATER
0.00	REPAIR WORK ON PUMP
0.00	REPAIR WORK ON HOSE
0.00	REPAIR WORK ON FITTING
0.00	REPAIR WORK ON VALVE
0.00	REPAIR WORK ON PLUG
0.00	REPAIR WORK ON GASKET
0.00	REPAIR WORK ON OIL
0.00	REPAIR WORK ON FILTER
0.00	REPAIR WORK ON DRAIN
0.00	REPAIR WORK ON FILL
0.00	REPAIR WORK ON CAP
0.00	REPAIR WORK ON SCREW
0.00	REPAIR WORK ON NUT
0.00	REPAIR WORK ON BOLT
0.00	REPAIR WORK ON WASH
0.00	REPAIR WORK ON WAX
0.00	REPAIR WORK ON

MERRLIN AUTO GROUP 2882 Amwiler Rd. - Atlanta, GA 30380 Ph: (770) 457-2699 www.merlinautogroup.com												SERVICE DEPARTMENT HOURS 9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday												ADAM MERRLIN Service Advisor / Tag # 3869 Mileage In 09/12/24 Reprint Status 05/15/24 R/O Open Date R/O Number 13013/2												Work Phone Vehicle Identification Number 124379N631049 In-Service Date 00/00/00 Color SILVER License Number 00/00/00												Year 1969 Make CHEVROLET Model CAMARO Body												P631049											
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	-------------------------------	--	--	--	--	--	--	--	--	--	--	--

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

MERLIN
AUTO GROUP
2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by my supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on street, highway, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs hereinto."

#7 - MR HVAC: HVAC
3869 HOSE DISCONNECTED STEREO GUYS LEFT THE HOSE
DISCONNECTED AND TUCKED OUT OF THE WAY. IT IS CON
NECTED AND WORKING.
Tech: MADE WILLIAMS (101)

MERLIN AUTO GROUP 2882 Armwiler Rd. - Atlanta, GA 30360 Ph: (770) 457-2699 www.merlinautogroup.com		SERVICE DEPARTMENT HOURS 9:00 a.m. to 6:00 p.m. Monday - Friday Closed Saturday & Sunday	
R/O Open Date	05/15/24	R/O Close Date	09/12/24
R/O Number	13013/3	Status	Reprint
		Mileage In	3869
		Mileage Out	3869
		Service Advisor / Tag #	ADAM MERLIN
Vehicle Identification Number	124379N631049	Home Phone	
Delivery Date	00/00/00	Work Phone	
In-Service Date	00/00/00	Body	
License Number	00/00/00	Model	CHEVROLET
		Make	CAMARO
Year	1969		
P631049			

MERLIN
AUTO GROUP
2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

MERTLIN AUTO GROUP

2882 AMWILDER RD
ATLANTA, GA 30360
(770) 457-2699
www.merlinauto.org

INVOICE

11271

CUSTOMER #: 10485

PAGE 1

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN/OUT	TAG
		69	CHEVROLET Camaro		124379N631049			3866/3866	T271
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
01JAN69 DI				18:00 09FEB22		CASH	27APR22		
R.O. OPENED		READY		OPTIONS:					
14:58 09FEB22		14:15 27APR22							
LINE OP CODE TECH TYPE HOURS									
LIST		NET		TOTAL					

A VEHICLE HAS A STRONG FUEL SMELL, CHECK AND ADVISE

CAUSE: Old fuel lines
MISC SEE TECH NOTES FOR INITIAL INSPECTION

RESULTS

3866 Old fuel lines inspection found the fuel lines are older and should be updated. There is a fuel smell from the area of the under car fuel lines. The over all installation of the fuel system is less than optimal. I would recommend starting at the fuel tank and address the entire fuel system. New hose, proper fittings, rewrite with appropriate connectors and wire protection. Time estimates depend on what is discovered after disassembly. The wiring should be incorporated into a complete rewrite of the entire car.

B VEHICLE WILL NOT STAY RUNNING, CHECK AND ADVISE

CAUSE: Bad alternator
MISC SEE TECH NOTES, THIS WAS DURING THE INITIAL

INSPECTION

3866 Bad alternator inspection found the battery to be very low. With a full charge the car stayed running. Need to repair the

alternator.

C PERFORM FULL VEHICLE MULTI-POINT INSPECTION

CAUSE: Old built in need of many updates.

MPI PERFORM FULL VEHICLE MULTI-POINT INSPECTION

101 C

3866 Old built in need of many updates.

The inspection finds a very well done engine / transmission / rear end build. The engine is a Part SHP block 434ci AFR heads. It is an old build and updates should be made.
The engine has several leaks, oil and coolant. The cam is a flat tappet hydraulic and should be updated to a hydraulic roller. The hydraulic roller will work much better with modern oils. It also has

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT
WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE. THE DEALERSHIP AND CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY OR DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.			
By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.			
ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	SALES TAX	LESS INSURANCE	TOTAL CHARGES
MISC. CHARGES *	SUBLET AMOUNT	GAS, OIL, LUBE	PARTS AMOUNT
LABOR AMOUNT	TOTALS		

CUSTOMER COPY

DEBIT CARD 2014 GM GLOBAL LLC 4011177 SERVICE INVOICE TYPE 2 25120 - MS-SF - GENERIC - 10001010

MERLIN AUTO GROUP

2882 AMWILLER RD
ATLANTA, GA 30360
(770) 457-2699
www.merlinauto.com

INVOICE

11271

CUSTOMER #: 10485

HOME:		BUS:		COUNT:		SERVICE ADVISOR: 111 DANIEL JOFFE	
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
69	CHEVROLET Camaro	124379N631049			3866/3866	T271	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN69 DD			18:00 09FEB22			CASH	27APR22
R.O. OPENED		READY		OPTIONS:			
14:58 09FEB22		14:15 27APR22					
LINE		OPCODE		TECH TYPE		HOURS	
LIST		NET		TOTAL			

The alternator needs to be repaired as it is not charging. The power steering pump is leaking and needs to be replaced. The coolant and heater hoses need to be replaced and again updated to a more modern set up. We need to get away from the braided stainless steel hoses and covers. On a driven street car, the abrasiveness will only cause issues. There are many modern hose options that perform better and look nicer than the old school stainless steel stuff. The breather can under the hood is falling off and the general condition of under hood parts needs to be addressed. Some electrical and fluid plumbing is very poorly done and will cause issues in the future. The chassis has no upgrades at all. When the car was built? this was not addressed. There are a number of things that should be done. The front frame body mount rubber is completely worn out and should be replaced with modern urethane mounts. The front suspension should be replaced with modern suspension that has corrected geometry. New A-arms, spindles, shocks & springs. New sway bar as well. New steering gear, the rods, idler arm, cross link etc. The steering box appears to be in good condition. I would replace the power steering hoses with modern aftermarket lines. The rear suspension is completely stock, it needs to be updated as well. I would replace the leaf springs with a modern 4 link and coil over shocks and sway bar. This set up corrects the geometry and provides a better quality ride and control. The brakes are old technology as well. They should be upgraded to take advantage of the 17 inch wheels already on the car. I recommend installing 6 piston Wilwood front calipers and 4 piston rear calipers along with vented rotors. The master cylinder would be changed to match the caliper upgrade. This brake system also incorporates an E brake that would be connected to the original pedal in the car. The wiring in the under hood area appears to have been added to as needed. This has some dangerous aspects. With modern parts like

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTY THE MANUFACTURER OR THE ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVERY FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY OR DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.		By signing below, you acknowledge that you were notified of and authorized the dealership to perform the service/repairs itemized in this invoice and that you received is being returned to you in exchange for your payment of the amount due.	
DATE		CUSTOMER SIGNATURE	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE		THIS AMOUNT	
UNLESS OTHERWISE INDICATED.		SALES TAX	
ALL PARTS ARE NEW		LESS INSURANCE	
TOTAL CHARGES		TOTAL CHARGES	
MISC. CHARGES		SUBLET AMOUNT	
GAS, OIL, LUBE		PARTS AMOUNT	
LABOR AMOUNT		LABOR AMOUNT	
DESCRIPTION		TOTALS	

CUSTOMER COPY

DealerCap 2014 COM GROUP LLC (3117) SERVICE INVOICE TYPE 2 - 2012 - 75107 - GENIUS - 050019

MERTLIN AUTO GROUP

2882 ANWILER RD
ATLANTA, GA 30360
(770) 457-2698
www.merlinauto.org

INVOICE

11271

CUSTOMER #: 10485

PAGE 3

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T271
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN69 DD			18:00 09FEB22			CASH
						27APR22
R.O. OPENED			READY	OPTIONS:		
14:58 09FEB22			14:15 27APR22			
LIST						
NET			TOTAL			

electric fuel injection and fuel pump, multiply cooling fans, a hotter ignition system, the original dash and car wiring is just up to the task. Plus the wiring is over fifty years old. I recommend a modern wiring harness with a new fuse box capable of handling the extras on this car. There are companies that pre-make complete car harness that are direct fit to the original dash, lights, & switches, and has added circuits for upgraded equipment to be properly run. Much safer and will be properly routed to look right and avoid issues. I also found the dash has AC but there is no compressor or condenser in the engine compartment. this car be added as well and the car can have working AC. Having listed all of the issues above, there are definitely issues that must be addressed and some that just make it a better car. We can discuss the clients desires for the car and determine the best way to proceed. Once we have a better idea of what the client has in mind, we can put together a price estimate. Even with completing everything listed, there are many options.

D** PULL MOTOR TO ADDRESS OIL AND COOLANT LEAKS

CAUSE: Gaskets leaks

MISC MOTOR HAS BEEN PULLED AND BROKEN DOWN, SEE

TECH NOTES

101 C

1 E9300 EDELBRÖCK 9300 GASGACINCH GASKET

SEALER

3866 Gaskets leaks pulled the engine and dismantled to access the old & coolant leaks. While apart it was found to have cylinder wear that is part of the poor running of the fuel injection washing the cylinders. The engine has a lot of frictional drag. The camshaft, lifters, & valve springs will be updated. I recommend updating the piston ring package to a more modern design. I recommend a complete disassembly and evaluation.

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	THIS AMOUNT
WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealer to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.			PLEASE PAY
		UNLESS OTHERWISE INDICATED.	SALES TAX
		ALL PARTS ARE NEW	LESS INSURANCE
			TOTAL CHARGES
			MISC. CHARGES*
			SUBLET AMOUNT
			GAS, OIL, LUBE
			PARTS AMOUNT
			LABOR AMOUNT
			TOTALS

CUSTOMER COPY

MerlinAuto.org 2014 CCM Group LLC (617) 777-2698 SERVICE INVOICE TYPE 2 - 29100 - 745-55 - GENERIC - 000010

*** REPLACE REAR SUSPENSION, ADD 4 LINK

101 C
MISC REMOVED ALL OLD PARTS AND FRAME
CAUSE: Old worn original parts
** REPLACE FRONT SUSPENSION

1** INSTALL NEW URETHANE BODY MOUNTS
CAUSE: Worn original parts
MISC REMOVED OLD BUSHING AND ASSESSED
101 C

*** REPLACE POWER STEERING PUMP
CAUSE: Leaking power steering
MISC REMOVED OLD PUMP AND HOSES
101 C

SERVICE ADVISOR: 111 DANIEL JOFFE

PAGE 4

INVOICE

CUSTOMER #: 10485

CUSTOMER #: 10485

MERTLIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertlinautogroup.com

INVOICE

11271

PAGE 6

SERVICE ADVISOR: 111 DANIEL JOFFE

HOME:	CONT:	CELL:	BUS:			
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
69	CHEVROLET Camaro	124379N631049			3866 / 3866	T271
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN69 DD		18:00 09FEB22				
R.O. OPENED		READY	OPTIONS:			
14:58 09FEB22	14:15 27APR22				CASH	27APR22
LINE OP CODE TECH TYPE HOURS						
LIST						
NET						
TOTAL						

modern electronic controlled unit.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTY ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY INCIDENTAL DAMAGES.		BY signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.	
DATE		CUSTOMER SIGNATURE	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE		THIS AMOUNT	
UNLESS OTHERWISE INDICATED.		SALES TAX	
ALL PARTS ARE NEW		TOTAL CHARGES	
MISC. CHARGES *		SUBLET AMOUNT	
GAS, OIL, LUBE		PARTS AMOUNT	
LABOR AMOUNT		TOTALS	
DESCRIPTION		TOTALS	

CUSTOMER COPY

DealerCAR 2014 CCK 959L LLC (0173) SERVICE INVOICE TYPE 2 - 2520 - *MSRP* - *GROSS* - *0800010

MERTLIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertlinautogroup.com

PAGE 1

INVOICE

11453

CUSTOMER #: 10485

BUS:		CONT.		CELL.		SERVICE ADVISOR: 111 DANIEL JOFFE	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	CHG
01JAN69 DD	69	CHEVROLET Camaro	124379N631049			3866/3866	31JAN23
COLOR		YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
R.O. OPENED		READY		OPTIONS:			
01JAN69 DD				18:00 02MAY22			
09:28 02MAY22		17:11 31JAN23					
LINE OP CODE TECH TYPE HOURS							
A RUST REPAIR TO BODY							
CAUSE: Body rust issues							
BODY PREPARE FOR TRANSPORT TO BODY SHOP							
101 C							
RAIL							
1 FRO169L CHEVROLET CAMARO LEFT REAR FRAME							
RAIL							
1 FRO169R CHEVROLET CAMARO RIGHT REAR FRAME							
1 4003567 CHEVROLET CAMARO FLOOR PAN 67-69							
1 402035069L CHEVROLET CAMARO LEFT INNER FENDER							
1 4123569L CHEVROLET LEFT SEAT PLATFORM							
1 4123569R CHEVROLET RIGHT SEAT PLATFORM							
1 3892752 CHEVROLET 67-69 LEAF SPRING MOUNT							
1 3892751 CHEVROLET 67-69 LEAF SPRING MOUNT							
1 CSF69 CHEVROLET CAMARO SUB FRAME							
1 402035069R CHEVROLET CAMARO RIGHT INNER FENDER							
SUBT. SANDBLAST AND POWDER COAT SUBFRAME, SPINDLES, AND OTHER PART							

3866 Body rust issues After finding body and chassis rust, the body was installed on the rotator to start the rust repair. Sort and prepare body for transport. 10/13/22, engine sorting.

B REAR SUSPENSION INSTALLATION

CAUSE: Prepare Rear Suspension

BODY PREP REAR END FOR NEW SUSPENSION AND BRAKES

101 C

1 11160201 RIDETECH HQ COILOVER SYSTEM FOR

67-69 GM

1 11169102 RIDETECH MUSCLEBAR SWAY BAR KIT

1 8510200 CHEVROLET 12 BOLT REAR DIFF COVER

1 MG13101210 DIFFERENTIAL YOKE

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIM ALL WARRANTIES, INCLUDING ANY IMPLIED WARRANTIES OR MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVERY FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY INCURRED FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.		DATE		CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE		THIS AMOUNT	
By signing below, you acknowledge that you were notified of and authorized the Dealer to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.									
LABOR AMOUNT		PARTS AMOUNT		GAS, OIL, LUBE		SUBLET AMOUNT		MISC. CHARGES	
TOTAL CHARGES		TOTAL CHARGES		SALES TAX		TOTAL CHARGES		TOTAL CHARGES	
UNLESS OTHERWISE INDICATED.		ALL PARTS ARE NEW		UNLESS OTHERWISE INDICATED.		UNLESS OTHERWISE INDICATED.		UNLESS OTHERWISE INDICATED.	
DESCRIPTION		TOTALS		TOTALS		TOTALS		TOTALS	

CUSTOMER COPY

DealerCAE 2014 GM GENI LLC (01/17) SERVICE INVOICE TYPE 2 - 25100 - 750507 - GENI010 - 959010

CUSTOMER # : 10485		11453		INVOICE		MERTLIN AUTO GROUP	
HOME:		CONT.		PAGE 2		2882 AMWILER RD ATLANTA, GA 30360 (770) 457-2699 www.mertlinautogroup.com	
BUS:		CELL:		SERVICE ADVISOR: 111 DANIEL JOFFE			
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT		
69	CHEVROLET Camaro	124379N631049			3866/3866		
DEL DATE	PROD DATE	WARR EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. D.
R.O. OPENED		READY		OPTIONS:			
01JAN69 DD		17:11 31JAN23		18:00 02MAY22		31JAN2	
09:28 02MAY22		17:11 31JAN23		LINE OP CODE TECH TYPE HOURS		LIST NET	
1 8310191 RICHMAN 12 BOLT CHEVROLET RESEAL KIT		WITH BEARINGS		1 3914813 CHEVROLET 68-69 INTERM PARK BRAKE		CABLE	
1 9793660 CHEVROLET 67-69 F-BODY FRONT PARK		BRAKE CABLE					
3866 Prepare Rear Suspension Disassembled the rear end. I found a lot of rust on the ends of the housing. This is where the new brakes bolt on. I had to file off a lot of old rusted metal from the original brakes backing plate. This housing was simply painted over and a proper restoration was never performed. After removing the ring and pinion I found debris from a previous issue. The debris was left behind and can get into the current set up and damage the bearings & gears. This was thoroughly cleaned. The housing will be sand blasted and the new suspension parts welded on. It will then be powder coated to preserve the work long term.							
C** SUBLET TO BODY SHOP FOR REPAIRS TO FLOOR, BODY MOUNTS, INSTALL CROSSMEMBER, INSTALL SEAT MOUNT BRACE BODY SUBLET TO BODY SHOP 101 ISP SUBT BROWN AND BROWN							
3866 Rearrange shop to prepare for the body to return. ***** D** SUBLET SEND MOTOR TO MACHINE SHOP ENGINE SUBLET 101 C SUBT SUBLET TO MACHINE SHOP FOR REPAIR							

CUSTOMER #: 10485

11453

INVOICE

PAGE 3

MERLIN
AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.merillnautogroup.com

SERVICE ADVISOR: 111 DANIEL JOFFE	LICENSE	NO.

BUS:

CONT: 1
CELL: 1

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T453
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN69 DD			18:00 02MAY22		CHG	31JAN23
R.O. OPENED		READY		OPTIONS:		
09:28 02MAY22		17:11 31JAN23		TOTAL NET LIST TOTAL		

*** PREPARE FRONT FRAME TO INCLUDE FRONT SUSPENSION, BOTH AXLES AND BRAKES

SUSPENSION PREPARATION

101

1 W992 CHEVROLET ENGINE MOUNT FRAME SIDE

1 CH25634 GM FRONT UPPER CONTROL ARM BOLT SET

1 K6582 CHEVROLET PITMAN ARM

1 DA1603 BLACK SEMI GLOSS PAINT

1 11009565 BORGESON 12.7:1 STEERING BOX

1 11169525 RIDE TECH TRU TURN SYSTEM WITHOUT

SPLIT IN DLE

1 11009766 WILWOOD COMPLETE SUPERLITE BRAKE

SYSTEM

1 11609705 WILWOOD 261-13269 BK ALUMINUM

MASTER CYLINDER
1-BPB0131-BPABE

1 KPB8131 BRAKE POWER BOOSTER
3 HARDWARE HARDWARE

2. HARDWARE HARDWARE

2 10004 AXLE BEARING AND SEAL KIT

3866 Restoration Work Prepare the new front frame for installation. Checking seams and welds. Finishing welds to a better level. Modifying front cross member for the extended oil pan clearance. Mounting suspension as a mock up. Modified spring pocket for coil over clearance. Disassembled the front frame and sent off to powder coat. Will perform final assembly when it returns.

F** ENGINE ASSEMBLY AFTER MACHINE SHOP

CAUSE: Engine Rebuild

ENGINE ASSEMBLY

101 C

1 82180 PERMALEX ULTRA BLACK SILICONE GASKET

MAKER

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESSED AND IMPLIED. WORKMANSHIP AND MATERIALS ARE NOT GUARANTEED FOR ANY PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS REPAIRER AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE. SUCH WARRANTIES, CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP UNDER ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.		DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT
*SHOP SUPPLY COSTS: A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for GAS, OIL, LUBE		ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	INCIDENTAL DAMAGES: DAMAGE FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER DAMAGE FOR PERFORMANCE UNDER SUCH WARRANTIES, CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP UNDER ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY	INCIDENTAL DAMAGES: DAMAGE FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER DAMAGE FOR PERFORMANCE UNDER SUCH WARRANTIES, CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP UNDER ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY	SALES TAX
LABOR AMOUNT					TOTAL CHARGES
DESCRIPTION		SUBJECT AMOUNT		MISC. CHARGES *	
TOTALS					

3000 engine rebuild inspection found the engine had a number of issues. The proper parts were acquired and fit to the block. The block was prepared and engine assembled. The heads were changed to allow for a more street able arrangement, a roller cam was added.

G** ELECTRONICS/INSTALL NEW DASH, INSTALL NEW GAUGES, INSTALL STEERING COLUMN, MASTER CYLINDER, BRAKE BOOSTER

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD "AS IS" WITHOUT ANY WARRANTY.

1/4"-28 X 1-1/4"
1 4008330 ARP 12PT STAINLESS STEEL NUT
1 70060 TAYLOR SPARK PLUG WIRE SET
1 72143 MOROSO CENTER BOLT WIRE LOOM KIT
1 FBW2821 BLUK HEAD 1/8 FEMALE PIPE
1 401174967S FUEL TANK STRAP HARD WARE KIT
1 MPC214A FREEZE PLUG
2 51069 CHEVROLET MIX OIL FILTER
1 940006ERT ALUMINUM ADAPTERS
1 6120560 ARP 12PT STAINLESS STEEL BOLT KIT
3 6731003 ARP 12PT BLACK OXIDE BOLT KIT
1 PP2467 NUT AND BOLT GAUGE
2 FBL1524 SOCKELESS FITTING BLACK
4 FBL1532 SOCKELESS FITTING BLACK
4 FBL1534 SOCKET FITTING BLACK
4 FBL1522 SOCKELESS FITTING BLACK
1 85459 BREATHER TANK
1 FCN RACING HOSE
2 6131000 ARP SS 12PT BOLT KIT
2 FBM2111 FUEL PUMP ADAPTER FITTING
1 CU70009 PERFORMANCE FIT RADIATOR ASSEMBLEY
1 FCV1003 AOP SOCKELESS HOSE
1 FCN0610 RACING HOSE
1 FBM1121 #4 90. ELBOW BOW FITTING
SUBJ ALTERNATOR REBUILD

01JAN69 DD	R.O. OPENED	READY	OPTIONS:	18:00 02MAY22	CHG	31JAN23
09:28 02MAY22	17:11 31JAN23					
LINE OP CODE TECH TYPE HOURS						
LIST						
NET						
TOTAL						

SERVICE ADVISOR: 111 DANIEL JOFFE

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.merlinalgroup.com

PAGE 6

INVOICE

11453

CUSTOMER #: 10485

MERTIN
AUTO GROUP

CUSTOMER #: 10485

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.merlinautogroup.com

SERVICE ADVISOR: 111 DANIEL JOFFE	LICENSE	MILEAGE
-----------------------------------	---------	---------

HOME:	BUS:	CELL:	CONT:
-------	------	-------	-------

[illegible]

FOR FEB 2023

1 14929 CHEVROLET STEERING COLUMN TO FLOOR
COVER
1 3939653 CHEVROLET BLACK DASH PAD FOR CAMARO
WITH A/C
1 R256A CHEVROLET CAMARO DOME LIGHT KIT
1 HC293 CHEVROLET CENTER DASH CLIPS
1 C69200 CHEVROLET CAMARO DASH CARRIER CLIP
KIT

1 SW101 1 TERM DOOR JAMB SWITCH
1 SW90 2 TERM DOOR JAMB SWITCH
1 K814 CHEVROLET F BODY DASH PAD MTG HARDWARE
1 101690221 CHEVROLET 1969 BLACK DASH PANEL
WITH AUTOMETER GAUGES
CLASSIC UPDATE

1 500686 CHEVROLET CAMARO CLASSIC UPDATE
WIRING HARNESS
1 69248 UNIVERSAL GPS SPEEDOMETER MODULE
1 1520790051 CHEVROLET IDIDIT REPLACEMENT
STERRING COLUMN TILT WITH FLOOR SHIFT
1 964191 CHEVROLET VINIAGE AIR REPLACEMENT
KIT69 CAMARO
1 473046 CHEVORLET A/C CONTROL PANEL KIT 69
CAMARO
CHEVROLET TRINITY SWITCH UPGRADE

KIT69 CAMARO
 1 473046 CHEVORLET A/C CONTROL PANEL KIT 69
 1 246780 CHEVORLET TRINARY SWITCH UPGRADE
 1 80690 B AND M MEGA SHIFTER
 1 14744 CHEVORLET STEERING COLUMN BRACKET
 100 922949A265 STAINLESS STEEL BUTTON HEAD
 10X32X1/2"
 5 94238A115 STAINLESS STEEL LOCKNUT 10X24
 25 95105A135 HEAVY DUTY RIVET NUT OPEN END
 10-32
 25 94238A103 18-8 STAINLESS STEEL LOCK NUT
 *REPAIRS ARE SOLD AND ALL REPAIRS ARE *SHOP SUPPLY

*SHOP SUPPLY COSTS: A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE MADE BY THE DEALERSHIP. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES OR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTY ON PARTS AND ACCESSORIES REPAIRS THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES. DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.
is being returned to you in exchange for your payment of the Amount Due.	By signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received the opportunity to inspect (or had the opportunity to inspect) any disposed parts as requested by you. The vehicle	is being returned to you in exchange for your payment of the Amount Due.
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	INDICATED.	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

11453

INVOICE

PAGE 8

HOME:	CONT
BUS:	CELL

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T453
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
						INV. DATE
01JAN69 DD			18:00 02MAY22		CHG	31JAN23
R.O. OPENED		READY		OPTIONS:		
		17:11 31JAN23				
09:28 02MAY22						
LINE OP CODE TECH TYPE HOURS						
LIST NET TOTAL						

3/8"-16
1 89845K77 6061 ALUMINUM HEX BAR 9/16"X1
25 90715A145 316 STAINLESS STEEL LOCK NUT
3/8"-16
50 91950A031 316 STAINLESS STEEL WASHER .406"
ID .812" OD
1 6544K17 LOW CARBON STEEL SHEET 24"X36"
25 HARDWARE HARDWARE1
2 5080 BREAK THRU PLUG 1"
1 5180N12 SLIP RESISTANT EXPANDABLE SLEEVING
1/4"
1 5180N16 SLIP RESISTANT EXPANDABLE SLEEVING
1/2"
1 5180N21 SLIP RESISTANT EXPANDABLE SLEEVING
3/4"
1 9307K57 RUBBER GROMMET 1 5/8" HOLE DIAMETER
1/16" THICK 3/4" ID
1 510458 TERMINAL RING
1 20301 SPEEDOMETER PORT PLUG
1 925128 GM POWER STEERING HOSE ADAPTER
1 MTZ-34R INTERSTATE BATTERY MTZ34R
50 92196A542 1/4-20 SS SOCKET HEAD SCREW
25 3225T25 5/8 DAMPING LOOP CLAMP
5 906605 5/16" COPPER TUG 6GA
25 5612201 RED ZGA BATTERY CABLE COIL
10 900975 NSBA CL-6 GGA BATTERY TERMINAL
SOLDER SLUG
5 906505 1/4" COPPER TUG 6GA
5 906625 5/16" COPPER TUG ZGA
1 91940121 POSITIVE QUICK CABLE BATTERY
TERMINAL ZGA-1GA
1 91940221 NEGATIVE QUICK CABLE BATTERY
TERMINAL ZGA-1GA

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES OR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES/REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERSONS USING SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY OR DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the service/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.		DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT
*SHOP SUPPLY COSTS: A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for PARTS AMOUNT LABOR AMOUNT SUBLET AMOUNT MISC. CHARGES * TOTAL CHARGES LESS INSURANCE SALES TAX TOTALS	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	is being returned to you in exchange for your payment of the Amount Due.			
	connection with the shop supplies used in the GA, OIL, LUBE	REPAIR.			
		DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.			
		ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERSONS USING SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY			
		ACCESSORIES/REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERSONS USING SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY			
		SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES/REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERSONS USING SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY			

11453

INVOICE

PAGE 9

SERVICE ADVISOR: 111 DANIEL JOFFE

H** HANG/FIT REAR SUSPENSION
CAUSE: New 4 Link Install

101
C
1 610259 WHEEL STUD

3866 New 4 Link Install A new four link rear suspension is being installed. I mounted the brackets after modifying them to fit. I then put the rear end in place and centered it. I set it at the proper height and tack welded the brackets to the rear end housing. I then removed the rear end and fully welded the new brackets on. It is ready for powder coat. There is a sample part and a note about what color and what needs to be coated and what doesn't need to be coated. *****

BODY SUBFRAME, IN PROGRESS, TO BE COMPLETED ON NEW REPAIR ORDER

1 40106 BATTERY TERMINAL KIT
1 C52Z16763S CHEVROLET HOOD BUMPERS

J** MOUNT TIRES/WHEELS

CAUSE: MOUNT AND BALANCE 4 NEW TIRES

TIRE 4 MOUNT AND BALANCE 4 NEW TIRES

3 64000 LUG NUT 1/2 CHROME ACORN
3 64001 LUG NUT 7/16 CHROME ACORN

[illegible]

CUSTOMER #: 10485

11453

MERTLIN
AUTO GROUP

INVOICE

PAGE 10

 2882 AMWILER RD
 ATLANTA, GA 30360
 (770) 457-2699
 www.mertlinautogroup.com

 BUS: _____
 HOME: _____
 CONT: _____
 CELL: _____

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T453
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN69 DD			18:00 02MAY22		CHG	31JAN23
R.O. OPENED		READY		OPTIONS:		
09:28 02MAY22		17:11 31JAN23				
LINE OP CODE TECH TYPE HOURS						
1ST						
NET						
TOTAL						

3866 NOT COMPLETED YET, OPENING LINE ON NEW REPAIR ORDER

 *** INSTALL DYNAMAT/SOUND DEADENING MATERIAL
 INTERIOR DETAIL DEPARTMENT

 101 C
 2 DYNAMAT DYNAMAT 18"X32"X.067 THICK

1 DYCXMGT1 DYNAMAT FLOOR KIT 69 CAMARO

1 DYCXMGT1 DYNAMAT CC TRUNK FLOOR KIT

1 DYCXMGT1 DYNAMAT CC DOOR KIT

1 DYCXMGT1 DYNAMAT TRUNK LID KIT

1 DYCXMGT1 DYNAMAT UNDER SEAT KIT

1 DYCXMGT1 DYNAMAT CC TRAY KIT

1 DYCXMGT1 DYNAMAT CC ROOF KIT

3866 INSTALLED DYNAMAT/SOUND DEADENING MATERIAL

 L** SUBLET FOR HEADLINER AND CARPETING
 UPHOLSTERY TO BE COMPLETED ON NEW REPAIR ORDER

99 C

 M** FINAL ASSEMBLY
 CAUSE: Restoration

BODY ASSEMBLY IN PROGRESS, TO BE COMPLETED ON NEW

REPAIR ORDER

101 C

1 3503569 CHEVROLET RADIATOR SUPPORT CAMARO 69

2 622116 EXHAUST BEND 2.5 45 DEGREE BEND PIPE

1 8814 ALUMINUM WELD IN BUNG

1 70975 RADIATOR HOSE

1 95105A135 HEAVY DUTY RIVET NOT OPEN END

10-32

1 14597819 WRAP AROUND SLEEVING, BRAIDED 3/4"

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY OR TO REPAIR. DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.	
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	
CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE
DATE	PLEASE PAY THIS AMOUNT
	SALES TAX
	LESS INSURANCE
	TOTAL CHARGES
	MISC. CHARGES *
	SUBLET AMOUNT
	GAS, OIL, LUBE
	PARTS AMOUNT
	LABOR AMOUNT
	TOTALS

CUSTOMER COPY

DealerCAP 2015 CDR Group, LLC (01/17) SERVICE INVOICE TYPE 2 - 2292C - "AS-IS" - GENERIC - 8/8/2010

MERTIN

2882 AMWILLER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertinautogroup.com

INVOICE

11453

PAGE 11

CUSTOMER #: 10485

HOME:		BUS:		CONT:		CELL:		SERVICE ADVISOR: 111 DANIEL JOFFE	
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG			
69	CHVROLET Camaro	124379N631049	3866/3866	T453					
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	CHG	31JAN23	
R.O. OPENED		READY		OPTIONS:					
09:28 02MAY22		17:11 31JAN23		18:00 02MAY22					
LINE OPCODE TECH TYPE HOURS									

1 1459T817 WRAP AROUND SLEEVING BRAIDED 1/2"
1 1459T813 WRAP AROUND SLEEVING BRAIDED 1/4"
1 95105A143 1/4"-20 THREAD ZINC PLATED STEEL
RIVET NUT OPEN END
1 G1487B ALUMINUM PLUG KIT 3/8"
1 G1488B ALUMINUM PLUG KIT 1/2"
2 1194A BUNG 02 SS 18MM X 1.5
1 FBM5282 ADAPTOR BLACK
1 FB1532 SOCKETLESS FITTING BLACK
4 FB1512 SOCKETLESS FITTING BLACK
1 AT581806ERL 6AN TUBE VENT
1 AT581906ERL TUBE SLEEVE
20 FCN0620 BLACK HOSE NO SOCKET
2 FBM5005 -06AN ADAPTER BLACK
2 FBM5009 -10AN ADAPTER BLACK
1 FBM5072 BLACK ADAPTER
1 FBM5100 -6AN BLACK BULKHEAD NUT
1 AL136132 POWER STEERING TANK
2 FBM1389 #6 STEEL 90 ELBOW
1 AT984004ERL HOSE

OTHER: 0.00 TOTAL LINE M:
3866 Restoration fit, mount and install parts for the final
assemble the wiring harness. Mount and wire radiator and fans
with AC function and ECU activation.

N** DIAGNOSE RIGHT REAR WINDOW FUNCTION.

CAUSE: Bad rollers

BODY CHECK AND ADVISE

101 C

1 110020 CHEVROLET WINDOW NUT TL

6 7648823 CHEVROLET 67-72 QTR GLAS ROLLER ASSY

OTHER: 0.00 TOTAL LINE N:

3866 Bad Rollers Inspection found the window rollers are old and
one has broken. I recommend replacing all of the rollers.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE

PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS

WARRANTY, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS

FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR

LABOR AND/OR MATERIALS WILL BE ADDED TO THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

THE REPAIR ORDER FOR THE REPAIR ORDER FOR THE REPAIR ORDER FOR

CUSTOMER #: 10485

11453

MERTIN
AUTO GROUP

INVOICE

2882 AMWILER RD
 ATLANTA, GA 30360
 (770) 457-2699
 www.mertinautogroup.com

PAGE 12

HOME: 7
 CONT: 1
 CELL: 2

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T453
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
						INV. DATE
01JAN69 DD			18:00 02MAY22		CHG	31JAN23
R.O. OPENED		READY		OPTIONS:		
09:28 02MAY22		17:11 31JAN23				
LINE OPCODE TECH TYPE HOURS						
CLOSING THIS REPAIR ORDER,						
OPENING REPAIR ORDER WITH ANY						
LINES STILL IN PROGRESS, ML						
1/31/23						
TOTAL						

LIST NET TOTAL

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, REPAIR, LOSS OF TIME, LOSS OF USE, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.	
DATE	CUSTOMER SIGNATURE
By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	
PLEASE PAY THIS AMOUNT	ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.
SALES TAX	
LESS INSURANCE	
TOTAL CHARGES	
MISC. CHARGES *	
SUBLET AMOUNT	
GAS, OIL, LUBE	
PARTS AMOUNT	
LABOR AMOUNT	
DESCRIPTION	

CUSTOMER COPY

DATE/CAP 2014 CMX Global, LLC (217) SERVICE INVOICE TYPE 2 - 25/20 - V48.18 - GENERIC - 05/03/10

MERTIN AUTO GROUP

2882 AMWILLER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertinautogroup.com

INVOICE

PAGE 3

12002

CUSTOMER #: 10485

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN69 PD			18:00 31JAN23				29FEB24
YEAR	COLOR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
69	CHEVROLET Camaro	124379N631049			3866/3866	T112002	

SERVICE ADVISOR: 107 MEAGAN ASHLEY LEWELLY

CELL:

CONT:

HOME:

BUS:

E** INSTALL BUMPER AND TRIM.

BODY BUMPER AND TRIM

2 14418924 FERRARI/MASERATI INTERIOR SCREW

MAX7MM 360/430/458 90128A211

1 SFT-31151 LIC PLATE BPR

3866 Blasted the bumper mounts, installed the bumper and aligned.

F** DETERMINE EXHAUST DESIGN AND NEEDS.

EXHAUST INSTALL NEW EXHAUST COMPONENTS

101 C

14 SUM-692125 CLAMP BAND

1 PYE-SGF60T EXHAUST SYSTEM

1 6053 KRYLON SEMI-FLAT BLACK

1 WIN0109 WINZER BRAKE PARTS CLEANER -

ORIGINAL FORMULA 8914520

G** MOUNT AND BALANCE 4 NEW TIRES

CAUSE: Old Tires

TIRE4 MOUNT AND BALANCE 4 NEW TIRES

101 C

2 20896 215/45R17 MICHELIN PS 4S

2 TD TIRE DISPOSAL

2 MM WHEEL WEIGHTS

2 08090 245/45R17 MICHELIN PS4S

2 TD TIRE DISPOSAL

2 MM WHEEL WEIGHTS

3866 Old Tires Mount and balance four new Michelin tires.

H** NO START, CHECK AND ADVISE

CAUSE: Starter / Cable

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	THIS AMOUNT
			SALES TAX
			LESS INSURANCE
			TOTAL CHARGES
			MISC. CHARGES *
			SUBLET AMOUNT
			GAS, OIL, LUBE
			PARTS AMOUNT
			LABOR AMOUNT
			TOTALS

CUSTOMER COPY

DealerCAR 2014 CDK GROUP, LLC (01/17) SERVICE INVOICE TYPE 2, 20120 - V51.07 - GENIUS - 0609010

MERTIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.merlinauto.com

INVOICE

12002

CUSTOMER #: 10485

PAGE 5

SERVICE ADVISOR: 107 MEAGAN ASHLEY LEWELLY

DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN69 DP	18:00 31JAN23					CHG	29FEB24
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
69	CHEVROLET Camaro	124379N631049				3866/3866	112002
COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	

BUS: CONT: HOME:

after install found no issues.

J** CHECK ALTERNATOR

CAUSE: Bad Alternator

ALL REPLACE ALTERNATOR

1 PWM-47293 ALTERNATOR

OTHER: 0.00 TOTAL LINE

3866 Bad Alternator Replaced the faulty alternator.

K** DIRECTIONAL INDICATOR ON DASH INOP, CHECK AND ADVISE

CAUSE: Wire Connection

LIGHTS CHECK AND ADVISE

101 C

OTHER: 0.00 TOTAL LINE K:

3866 Wire Connection Wire connection had come loose. Attached the

connector. Full function has been restored.

L** RADIO MUST BE MANUALLY TURNED OFF, PLEASE CHECK AND ADVISE

CAUSE: Bad Relays

RADIO RADIO IS INOP, PLEASE CHECK AND ADVISE

101 C

OTHER: 0.00 TOTAL LINE L:

3866 Bad Relays

Inspection found the radio was staying on after the key was off.

Further checking found the complete accessory circuit in the fuse box

the fan circuit fuse being pulled would turn off the radio. After

checking wires and connections I found the fan relays were bleeding

battery power internally and back feeding the accessory circuit. I

changed both relays and full function returned.

New DS door sill plate installed.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE

PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL

WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF

MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR

AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE

SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTY ON PARTS AND

ACCESSORIES REPAIRABLES THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE

ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE

LIABLE FOR PERFORMANCE OF SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO

RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY

DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER

INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the

dealership to perform the services/repairs itemized in this invoice and that you received

is being returned to you in exchange for your payment of the amount due.

CUSTOMER SIGNATURE

DATE

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

PLEASE PAY THIS AMOUNT

SALES TAX

LESS INSURANCE

TOTAL CHARGES

MISC. CHARGES

SUBLET AMOUNT

GAS, OIL, LUBE

PARTS AMOUNT

LABOR AMOUNT

DESCRIPTION

TOTALS

CUSTOMER COPY

DEALCAR 2014 GM GMAL, LLC (31417) SERVICE INVOICE TYPE 2 - 2520 - *MSR* - GEMIC - 965810

MERTLIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2698
www.merlinauto.com

INVOICE

PAGE 6

12002

CUSTOMER #: 10485

HOME:

CELL:

SERVICE ADVISOR: 107 MEGAN ASHLEY LEWELLY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3866/3866	T12002
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN69 DD			18:00 31JAN23		CHG	29FEB24
R.O. OPENED		READY		OPTIONS:		
17:19 31JAN23		12:33 29FEB24				
LINE OPCODE TECH TYPE HOURS						
LIST			NET		TOTAL	

RADIO RADIO IS INOP, PLEASE CHECK AND ADVISE

99

SUBL INSTALL BLUETOOTH COMPATIBLE RADIO, SPEAKERS, CUSTOM PANELS.

C

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL IMPLIED WARRANTIES, MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR OR SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY OR DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.		By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received is being returned to you in exchange for your payment of the amount due.	
DATE		CUSTOMER SIGNATURE	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE		ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.	
PLEASE PAY THIS AMOUNT		SALES TAX	
TOTAL CHARGES		LESS INSURANCE	
MISC. CHARGES*		TOTAL CHARGES	
SUBLET AMOUNT		GAS, OIL, LUBE	
PARTS AMOUNT		LABOR AMOUNT	
DESCRIPTION		TOTALS	

CUSTOMER COPY

DealerCAR 2014 CCK 0944L LLC (01/17) SERVICE INVOICE TYPE 2 - 2520 - *MS-15* - GENERIC - 0089010

MERTLIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertlinautogroup.com

INVOICE

PAGE 1

12827

CUSTOMER #: 10485

HOME:

CONT: 770-457-2699
CELL: 770-457-2699

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3867/3867	T2827
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
						INV. DATE
01JAN69 DT			18:00 29FEB24			CHG
						12SEBP24
R.O. OPENED		READY		OPTIONS:		
12:43 29FEB24		15:46 12SEP24				

3867 Starter Shim I removed the starter and changed the shims in the nose. I also addressed the noise in the power steering and resolved that. I then went with the client on a test drive.

C** PERFORM CERAMIC COATING - FULL VEHICLE DETAIL, PAINT CORRECTION, GTECHNIO PLATINUM KIT TO PAINTED SURFACES/GLASS/PLASTICS/WHEELS/INTERIOR

CAUSE: PERFORM CERAMIC COATING - FULL VEHICLE DETAIL, PAINT CORRECTION, GTECHNIO PLATINUM KIT TO PAINTED SURFACES/GLASS/PLASTICS/WHEELS/INTERIOR

CERAMIC PERFORM CERAMIC COATING - FULL VEHICLE DETAIL, PAINT CORRECTION, GTECHNIO PLATINUM KIT TO PAINTED SURFACES/GLASS/PLASTICS/WHEELS/INTERIOR

101 CI
99 CI

1 GTECH CERAMIC COATING PLATINUM KIT

0.00 TOTAL LINE C:

D** PASSENGER WINDOW IS SQUEAK, CHECK AND ADVISE

GLASS R&R DOOR PANNEL AND INSPECT

101 CI

0.00 TOTAL LINE D:

3867 unknown pulled the door panel out don't find anything loose.

Will drive again and evaluate.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY OR INCIDENTAL DAMAGES. BY signing below, you acknowledge that you were notified of and authorized the dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE
CUSTOMER SIGNATURE
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

PLEASE PAY THIS AMOUNT

SALES TAX

LESS INSURANCE

TOTAL CHARGES

MISC. CHARGES

SUBLET AMOUNT

GAS, OIL, LUBE

PARTS AMOUNT

LABOR AMOUNT

TOTALS

CUSTOMER COPY

DealerCap 2014 CCM Group, LLC (31/17) SERVICE INVOICE TYPE 2 - 25/20 - "MS" - CUMMINS - 000010

CUSTOMER #: 10485

12827

MERTIN
AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertinautogroup.com

PAGE 2

INVOICE

HOME: 10485
BUS: 10485
CONT: 10485

SERVICE ADVISOR: 111 DANIEL JOFFE

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
69	CHEVROLET Camaro	124379N631049			3867/3867	T2827
DEL DATE	PROD DATE	WARR EXP	PROMISED	PO NO	RATE	PAYMENT
01JAN69 DJ			18:00 29FEB24			12SEP24
R.O. OPENED	READY	OPTIONS	CHG	CHG	CHG	CHG
12:43 29FEB24	15:46 12SEP24					
LINE OPCODE TECH TYPE HOURS						
E** A/C IS INOP, CHECK AND ADVISE						
CAUSE: Bad Ground						
A/C DIAGNOSE AND REPAIR GROUND FOR AC COMPRESSOR						
101 CI						
OTHER: 0.00 TOTAL LINE E:						
3867 Bad Ground Inspection found the ground for the compressor was						
not good due to the powder coated bracket. I added an additional ground						
strap and restored function.						
F** STEERING WHEEL IS OFF CENTER, CHECK AND ADVISE						
CAUSE: Needs Alignment						
STEER PERFORM ALIGNMENT.						
101 CI						
OTHER: 0.00 TOTAL LINE F:						
3867 Needs Alignment Performed alignment with custom specs for the						
Ride Tech suspension.						
G** MAIN BATTERY CABLE IS EXPOSED UNDER THE CAR, SECURE AND ADVISE						
CAUSE: Reroute Needed						
BATT REROUTE STARTER POWER CABLE						
101 CI						
1 4237N102 ROD END						
OTHER: 0.00 TOTAL LINE						
3867 Reroute Needed It was determined the routing of the starter						
power cable was not as we wanted. I removed the wire and rerouted it to						
a more pleasing position.						

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY OR INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealer to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

CUSTOMER SIGNATURE _____

AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE _____

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

MISC. CHARGES

TOTAL CHARGES

LESS INSURANCE

SALES TAX

PLEASE PAY THIS AMOUNT

CUSTOMER COPY

DealerCAR 2014 CDK Global LLC (01/17) SERVICE INVOICE TYPE 1, 25/20 - VASIS - GENERIC - 000010

MERTIN

AUTO GROUP

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertinautogroup.com

INVOICE
12939

PAGE 1

CUSTOMER #: 10485

HOME: BUS: CONT: CELL:

SERVICE ADVISOR: 108 ADAM GREG MERTIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3867/3867	T2939
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
						INV. DATE
01JAN69 DD			18:00 22APR24			25APR24
R.O. OPENED		READY		OPTIONS:		
07:57 22APR24		15:41 25APR24				
LINE OP CODE TECH TYPE HOURS						
A REPLACE 12V BATTERY						
CAUSE: REPLACE 12V BATTERY						
BATT REPLACE 12V BATTERY						
104ISERV						
1 MTZ-34R INTERSTATE BATTERY MTZ34R						
-1 MTZ-34R INTERSTATE BATTERY MTZ34R						
OTHER: 0.00 TOTAL LINE A:						
3867 WENT TO CUSTOMERS HOUSE AND CHECKED NO START ISSUE. FOUND THE						
BATTERY WAS DEAD REPLACED THE BATTERY AND INSTALLED A BATTERY TENDER.						
CHECKED CAR FOR A ELECTRICAL DRAW DID NOT FIND ONE. LABELED THE BATTERY						
CUT OFF SWITCH ON/OFF.						

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES TO PROPERTY OR REPAIRS FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.

DATE		CUSTOMER SIGNATURE		AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE		PLEASE PAY THIS AMOUNT	
ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.		SALES TAX		LESS INSURANCE		TOTAL CHARGES	
MISC. CHARGES *		SUBLET AMOUNT		GAS, OIL, LUBE		PARTS AMOUNT	
LABOR AMOUNT		DESCRIPTION		A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.			

CUSTOMER COPY

DealerCAP 2014 GM Global LLC 10/17/13 SERVICE INVOICE TYPE 2 - 2500 - VASIS - GENERAL - 0609010

CUSTOMER #: 10485

13013

MERTIN
AUTO GROUP

INVOICE

2882 AMWILER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertinauto.com

PAGE 1

HOME: CONT: BUS: CELL

SERVICE ADVISOR: 108 ADAM GREG MERTIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3869/3869	T3013
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
						INV. DATE
01JAN69 DI			18:00 15MAY24		CHG	12SEP24
R.O. OPENED		READY		OPTIONS:		
18:04 15MAY24		15:40 12SEP24				
A NO START, CHECK AND ADVISE						
CAUSE: NO START, CHECK AND ADVISE						
NOSTART NO START, CHECK AND ADVISE						
1 SNE-550-511-BAX SNIPER 2 KIT						
1 17025 OXYGEN SENSOR						
OTHER: 0.00 TOTAL LINE A:						
3869 FOUND SEVERAL GROUND WIRES NOT COMPLETELY CONNECTED. THE						
BATTERY SWITCH IS BAD THE STARTER NEEDS TO BE REPLACED IT DOES NOT WANT						
TO ENGAGE.						

C** R&R TRANSMISSION TO REPLACE BROKEN FLEX PLATE AND STARTER						
TRANS FLEX PLATE						
104 C1						
1 2441601 GM STARTER						
1 399273 GM SFI APPROVED FLEXPLATE						
0.00 TOTAL LINE C:						
3869 R&R TRANSMISSION TO REPLACE THE BROKEN FLEX PLATE AND STARTER.						
AFTER PUTTING THE CAR BACK TOGETHER CAR WOULD NOT START JUST TURN OVER.						

D** VEHICLE IS STILL NOT STARTING, CHECK AND ADVISE.						
CAUSE: Bad Fuel Injection Unit						
NOSTART NO START, CHECK AND ADVISE						

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE						
PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL						
WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF						
MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR						
SALE OF PARTS OR PRODUCTS OR THE REPAIR, THE ONLY WARRANTY ON PARTS AND						
ACCESSORIES OR REPAIRS WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE						
ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE						
LIABLE FOR PERFORMANCE OF SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO						
RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY						
DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER						
INCIDENTAL DAMAGES.						
By signing below, you acknowledge that you were notified of and authorized the						
dealership to perform the services/repairs itemized in this invoice and that you received						
(or had the opportunity to inspect) any replaced parts as requested by you. The vehicle						
is being returned to you in exchange for your payment of the amount due.						
DATE	CUSTOMER SIGNATURE					
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE						
PLEASE PAY THIS AMOUNT						
TOTALS	DESCRIPTION					
LABOR AMOUNT						
PARTS AMOUNT						
GAS, OIL, LUBE						
SUBLET AMOUNT						
MISC. CHARGES						
TOTAL CHARGES						
LESS INSURANCE						
SALES TAX						

CUSTOMER COPY

DealerCAR 2014 GM Camaro LTZ (01/17 SERVICE INVOICE) TYPE 2 - 2512C - VASIS - GENIUS - 999010

CUSTOMER #: 10485

13013

MERTLIN
AUTO GROUP

2882 AMWILLER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertlinautogroup.com

PAGE 2

NAME: BUS: CONT: CELL

SERVICE ADVISOR: 108 ADAM GREG MERTLIN

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
		69	CHEVROLET Camaro		124379N631049			3869/3869		T3013
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE		
01JAN69 DD				18:00 15MAY24			CHG	12SEP24		
R.O. OPENED		READY		OPTIONS:						
18:04 15MAY24		15:40 12SEP24								
LINE OP CODE TECH TYPE HOURS										
LIST										
NET										
TOTAL										

OTHER: 0.00 TOTAL LINE D:

3869 had fuel injection unit. Inspection found the voltage at the ignition was low. Will rewrite

turning over the engine. I have tested all of the wiring with no issues

found. I have tested the distributor and coil. I have tested the injection

unit is not firing the ignition system. I have an email into tech

support and will update when I hear back. Spoke with Holley, they agree

the injection system has an issue. It is not user serviceable and out

of warranty. They recommend upgrading. They do not offer a repair

service for the Sniper 1 system.

We ordered a Sniper 2 upgrade unit from Summit. The new Sniper 2

was installed and the car started right away. There were no longer

issues. It will need to be adjusted and tuned some to get the best

performance.

It was mentioned that the started needed to be shim adjusted.

Mertlin South had replaced the started and flex plate after there was a

gear failure. I engaged the gear to flex plate and checked the

clearance. It was excessive. I removed shims and it was still too much.

I removed all of the shims and it was too tight. I determined 1, 1/64

shim was correct. I spun the started to check the sound and found it

was moving a lot. Closer inspection found the started was not tightly

fastened to the aluminum adapter that bolts to the block. I removed the

starter and tightened the bolts. They were slightly loose but one had

stripped and would not tighten. I took the bolts out and the adapter

block is just poorly cast and finished. I machined the cast surfaces to

insure a good fit. I then machine the two threaded holes for Timesert

threaded inserts. Once repaired, the starter was installed and works

well again. The rear seat was put back in and the shifter assembled.

Wires were secured and grommet put in place. Tuning became an issue as

the car was driven. We ordered the computer interface cable and found

it was leaning itself quickly. I found with data log, the 02 was dead.

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	PLEASE PAY THIS AMOUNT
WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY INCURRED FROM LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealer to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the amount due.			UNLESS OTHERWISE INDICATED.
ALL PARTS ARE NEW			SALES TAX
LESS INSURANCE			TOTAL CHARGES
TOTAL CHARGES			MISC. CHARGES
SUBLET AMOUNT			GAS, OIL, LUBE
PARTS AMOUNT			LABOR AMOUNT
TOTALS			DESCRIPTION

CUSTOMER COPY

DealerCAP 2014 GM Corp. (Global, LLC) (GM) SERVICE INVOICE TYPE 2 - 2010 - VARI-1 - GENIUM - 909010

CUSTOMER #: 10485

13013

MERTLIN
AUTO GROUP

INVOICE

2882 AMWILLER RD
ATLANTA, GA 30360
(770) 457-2699
www.mertlinautogroup.com

PAGE 3

SERVICE ADVISOR: 108 ADAM GREG MERTLIN

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
	69	CHEVROLET Camaro	124379N631049		3869 / 3869	T3013
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
			18:00 15MAY24			12SEP24
R.O. OPENED		READY		OPTIONS:		
18:04 15MAY24		15:40 12SEP24				
LINE OP CODE TECH TYPE HOURS						
LIST NET TOTAL						

I replaced the 02 and was able to tune the car again. It is running well.

E** DIAGNOSE POSSIBLE NOISE FROM FLEX PLATE

CAUSE: Possible oil contamination

DIAG DIAGNOSE

101 C1

8 822347 VALVOLINE 20W50 VRI ENGINE OIL

1 WIX51069 OIL FILTER

OTHER: 0.00 TOTAL LINE E:

3869 Possible oil contamination found the oil smells heavily of gas. I drained the oil and it was very runny and black and smelled of oil. I removed the filter and cut it open but found nothing. I will change the oil and filter and reevaluate. After the oil change, the oil pressure was restored and very good. The ticking noise was found to be a loose plug wire and the tick was the arcing of the spark. Plug wire is secure and engine sounds great.

F** CHECK AC CONDENSATION DRAIN UNDERDASH.

CAUSE: Missing Hose

HVAC DRAIN HOSE

101 C1

1 H-156 1/2 INCH HEATER HOSE

OTHER: 0.00 TOTAL LINE F:

3869 Missing Hose The drain hose was not installed after carpet. I installed the drain hose.

G** CHECK AC DUCTING TO LEFT DRIVER'S VENT AND ADVISE.

CAUSE: Hose Disconnected

HVAC VENT HOSE

101 C1

3869 Hose Disconnected Stereo guys left the hose disconnected and tucked out of the way. It is connected and working.

WARRANTY DISCLAIMER: ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE. THE DEALERSHIP ASSUMES NO LIABILITY FOR ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH WARRANTIES SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES. DAMAGES TO PROPERTY, REPAIR, LOSS OF TIME, LOSS OF USE, LOSS OF PROFIT OR INCOME, OR ANY OTHER DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.	
DATE	CUSTOMER SIGNATURE
By signing below you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.	
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	
PLEASE PAY THIS AMOUNT	UNLESS OTHERWISE INDICATED.
SALES TAX	ALL PARTS ARE NEW
LESS INSURANCE	
TOTAL CHARGES	
MSC. CHARGES	
SUBLET AMOUNT	
GAS, OIL, LUBE	
PARTS AMOUNT	
LABOR AMOUNT	
DESCRIPTION	

CUSTOMER COPY

DealerCAP 2014 COK BOOK, LLC (P) 1717 SERVICE INVOICE TYPE 2 - 2520 - 14515 - GENIUM - 003010