

CUSTOMER #: 10918

12445

INVOICE

PAGE 1

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

SERVICE ADVISOR: 117 PARK MONTELEONE										
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939				8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE	
01JUL89	01JUL89	01JUL1991	18:00 29AUG23					AE	14NOV23	
R.O. OPENED		READY		OPTIONS:						
15:06 29AUG23		18:10 14NOV23								

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A PERFORM FULL VEHICLE COMPLIMENTARY MULTI-POINT INSPECTION

CAUSE: MPI

MPI PERFORM FULL VEHICLE COMPLIMENTARY  
MULTI-POINT INSPECTION

123ISERV

(N/C)

101ISERV

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

8660 MPI

passenger low beam headlight out, left turn signal intermittent

Battery needs charge

Engine oil drain plug leaking - dripping off of the undercover above it

tires DOT is from 1999, tread= 6/32" front and 5/32" rear

front driver side brake pads has crack through the middle all the way through from left to right side

alternator top mounting bracket is missing a nut

front lid shocks worn and not holding deck lid

Tech 101 :

It has had a cam belt at some time but I don't think the cam seals or O-rings were done. If they were done, they are not working. The cam O-rings are leaking. While this could be lived with if the client wanted, at some point it needs to be addressed. There is oil dripping, I would call it a dynamic leak for sure. The right front shock is damp and would indicate some seepage, not a big issue. The coolant hoses have never been touched. It is a nice visual for originality. The clutch releases a bit high and would indicate some wear, again original. The tire are original and if this is a low mileage, static show / investment car that will not be driven, then this is fine. Same with the oil leak, cracked brake pad, shock seepage, & clutch feel. The fuel door release is sticking open. May just need lube and movement to free it up enough.

\*\*\*\*\*

B\*\* CHECK AND DIAG FOR LIGHTS AND BLINKERS

CAUSE: Lights

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

12445

INVOICE

PAGE 2

**MERLIN**  
AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
[www.merlinautogroup.com](http://www.merlinautogroup.com)

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939				8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE		PAYMENT	INV. DATE	
01JUL89 DD	01JUL89	01JUL1991	18:00 29AUG23					AE	14NOV23	

R.O. OPENED	READY	OPTIONS:
15:06 29AUG23	18:10 14NOV23	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
		LIGHTS	DIAGNOSE	LIGHT FUNCTIONS AND REPLACE BULBS			
		123	CU				
	1	158	MINI BULB-2PK				
	1	9006	HEADLIGHT BULB				
	8	36806	ZY NYL LK NUT M6 X 1.00				

8660 Lights Low beam bulb passenger side is out (9008) and both front side marker bulbs are out (158)

\*\*\*\*\*

C\*\* MAJOR MONDIAL SERVICE - OIL AND FILTER CHANGE, BRAKE FLUID EXCHANGE, COOLANT EXCHANGE, GEAR OIL CHANGE, ENGINE AIR FILTER REPLACEMENT, REPLACE SPARK PLUGS, REPLACE WIPER BLADES, REPLACE ACCESSORY BELTS, REPLACE TIMING BELTS, REPLACE CAM SEALS

CAUSE: DUE FOR MAJOR SERVICE

MAJOR-MONDIAL MAJOR MONDIAL SERVICE - OIL AND  
FILTER CHANGE, BRAKE FLUID EXCHANGE, COOLANT  
EXCHANGE, GEAR OIL CHANGE, ENGINE AIR FILTER  
REPLACEMENT, REPLACE SPARK PLUGS, REPLACE  
WIPER BLADES, REPLACE ACCESSORY BELTS,  
REPLACE TIMING BELTS, REPLACE CAM SEALS

123 CU

101 CU

1 197654 FERRARI OIL FILTER

348/355/360/MONDIAL T

10 PEN5W40 PENNZOIL 5W40

4 10261860 COPPER WASHER M22 X 29 4602229

1 WIN0109 WINZER BRAKE PARTS CLEANER -

ORIGINAL FORMULA 8914520

1 601458 SYNTHETIC DOT 3 AND 4 BRAKE FLUID 1QT

2 1GAL GREEN COOLANT/ANTIFREEZE 1GAL

1 155871 FERRARI AIR FILTER 348/MONDIAL T

2 117792 FERRARI FUEL FILTER

308/328/355/MONDIAL/TR - BOSCH F5601

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR OF THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

* <b>SHOP SUPPLY COSTS:</b>	
-----------------------------	--

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

CUSTOMER #: 10918

12445

INVOICE

PAGE 3

# MERLIN

## AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

SERVICE ADVISOR: 117 YEAR ROYALTY										
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939				8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE	
01JUL89	01JUL89	01JUL1991	18:00 29AUG23					AE	14NOV23	
R.O. OPENED		READY		OPTIONS:						
15:06 29AUG23		18:10 14NOV23								

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
				0450905601			
				8 150180 NGK SPARK PLUG 7162 DR8EA CHAMPION A6GC			
				1 133628 FERRARI OIL SEAL DX DIFF 45X60X8 CW			
				1 132843 FERRARI TIMING BELT 348/MONDIAL T			
				1 PT348 FERRARI TIMING BELT BEARINGS 348/MONDIAL T			
				1 199823 FERRARI ALTERNATOR WATER PUMP BELT MONDIAL T			
				1 199819 FERRARI A/C BELT 348/MONDIAL T			
				2 150075 FERRARI END PLATE GASKET308/348/512			
				1 150074 FERRARI END PLATE GASKET			
				1 150076 FERRARI SUPPORT GASKET 348			
				4 163987 FERRARI CAM SEAL CYLINDER HEAD 355/456/550/575/612			
				4 117275 FERRARI CAM O-RING 308/328/348/456/550/355/MONDIAL			
				4 114808 FERRARI CAM BOLT O-RING 348/355/512/575 MULT MODELS			
				1 150078 FERRARI CAM COVER GASKET 308/328/MON/348			
				1 150084 FERRARI CAM COVER GASKET 308/328/MON/348			
				1 91180A716 M12X1.25 SCREW SET			
				1 91180A720 M12X1.25 SCREW SET			
				1 90576A141 NYLON LOCKNUT			
				1 WIN3537 WINZER COPPER WASHER 16X22 4601622 10257060			
				28 100044 FERRARI CAM COVER ACORN NUT 308/328/348/355 NA6NYLOC			
				1 101239 FERRARI CAM COVER TALL ACORN NUT 6X1.0 348/456/550512TR NA6NYLOC			
				1 149917 FERRARI 348 PHASE SENSOR SEAL			
				4 MOB75W90 MOBIL 1 75W90 GEAR OIL 1 QUART			

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 10918

12445

INVOICE

PAGE 4

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG	
RED		89	FERRARI MONDIAL		ZFFFC33AXK0081939		8660/8692		T2445	
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE
01JUL89		DD	01JUL89	01JUL1991	18:00	29AUG23			AE	14NOV23
R.O. OPENED			READY		OPTIONS:					
15:06			29AUG23							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
PARTS:	2592.84	LABOR:	10125.00	OTHER:	0.00	TOTAL LINE C:	

\*\*\*\*\*

D\*\* RECHARGE AND TEST THE BATTERY.

CAUSE: Battery

BATT CHARGE AND PERFORM BATTER LOAD TEST

123 CU

1 HARDWARE HARDWARE1

8660 Battery Charged battery overnight, battery is reading at 100%

\*\*\*\*\*

E\*\* REPLACE THE COOLANT HOSES AS NEEDED DURING THE SERVICE

CAUSE: Old Hose

COOLING INSPECT AND REPLACE COOLANT HOSES AS  
NEEDED.

101 CU

2 139468 FERRARI MOLDED COOLANT HOSES

8660 Old Hose Replaced the two curved hoses we had to detach during  
the service. Hardware cleaned and inspected.

\*\*\*\*\*

F\*\* FUEL DOOR IS STICKING, ATTEMPT TO LUBE.

CAUSE: Solenoid Sticking

FUELSYS REPAIR FUEL DOOR

123 CU

101 CU

5 HARDWARE HARDWARE1

8660 Solenoid Sticking Fuel door piston does not retract when  
actuated from switch but will retract from emergency pull in engine bay  
but does not reset after pull. Emergency pull seems to be pulled out  
too far and will not go back. Recommend Replacement of solenoid. No  
replacement is available. I removed the solenoid and disassembled it. I  
found the magnetic coil had over heated and warped some of the plastic

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE



CUSTOMER #: 10918

12445

INVOICE

PAGE 5

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG			
RED		89	FERRARI MONDIAL		ZFFFC33AXK0081939				8660/8692		T2445			
DEL. DATE		PROD. DATE	WARR. EXP.		PROMISED		PO NO.		RATE		PAYMENT		INV. DATE	
01JUL89		01JUL89	01JUL1991		18:00 29AUG23				AE		14NOV23			
R.O. OPENED			READY			OPTIONS:								
15:06 29AUG23			18:10 14NOV23											

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
the rod passes through. I clearanced the passage and reassembled. Bench testing found it worked great. I installed it in the car and found the switch was rather sticky. Probably why the coil was over heated. I will remove the switch and see if it can be repaired. Had to remove a lot of the center console to access the switch. Switch was not salvageable, new switch on order. New switch arrived and was installed. Adjusted the door a bit for better function. Full function has been restored.							

\*\*\*\*\*

G\*\* MOUNT AND BALANCE 4 NEW TIRES

CAUSE: mount and balance tires

TIRE4 MOUNT AND BALANCE 4 NEW TIRES

123 CU

2 00560 225/55R16 BFG TIRE

2 TD TIRE DISPOSAL

2 WW WHEEL WEIGHTS

2 91132 205/55R16 BFG TIRE

2 TD TIRE DISPOSAL

8660 mount and balance tires mounted rear tires 225/55/16  
directional tires filled to spec psi. front tires 205/55/16 directional  
filled to spec psi.

\*\*\*\*\*

H\*\* CUSTOMER STATES HAND BRAKE WON'T DISENGAGE, CHECK AND ADVISE.

CAUSE: Needs adjustment

BRAKES ADJUST PARKING BRAKE

123 CU

8660 Needs adjustment Adjusted as part of the service.

\*\*\*\*\*

I\*\* REPLACED FRONT BRAKE PADS

CAUSE: Cracked Brake Pads

FBRK REPLACED FRONT BRAKE PADS

101 CU

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 10918

12445

INVOICE

PAGE 6

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

SERVICE ADVISOR: 117 YEAR ROYALTY										
COLOR	YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939				8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT		INV. DATE
01JUL89	01JUL89	01JUL1991	18:00 29AUG23				AE		14NOV23	
R.O. OPENED		READY		OPTIONS:						
15:06 29AUG23		18:10 14NOV23								

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
1	135704	FERRARI	BRAKE PAD 328/MONDIAL				

8660 Cracked Brake Pads Inspection had found the front brake pads on the left had cracked. It was decided to replace the front pads. I removed the old pads and installed new pads. It went together very well.

\*\*\*\*\*

J PERFORM CYLINDER HEAD OIL DRAIN UPDATE

CAUSE: Oil Drain Back Update

ENGINE PERFORM CYLINDER HEAD OIL DRAIN BACK  
UPDATE.

101 CU

1 88455A42 SST 4MM BIT

8660 Oil Drain Back Update This engine has the oil drain back holes in the wrong place. There was a recall on this and a special tool to re-drill the drain back holes. I acquired the special tool and bit. I cleaned the heads and removed any oil residue. I used a vacuum in the engine to collect and drill debris. I then drilled four new drain holes, one for each cam. This will help keep the oil leakage from happening.

\*\*\*\*\*

K REPLACE ALTERNATOR IDLE PULLEY BEARING

CAUSE: Bad Bearing

ENGINE REPLACE ALTERNATOR PULLY BEARING

101 CU

1 177436 PULLEY BEARING

8660 Bad Bearing During the service, the alternator idler bearing was found to be failing. The bearing was very rough when spun by hand. I removed the pulley and adjustment assembly and cleaned it. I pressed out the old bearing and installed a new one. I greased the assembly for smooth operation and installed it back on the engine. Full function has been restored.

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 10918

12445

INVOICE

PAGE 7

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
RED		89	FERRARI MONDIAL		ZFFFC33AXK0081939		8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE	
01JUL89	01JUL89	01JUL1991	18:00 29AUG23				AE	14NOV23	
R.O. OPENED		READY		OPTIONS:					
15:06 29AUG23		18:10 14NOV23							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
L**	REPLACE	WATER	PUMP				
CAUSE: Bad Bearing							
COOLING REPLACE WATER PUMP (DURING MAJOR SERVICE)							
			101	CU			
	1	143275	WATER	PUMP			
	2	5392032	HOSE	CLAMP M20X32			
	1	NPA5658	NAPA	HEATER HOSE 3/4" ID PER FOOT			
	7	36806	ZY	NYL LK NUT M6 X 1.00			

8660 Bad Bearing During the service inspection it was discovered the water pump bearing had excess play. I new pump was ordered and the old one removed. The pump was the original unit. I found the fasteners were rusted and in need of attention. the housing, studs, & bolts were cleaned and the new pump was installed. While it was off we opted to replace the thermostat as well. The small hose in the valley was also replaced while the pump was off. The larger one is silicone and was in very good condition.

\*\*\*\*\*

## M\*\* REPLACE TIMING SENSORS.

CAUSE: Degraded Sensors

ENGINE REPLACE ENGINE TIMING SENSORS

101 CU

2 130975 SPEED SENSOR

8660 Degraded Sensors During the service procedure, the timing sensor must be removed. As they age they become brittle and the wire become damaged. Handling the sensors and wires usually results in issues. The wires on this car were very bad. Both sensors were replaced to avoid issues. Once the car was started, the sensors were worked perfectly.

\*\*\*\*\*

## N\*\* REPLACE RUBBER BRAKE LINES.

CAUSE: Bad Hoses

BRAKES REPLACE DAMAGED OR STOPPED BRAKE LINES

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

## \* SHOP SUPPLY COSTS:

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 10918

12445

INVOICE

PAGE 8

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

SERVICE ADVISOR: 117 MARK ROBINETTE							
COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT	TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939		8660/8692	T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JUL89 DD	01JUL89	01JUL1991	18:00 29AUG23			AE	14NOV23

R.O. OPENED	READY	OPTIONS:
15:06 29AUG23	18:10 14NOV23	

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
		101	CU				
2	118100	FERRARI	BRAKE HOSE	325MM			
2	118101	FERRARI	BRAKE HOSE	380MM			

8660 Bad Hoses During the service it was discovered the brake hoses were swollen internally and not flowing properly. They were original. All four rubber brake hoses were replaced.

\*\*\*\*\*

O\*\* RIGHT WINDOW IS INOP, CHECK ADN ADVISE

CAUSE: Bad Switch

BODY DIAGNOSE AND REPLACE WINDOW SWITCH

101 CU

8660 Bad Switch The left hand window switch for controlling the right window is sticking and won't allow full function. It is currently working but the left switch should be replaced.

\*\*\*\*\*

P\*\* LEFT HAND PASS. WINDOW SWITCH IS STICKY AND FAILING, REPLACE.

CAUSE: Bad Window Switch

BODY REPLACE LEFT WINDOW SWITCH

101 CU

1 137497 WINDOW SWITCH

1 137486 RH WINDOW SW

8660 Bad Window Switch Left passenger window switch was sticking and causing the right passenger window to not work. Replaced the left passenger window switch. Full function has been restored.

\*\*\*\*\*

Q\*\* REPLACE STRUTS

CAUSE: Bad Struts

STRUTS REPLACE STRUTS

101 CU

2 60559500 HOOD STRUT

1 60563300 LIFT STRUT

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE



CUSTOMER #: 10918

12445

INVOICE

PAGE 9

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
RED		89	FERRARI MONDIAL		ZFFFC33AXK0081939			8660/8692		T2445
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE	PAYMENT	INV. DATE
01JUL89		DD01JUL89	01JUL1991	18:00 29AUG23					AE	14NOV23
R.O. OPENED			READY		OPTIONS:					
15:06 29AUG23			18:10 14NOV23							

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET
------	--------	------	------	-------	------	-----

8660 Bad Struts During the service it was discovered the front and rear trunk struts were bad. Ordered new ones and installed them without issue. Full function has been restored.

\*\*\*\*\*

R\*\* REMOVE "PERIOD CORRECT" CELL PHONE AND ALARM COMPONENTS.

CAUSE: Old Parts Removal

RADIO RADIO IS INOP, PLEASE CHECK AND ADVISE

8660 Old Parts Removal During the removal of the fuel door switch, it was necessary to move very old car phone and alarm parts. Client agreed to have them permanently removed. I removed the alarm and all of its components as well as disconnecting everything from the original car wiring. The cell phone and electronics were removed. I did leave the small antenna mounted to the rear fender. Didn't want to leave a hole.

\*\*\*\*\*

S\*\* HVAC FAN WILL NOT TURN ON TO ANY SPEED, DIAGNOSE AND ADVISE.

CAUSE: Undetermined At This Time

HVAC HVAC DIAG

101 CN

8660 Undetermined At This Time After early diagnostic work, client declined further diagnostic work at this time. Switches have power and ground, further diagnostic would require a further dive into the dash and AC box. It was declined.

\*\*\*\*\*

T\*\* WHEN THE AC BUTTON IS PUSHED THERE IS A REPEATED CLICK FROM THE PASSENGER SIDE OF THE DASH, ADVISE.

HVAC CHECK A/C BUTTON

99ISERV

\*\*\*\*\*

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 10918

12445

INVOICE

PAGE 10

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

SERVICE ADVISOR: 117 MARK MCDANIEL

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
RED	89	FERRARI MONDIAL		ZFFFC33AXK0081939		8660/8692		T2445
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
01JUL89	01JUL89	01JUL1991	18:00 29AUG23				AE	14NOV23
R.O. OPENED		READY		OPTIONS:				
15:06 29AUG23		18:10 14NOV23						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
U**	VEHICLE TRANSPORT						
	TRANSPORT VEHICLE TRANSPORT						
	99ISERV						
	FRT-S TRANSPORT VEHICLE FROM HOME IN ATLANTA TO						
	MAG						
	FRT-S TRANSPORT VEHICLE FROM MAG TO OWNER'S HOME						
	IN ATLANTA						

\*\*\*\*\*

<b>WARRANTY DISCLAIMER:</b> ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES. By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.		<b>* SHOP SUPPLY COSTS:</b> A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.		DESCRIPTION	TOTALS
		<b>ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.</b>		LABOR AMOUNT	---
DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE				PARTS AMOUNT	---
				GAS, OIL, LUBE	---
				SUBLET AMOUNT	---
				MISC. CHARGES *	---
				TOTAL CHARGES	---
				LESS INSURANCE	---
				SALES TAX	---
				<b>PLEASE PAY THIS AMOUNT</b>	---