

# REPAIR ORDER - AUDIT COPY

MERLIN AUTO GROUP  
2882 AMWILER RD  
Atlanta, GA 30360

Work Phone	R/O Open Date	R/O Number
Home Phone	R/O Close Date	Receipt No.
Body	Mileage In	Mileage Out
License Number	Service Advisor	
Account No.	Delivery Date	In-Service Date

Year	Make	Model
1998	MITSUBISHI	PAJERO
Vehicle Identification Number		Color
V554401402		SILVER

8/13/25	6000700/1
8/29/25	Original
193456	193460
LAUREL BAKER	

INVENTORY: P401402C

#1 - P3: PERFORM DETAILED MECHANICAL INSPECTION Work performed by Tech 121 3.00hrs @ 300.00 3 HOUR INSPECTION COMPLETED.	900.00	I
#2 - BATT: REPLACE 12V BATTERY Caused by 12v BATTERY WILL NOT HOLD A CHARGE. Work performed by Tech 121 1.00hrs @ 300.00 MT24 : INTERSTATE BATTERY MT24 1@183.24 12V BATTERY REPLACED.	300.00 183.24	I
#3 - ELECTRICAL: ELECTRICAL Install a new negative battery terminal. Caused by Negative terminal previously overtightened and damaged. Will not tighten properly. Work performed by Tech 121 0.50hrs @ 300.00 781101 : NEG BATT CABLE 1@15.59 Negative terminal cable replaced.	150.00 15.59	I

	INTERNAL	SERVICE CONT.	WARRANTY	CUSTOMER PAY	COST
LABOR	1350.00				
PARTS	198.83				
DEDUCTIBLE					
SUBLET					
SHOP SUPPLIES	77.44				
HAZARDOUS MATERIALS					
SALES TAX OR TAX I.D.					
SPECIAL ORDER DEPOSIT					
DISCOUNTS					
	1626.27				