

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
05/09/25	6000551/1
R/O Close Date	Status
06/24/25	Reprint
Mileage In	Mileage Out
30854	30854
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>#1 - MR P3: PERFORM DETAILED MECHANICAL INSPECTION Caused by Perform inspection as needed Tech: THOMAS MCKELLAR(127) Perform inspection and test drive. Complete.</p>	Internal
<p>#2 - MR NOSTART: NO START, CHECK AND ADVISE Caused by Hood release is not working. Tech: WADE WILLIAMS(101) Inspection found the handle moves but had great resistance. I used the emergency release and got the hood open.</p>	Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
07/18/25	6000660/1
R/O Close Date	Status
08/29/25	Reprint
Mileage In	Mileage Out
30855	30855
Service Advisor / Tag #	
LAUREL BAKER	

1			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>#1 - MR BATT: REPLACE 12V BATTERY Caused by BATTERY NOT HOLDING CHARGE. Tech: VS(121) Installed MTX48H6 :INTERSTATE BATTERY MTX48H6 Installed 103549 :FERRARI RING UNDERTRAY 575 Installed 103550 :SPACER Installed 4110520 :FENDER WASHER ZY M5X20 Installed 65774200 :FERRARI 6MM CAGE NUT 456/575 B BATTERY REPLACED.</p>	<p>Internal Internal Internal Internal Internal Internal</p>
<p>#2 - MR HVAC: HVAC Client states the A/C is not blowing cold, please check and advise Caused by Bad AC Dash Temp Sensor Tech: WADE WILLIAMS(101) Installed 63934200 :SENSOR Installed 63994500 :GRILL Installed 63994700 :WASHER Freight: FEDEX Installed R134A :R134A REFRIGERANT I spoke with Adam and he explained the noise and it ended up being the AC inner compartment sensor. I removed the sensor and found it has broken and the fan was hitting a broken bit and that was the noise. I suspect the sensor is also</p>	<p>Internal Internal Internal Internal Internal Internal</p>

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
07/18/25	6000660/2
R/O Close Date	Status
08/29/25	Reprint
Mileage In	Mileage Out
30855	30855
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>why the AC has stopped cooling well. Once this is repaired we will evaluate the over AC function. Evac and recharge and the system is blowing 55 degrees.</p>	
<p>#3 - MR NOISE: CHECK AND ADVISE Client states there is noise coming from under the steering column, check and advise Caused by Bad Temp Sensor Tech: WADE WILLIAMS (101) Inspection found the temp sensor on the dash had broken and the little fan was hitting internal parts. It failed completely and the AC stopped working. Installed a new sensor, backing plate, & grill. The AC is functioning again but needs further diag for full function to be restored.</p>	Internal
<p>#4 - MR DIAG: FIVE HOURS OF DIAGNOSIS Hood latch is inop, check and advise Caused by Seized Cable Tech: WADE WILLIAMS (101) Installed 65278100R :HOOD REL HANDLE Installed 65832600A :HOOD CABLE Installed 81266200 :M5X.80 25MM SCREW Installed 14440834 :18-8 SS HEX DRIVE FLAT HEAD M5 The pull cable has seized. To remove the cable, you must open the release handle. With a seized</p>	Internal Internal Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X
© 2016 DEALERTRACK TECHNOLOGIES - Dealership Application Group

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
07/18/25	6000660/3
R/O Close Date	Status
08/29/25	Reprint
Mileage In	Mileage Out
30855	30855
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>cable that can not happen. The release handle is broken already and in very poor condition. We are checking on availability and if we can get a handle, we will break the old one and remove it. Then the cable can be replaced. removed the old broken handle. Installed new handle and routed new cable. The old cable was epoxied to the housing. Had to carefully removed the epoxy to save the part. Housing and handle are in with a new cable and full function was restored.</p>	
<p>#5 - MR LEAK: CHECK AND ADVISE While parked, noted coolant seepage, please check and advise Caused by Bad Coolant Pump Tech: WADE WILLIAMS (101) Installed 65460300 :AUX WATER PUMP Freight: FEDEX Inspection found the auxiliary coolant pump has failed and is leaking coolant. Will need a replacement pump, 2.0 hr est.</p>	<p>Internal Internal Internal</p>
<p>#6 - MR COOLING: CHECK AND ADVISE Remove and replace coolant pump Caused by Bad Pump Tech: WADE WILLIAMS (101) Installed 218457 :CONNECTOR</p>	<p>Internal Internal</p>

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
07/18/25	6000660/4
R/O Close Date	Status
08/29/25	Reprint
Mileage In	Mileage Out
30855	30855
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Installed 5391625 :HOSE CLAMP NORMA M16 X 25	Internal
Installed 5392032 :HOSE CLAMP M20X32	Internal
Installed HARDWARE :HARDWARE1	Internal
Inspection found the heater coolant pump had failed and was leaking. I ordered a new one, upon arrival it was discovered it had updated connections. The wiring had to be modified and a new Amp Bosch connection added to the harness to connect the new pump. I installed the new pump and wiring, used new hose clamps and nuts. It is now working without leaking.	

#7 - MR STICKY: REPAIR STICKY BUTTONS	
Work performed by G4 A001 : 000034 ()	Labor: Internal
Work performed by G4 A001 : 000034 ()	Parts: Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES: Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/23/25	6000818/1
R/O Close Date	Status
01/12/26	
Mileage In	Mileage Out
30902	30903
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
INVENTORY: P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
<p>#1 - MR INTERIOR: INTERIOR Rear view mirror isn't attached, please repair Caused by Broken Windshield Tech: WADE WILLIAMS (101) Sub Total: Labor: .00 Parts: .00 Total: .00 The windshield is broken and the mirror has a chunk of glass still on it. Without replacing the windshield, some kind of super glue is the only option and I am not sure that will hold. I would suggest we contact Trudy and see if she has a suggestion for remounting.</p>	Internal
<p>#2 - MR LATCHES: CHECK AND ADVISE The trunk is not opening, check and advise on repairs Caused by WW- Blown & Incorrect Fuse. MB- Emergency release cable not working and trunk not opening every time due to sticking latch mechanism. Tech: WADE WILLIAMS (101) Tech: MALCOLM BARNETT (102) Installed 92581A450 :STEELE RAISED THUMB SCREW M6 Sub Total: Labor: .00 Parts: .00 Total: .00 WW- Inspection found the trunk release button was not opening the trunk. Tested the switch, good. Inspected the fuse and found it was blown. Also, it was 10amp not 15 as it should be. I installed a new 15 amp fuse and full function was restored.</p>	Internal Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/23/25	6000818/2
R/O Close Date	Status
01/12/26	
Mileage In	Mileage Out
30902	30903
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
INVENTORY: P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
The fuse panel access door had no fasteners. I installed two new thumb screws to allow better fuse door access and still have it fastened. MB-Adjusted emergency cable and lubricated. Cleaned and lubricated latch mechanism and verified correct operation.	

#3 - MR BODY: BODY Install a US tag bracket Caused by No Bracket. It is a Japan car. Tech: WADE WILLIAMS(101) Installed 046616 :PH PAN SCREW MS M6X16X1 Installed HARDWARE :HARDWARE1 Sub Total: Labor: .00 Parts: .00 Total: .00 Modified the existing bracket to accept a US tag.	Internal Internal Internal

#4 - MR NOISE: CHECK AND ADVISE Check for wind noise heard from drivers window. Tech: MALCOLM BARNETT(102) Sub Total: Labor: .00 Parts: .00 Total: .00	Internal

#5 - MR LIGHTS: CHECK AND ADVISE Turn signal is inop, check and advise Caused by Turn signal relay has internal fault. Tech: MALCOLM BARNETT(102) Installed 171375 :FERRARI 456 FLASHER RELAY Replaced turn signal relay to correct condition.	Internal Internal

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X

MERLIN AUTO GROUP

2882 Amwiler Rd. - Atlanta, GA 30360
Ph: (770) 457-2699 | www.merlinautogroup.com

SERVICE DEPARTMENT HOURS
9:00 a.m. to 6:00 p.m.
Monday - Friday
Closed Saturday & Sunday

R/O Open Date	R/O Number
10/23/25	6000818/3
R/O Close Date	Status
01/12/26	
Mileage In	Mileage Out
30902	30903
Service Advisor / Tag #	
LAUREL BAKER	

			Work Phone	Vehicle Identification Number	
				ZFFSD44S000099845	
			Home Phone	Delivery Date	In-Service Date
				00/00/00	00/00/00
Year	Make	Model	Body	Color	License Number
1996	FERRARI	456		BLUE	
INVENTORY: P099845C					

DESCRIPTION OF SERVICE AND PARTS	AMOUNT
Verified correct operation of turn signals and hazards after repairs.	

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OF WARRANTIES. Any warranties on the products sold hereby are those made by the manufacturer. The seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

LABOR	.00
PARTS	.00
DEDUCTIBLE	.00
SUBLET	.00
SHOP SUPPLIES	.00
HAZARDOUS MATERIALS	.00
SALES TAX OR TAX I.D.	.00
SPECIAL ORDER DEPOSIT	.00
DISCOUNTS	.00
TOTAL DUE	.00

NO RETURN ON ELECTRICAL OR SAFETY ITEMS OR SPECIAL ORDERS.

X