

CUSTOMER #: 1913656

12393

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

MERLIN AUTO GROUP

2882 AMWILER RD

ATLANTA, GA 30360

HOME: 770-457-2699 CONT: 770-457-2699

INVOICE

PAGE 1

BUS: CELL: SERVICE ADVISOR: 115 LAUREL BAKER

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
YELLOW		95	FERRARI F355 Berline		ZFFPR41A6S0100630				19048/19118		T2393
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE		PAYMENT	INV. DATE
15MAR23 DD				18:00 03AUG23				225.00		CASH	29SEP23

R.O. OPENED READY OPTIONS: STK: P100630C

15:05 03AUG23 12:43 29SEP23

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	MAJOR	355	SERVICE - OIL & FILTER CHANGE, BRAKE FLUID EXCHANGE, GEAR/F1 FLUID EXCHANGE, STEERING FLUID EXCHANGE, COOLANT EXCHANGE, ENGINE AIR FILTER REPLACEMENT, REPLACE SPARK PLUGS, REPLACE FUEL FILTERS, REPLACE TIMING AND DRIVE BELTS				

CAUSE: MAJOR SERVICE

MAJOR-355 MAJOR SERVICE F355

121	INT						(N/C)
2	10261860	COPPER WASHER M22 X 29 4602229					(N/C)
2	WIN0109	WINZER BRAKE PARTS CLEANER - ORIGINAL FORMULA 8914520					(N/C)
1	WIN3532	WINZER COPPER WASHER 10X14 4601014					(N/C)
1	WIN3537	WINZER COPPER WASHER 16X22 4601622					(N/C)
10257060							(N/C)
1	197654	FERRARI OIL FILTER					(N/C)
348/355/360	MONDIAL T						(N/C)
10	PEN5W40	PENNZOIL 5W40					(N/C)
8	169483	FERRARI NGK SPARK PLUG 4259 F355					(N/C)
PMR7A							(N/C)
2	151562	FERRARI AIR FILTER 355/456					(N/C)
2	152212	FERRARI FUEL FILTER					(N/C)
348/456/550/512/355	2.7 -						(N/C)
BOSCH0450905087	TECNOCAR						(N/C)
2	184986	FERRARI TIMING BELT 355/360					(N/C)
2	167464	FERRARI 355 TIMING BEARING PT355					(N/C)
1	199830	FERRARI A/C BELT 348/355					(N/C)
1	199832	FERRARI 355 POWER STEERING BELT					(N/C)
1	199833	FERRARI 355 ALTERNATOR BELT					(N/C)
2	140787	FERRARI PHASE SENSOR GASKET					(N/C)
456/550/355							(N/C)
8	149554	FERRARI 355 SPARK PLUG TUBE O-RING					(N/C)
1	163620	FERRARI F355 LH PLUG COVER GASKET					(N/C)
1	163621	FERRARI F355 RH PLUG COVER GASKET					(N/C)
1	176156	FERRARI 355 CAM COVER GASKET					(N/C)
1	176157	FERRARI 355 CAM COVER GASKET					(N/C)

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 1913656

12393

# MERLIN AUTO GROUP

MERLIN AUTO GROUP

2882 AMWILER RD

ATLANTA, GA 30360

HOME: 770-457-2699 CONT: 770-457-2699

INVOICE

PAGE 2

 2882 AMWILER RD  
 ATLANTA, GA 30360  
 (770) 457-2699  
 www.merlinautogroup.com

BUS: CELL: SERVICE ADVISOR: 115 LAUREL BAKER

COLOR		YEAR	MAKE/MODEL		VIN		LICENSE		MILEAGE IN / OUT		TAG
YELLOW		95	FERRARI F355 Berline		ZFFPR41A6S0100630				19048/19118		T2393
DEL. DATE		PROD. DATE	WARR. EXP.	PROMISED		PO NO.		RATE		PAYMENT	INV. DATE
15MAR23 DD				18:00 03AUG23				225.00		CASH	29SEP23

R.O. OPENED READY OPTIONS: STK: P100630C

15:05 03AUG23 12:43 29SEP23

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
4	163987	FERRARI	CAM SEAL CYLINDER HEAD				(N/C)
	355/456/550/575/612						
4	114808	FERRARI	CAM BOLT O-RING				(N/C)
	348/355/512/575	MULT MODELS					
2	117275	FERRARI	CAM O-RING				(N/C)
	308/328/348/456/550/355/	MONDIAL					
4	158349	FERRARI	CAM O-RINGS 355/575M/612				(N/C)
1	63934300	FERRARI	348/355 A/C DRIER				(N/C)
2	1GAL	GREEN COOLANT/ANTIFREEZE	1GAL				(N/C)
1	601458	SYNTHETIC DOT 3 AND 4 BRAKE FLUID	1QT				(N/C)
5	MOB75W90	MOBIL 1 75W90 GEAR OIL	1 QUART				(N/C)
1	133628	FERRARI	OIL SEAL DX DIFF 45X60X8 CW				(N/C)
1	10396480	FERRARI	RUBBER GROMMET 14-5 X 1.5				(N/C)
	308/458/430/	MONDIAL					
2	HARDWARE	HARDWARE1					(N/C)
6	WIN3533	WINZER	COPPER WASHER 12X16 4601216				(N/C)
2	4601420	COPPER WASHER	14X20				(N/C)
1	157289	SCREW					(N/C)
2	137534	FERRARI	SCREW 355/348 MUFFLER MOUNT				(N/C)
1	167266	FERRARI	EXHAUST BOLT 355/360				(N/C)
	M6X1X35MM 91292A141						
1	176921	176921	TOP LOCK DISTORTED THREAD				(N/C)
	LOCKNUT M6X1MM	FERRARI 355					
2	149707	FERRARI/MASERATI	SHIM SPACER				(N/C)
	355/360/4200						
1	602241	VALVOLINE	POWER STEERING FLUID				(N/C)
6	100044	FERRARI	CAM COVER ACORN NUT				(N/C)
	308/328/348/355	NA6NYLOC					
1	36808	ZY NYL LK NUT M8X1.25	SW13				(N/C)
8	HARDWARE	HARDWARE1					(N/C)
6	113113	WASHER					(N/C)
6	10519424	WASHER					(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

19048 MAJOR SERVICE Removed engine and transmission. Replaced

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

## \*SHOP SUPPLY COSTS:

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

CUSTOMER #: 1913656

12393

**MERLIN  
AUTO GROUP**2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

INVOICE

MERLIN AUTO GROUP

2882 AMWILER RD

ATLANTA, GA 30360

HOME: 770-457-2699 CONT: 770-457-2699

PAGE 3

BUS: CELL: SERVICE ADVISOR: 115 LAUREL BAKER

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
YELLOW	95	FERRARI F355 Berline		ZFFPR41A6S0100630		19048/19118		T2393
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
15MAR23 DD			18:00 03AUG23			225.00	CASH	29SEP23

R.O. OPENED READY OPTIONS: STK: P100630C

15:05 03AUG23 12:43 29SEP23

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
					timing belt and tensioner pulleys as well as cam cover gaskets. Once engine was reinstalled, we replaced all fluids, bled the brake, cooling system, and clutch and recharged the A/C. Completed a test drive to confirm repair.		

\*\*\*\*\*

B\*\* REFINISH CAM COVERS

CAUSE: CAM COVER PAINT CHIPPING

ENGINE REFINISH CAM COVERS

121 INT (N/C)

1 VHT0113 VHT WRINKLE PLUS RED SP204 (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00

19048 CAM COVER PAINT CHIPPING CAM COVERS REFINISHED AND

REINSTALLED.

\*\*\*\*\*

C\*\* R&amp;R SPARK PLUG WIRES

CAUSE: SPARK PLUG WIRES COVERED IN SILICONE

SPARK REPLACE SPARK PLUGS WIRES

121 INT (N/C)

1 9793 IGN WIRE SET (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

19048 SPARK PLUG WIRES COVERED IN SILICONE SPARK PLUG WIRES

REPLACED.

\*\*\*\*\*

D\*\* R&amp;R CAT PIPES

CAUSE: CATALYTIC CONVERTERS BAD

EXHAUST INSTALL STRAIGHT PIPES

121 INT (N/C)

2 WIN3538 WINZER COPPER WASHER 18X24 4601824 (N/C)

4 14058519 FERRARI/MASERATI EXHAUST COPPER NUT

355/430/3200GT 210971 NCF8X12 (N/C)

4 HARDWARE HARDWARE1 (N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE D: 0.00

19048 CATALYTIC CONVERTERS BAD BOTH CATALYTIC CONVERTERS REPLACED

WITH STRAIGHT PIPES.

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE



CUSTOMER #: 1913656

12393

# MERLIN AUTO GROUP

2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

MERLIN AUTO GROUP

2882 AMWILER RD

ATLANTA, GA 30360

HOME: 770-457-2699 CONT: 770-457-2699

INVOICE

PAGE 4

BUS: CELL: SERVICE ADVISOR: 115 LAUREL BAKER

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
YELLOW	95	FERRARI F355 Berline		ZFFPR41A6S0100630		19048/19118		T2393
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
15MAR23 DD			18:00 03AUG23			225.00	CASH	29SEP23

R.O. OPENED READY OPTIONS: STK: P100630C

15:05 03AUG23 12:43 29SEP23

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

E\*\* R&amp;R THROTTLE CABLE

CAUSE: THROTTLE CABLE FRAYED.

ENGINE REPLACE THROTTLE CABLE

121 INT

(N/C)

1 164441 FERRARI 355 THROTTLE CABLE

(N/C)

1 63566800 ACC PEDAL COVER

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00

19048 THROTTLE CABLE FRAYED. Throttle cable replaced.

\*\*\*\*\*

F\*\* REPAIR INNER FENDER LINER.

CAUSE: INNER FENDER LINER DAMAGED

BODY INNER FENDER LINER

121 INT

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F: 0.00

19048 INNER FENDER LINER DAMAGED Inner fender liner repaired.

\*\*\*\*\*

G\*\* DIAG A/C NOT BLOWING COLD WHILE STOPPED.

CAUSE: A/C NOT BLOWING COLD CONSISTENTLY

A/C CHECK AND ADVISE

121 INT

(N/C)

1 173030 FERRARI COMPLETE RADIATOR FAN

ASSEMBLY 355

(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE G: 0.00

19048 A/C NOT BLOWING COLD CONSISTENTLY Ran vehicle until engine was at operating temperature, noticed coolant temp was abnormally high and checked both fans. The right side (oil cooler) fan was functioning normally and the left (A/C) was barely turning. We unplugged the connector and hooked up 12V straight to the fan and found the fan would barely turn. After fan replacement, engine was brought up to operating temp and A/C was checked. A/C now blowing cold at idle.

\*\*\*\*\*

H\*\* RESEAT OIL COOLER LINE FOR LEAKAGE.

CAUSE: OIL LINE LEAKING

LEAK CHECK AND ADVISE

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES *	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
<b>PLEASE PAY THIS AMOUNT</b>	

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE



CUSTOMER #: 1913656

12393

**MERLIN  
AUTO GROUP**2882 AMWILER RD  
ATLANTA, GA 30360  
(770) 457-2699  
www.merlinautogroup.com

MERLIN AUTO GROUP

2882 AMWILER RD

ATLANTA, GA 30360

HOME: 770-457-2699 CONT: 770-457-2699

INVOICE

PAGE 5

BUS: CELL: SERVICE ADVISOR: 115 LAUREL BAKER

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN / OUT		TAG
YELLOW	95	FERRARI F355 Berline		ZFFPR41A6S0100630		19048/19118		T2393
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED		PO NO.	RATE	PAYMENT	INV. DATE
15MAR23 DD			18:00 03AUG23			225.00	CASH	29SEP23

R.O. OPENED READY OPTIONS: STK: P100630C

15:05 03AUG23 12:43 29SEP23

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
			121	INT			(N/C)

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE H: 0.00

19048 OIL LINE LEAKING Oil line was moved and reinstalled. Line no longer leaking, but will recheck after longer test drive.

\*\*\*\*\*

I\*\* ADJUST PARKING BRAKE

CAUSE: PARKING BRAKE ADJUSTMENT

BRAKES SERVICE BRAKES

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE I: 0.00

19048 PARKING BRAKE ADJUSTMENT Parking brake adjustment completed.

\*\*\*\*\*

J\*\* INTERNAL LIGHTS ARE NOT WORKING, CHECK AND ADVISE

CAUSE: INTERNAL LIGHTS NOT WORKING

LIGHTS CHECK AND ADVISE

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE J: 0.00

19048 INTERNAL LIGHTS NOT WORKING Checked fuse for interior lights. Found a blown fuse and replaced it. Now interior lights working normally.

\*\*\*\*\*

K\*\* BATTERY LIGHT IS ON, CHECK AND ADVISE

CAUSE: CHECK BATTERY

BATT CHECK BATTERY LIGHT

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE K: 0.00

19048 Battery is good. Checked all connections and ground wires - all secure. Checked for any damaged wires and none found. Only note for inspection is that the alternator has a bit of residue from previous oil leaks prior to service. After several overnight road tests, the issue has resolved.

\*\*\*\*\*

**WARRANTY DISCLAIMER:** ALL PARTS AND ACCESSORIES ARE SOLD AND ALL REPAIRS ARE PROVIDED BY THE DEALERSHIP AS-IS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR. THE ONLY WARRANTIES ON PARTS AND ACCESSORIES OR REPAIRS ARE THOSE WHICH MAY BE OFFERED BY THE MANUFACTURER OR THE ORIGINAL PARTS DISTRIBUTOR AND ONLY SUCH MANUFACTURER OR DISTRIBUTOR SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. CUSTOMER SHALL NOT BE ENTITLED TO RECOVER FROM THE DEALERSHIP ANY CONSEQUENTIAL DAMAGES, DAMAGES TO PROPERTY, DAMAGES FOR LOSS OF USE, LOSS OF TIME, LOSS OF PROFIT OR INCOME, OR ANY OTHER INCIDENTAL DAMAGES.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

**\* SHOP SUPPLY COSTS:**

A charge equal to 5% of the total cost of parts and labor will be added to the Repair Order for shop supplies used in connection with the repair.

**ALL PARTS ARE NEW  
UNLESS OTHERWISE  
INDICATED.**

DESCRIPTION	TOTALS
LABOR AMOUNT	0.00
PARTS AMOUNT	0.00
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES *	0.00
TOTAL CHARGES	0.00
LESS INSURANCE	0.00
SALES TAX	0.00
<b>PLEASE PAY THIS AMOUNT</b>	<b>0.00</b>

DATE CUSTOMER SIGNATURE AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

**AUTOSUPERSHIELD**

4701 North Dixie Hwy  
Boca Raton, FL 33431  
Phone: 561-367-0101  
Fax: 561-347-8554

3748

DATE: 3-27-13

S O L D T O	NAME		<b>SERVICE</b> <input checked="" type="checkbox"/> Paint Protection <input type="checkbox"/> Window Tint <input type="checkbox"/> Detailing <input type="checkbox"/> Other _____		
	ADDRESS				
	CITY, ST, ZIP				
	PHONE				
YEAR	MAKE	MODEL			
1995	FERRARI	355 YELLOW			
QUANTITY	DESCRIPTION		HOURS	RATE	AMOUNT
	PAINT SHIELD INSTALLED				
	ProForm Design				
	24" HOOD & FENDERS				
	MIRRORS & POSTS				
	FRONT BUMPER COVER				
	WHEEL ARCHES				
	c/o Phil				
	THANK YOU!				
VIN #			RO#	KEY TAG	SUBTOTAL:
A650100630					SALES TAX:
X					TOTAL: \$750.00

APPROVAL SIGNATURE

By signing I authorize payment to Auto SuperShield and approve that the work was completed to my satisfaction without damage to the vehicle.

Thank You



**Klub Sport Racing, Inc.**

3709 Interstate Park Rd. S  
Riviera Beach, FL 33404

# INVOICE

Date

Invoice #

3/28/2013

33689

Billed to:

Phone: 561-844-8752

Fax: 561-844-8772

TERMS	DUE DATE	CAR#	PROJECT	OTHER INFORMATION	
	3/28/2013				
QTY/HRS	DESCRIPTION OF SERVICE			RATE	AMOUNT
1	REIMBURSEMENT FOR AUTOSUPERSHIELD OF 1995 FERRARI 355			750.00	750.00
1	1/2 PINT TOUCH UP PAINT -- REIMBURSEMENT			62.70	62.70
Thank you for your business.				Subtotal	\$812.70
E-mail Address officemanager@klubsportracing.com				Sales Tax (0.0%)	\$0.00
TERMS: INDICATED ABOVE FROM INVOICE DATE unless prior arrangements are made. Invoices not paid in accordance with terms are subject to a service charge of 1.5%, per month, or any part there of; approximately 18.0% per year.				Total	\$812.70
				Payments/Credits	\$0.00
				Balance Due	\$812.70



**Auto Tronics**  
995 B Jaymor Road  
Southampton, PA. 18966  
Phone: 215-357-2877 Fax: 215-357-2890

**INVOICE**

**18609**

**INVOICE**

Work Completed Date : 08/10/2016

Vehicle Received: 08/10/2016

Invoice Date: 08/10/2016

1995 Ferrari - F355 Berlinetta - 3.5L, V8

Lic # : 0100630 - PA

Odometer In : 18240

VIN # : ZFFPR41A6 S0100630

Cust ID : 1870

Part Description	I Number	Qty	Sale	Ext	Labor Description	Extended
A/C COMPRESSOR	157355	1.00	520.00	520.00		
FREON	R134A	1.76	12.95	22.79		
A/C DYE	DYE	1.00	3.73	3.73		
FUSE HOLDER 30 AMP	BUSBP/MHD-RP	1.00	2.44	2.44		
Annual Inside Safety Sticker	AI STICKER	1.00	5.00	5.00		
Shop Supplies				18.85		

Org. Estimate 9,856.17 Revisions 0.00 Current Estimate 9,856.17

Labor:	3,860.00
Parts:	5,209.55
Sublet:	1,293.51
Discount:	-750.00
SubTotal:	9,613.06
Tax:	0.00
Total:	9,613.06
Bal Due:	\$9,613.06

**[ Payments - ]**

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Written By: F. Owen - Technicians : O. Antony; SELECT TECHNICIAN : F. Owen; Kuhner, Brian



**Brandon Motor Cars, Inc.**3709 Interstate Park Rd. S  
Riviera Beach, FL 33404**INVOICE**

Date

Invoice #

3/28/2013

33693

Billed to:

**PAID**

Phone: 561-844-8752

Fax: 561-844-8772

1995 FERRARI  
ZFFPR41A680100630

TERMS		DUE DATE	CAR#	PROJECT	OTHER INFORMATION	
		3/28/2013				
QTY/HRS	DESCRIPTION OF SERVICE				RATE	AMOUNT
	MILEAGE OUT: 15,596					
	PRE-SALE SERVICE AT NO CHARGE					
	PARTS					
2	BOSCH ELECTRIC FUEL PUMPS				0.00	0.00T
1	FUEL FILTERS				0.00	0.00T
1	OIL FILTER				0.00	0.00T
2	FRONT HOOD GAS STRUTS				0.00	0.00T
2	REAR DECK LID GAS STRUTS				0.00	0.00T
1	QUART BRAKE FLUID				0.00	0.00T
10	GALLONS 93 OCTANE FUEL				0.00	0.00T
9	QUARTS MOBIL 1 MOTOR OIL				0.00	0.00T
4	QUARTS GEAR BOX FLUID				0.00	0.00T
1	INTERSTATE BATTERY				0.00	0.00T
1	CV JOINT BOOT				0.00	0.00T
1	TUBE CV JOINT GREASE				0.00	0.00T
	SUB-TOTAL					0.00
	LABOR					
25	MAJOR SERVICE AFTER SITTING. REMOVE AND REPLACE BATTERY; REMOVE FUEL TANKS, CLEAN TANKS AND REPLACE FUEL PUMPS; REPLACE FUEL FILTERS. LUBE, OIL & FILTER. SERVICE TRANSMISSION. REPLACE TORN INNER RIGHT JOINT CV BOOT. REMOVE RIGHT MOTOR MOUNT; REPAIR CRACK. FLUSH BRAKE SYSTEM, REPLACE HOOD AND DECK LID SHOCKS, DE-STICKY PLASTIC IN INTERIOR. TREAT LEATHER, WASH & WAX.				0.00	0.00T
	SUB-TOTAL					0.00
Thank you for your business.					Subtotal	\$0.00
E-mail Address officemanager@klubsportracing.com					Sales Tax (0.0%)	\$0.00
TERMS: INDICATED ABOVE FROM INVOICE DATE unless prior arrangements are made. Invoices not paid in accordance with terms are subject to a service charge of 1.5%, per month, or any part thereof; approximately 18.0% per year.					Total	\$0.00
					Payments/Credits	\$0.00
					Balance Due	\$0.00



# AUTO ELITE CORP.

2085 HUDSON STREET

024

E.R.F. # 001349

INV0000587

1/14/02

1/14/02

FERRARI

355 TB YELLOW

ID#100630

LTF25T

11993

95

REMOVE ENGINE REPLACE TIMING BELTS CAM SEALS V/COVER GSKTS REPL ALL THE BELTS FILTERS  
FLUIDS AND SPARK PLUGS

QUANTITY	ITEM NUMBER	DESCRIPTION	PRICE	TOTAL
1	SERV	LABOR 30 HRS		\$1,950.00
2	181610	TIMING BELT	\$83.82	\$167.64
1	158101	P/S BELT	\$7.47	\$7.47
1	158102	W/PUMP BELT	\$20.39	\$20.39
1	156703	A/C BELT	\$10.99	\$10.99
1	164417	UPPER WATER HOSE	\$68.34	\$68.34
8	NGKPMR7A	355 PLATINUM SPARK PLUG	\$35.80	\$286.40
2	151562	AIR FILTER	\$40.37	\$80.74
1	130623	OIL FILTER	\$13.59	\$13.59
2	F117792	FUEL FILTER	\$34.39	\$68.78
1	GSKT KIT	ALL V/C GSKT O/RINGS AND SEALS	\$183.92	\$183.92
5	SHELL 75W90	SIND GEAR OIL	\$13.40	\$67.00
10	AGIP SIND 2000	SINDETIC MOTOR OIL	\$5.50	\$55.00
2	ANTI FREEZE	GALLON COOLANT FLUID	\$10.00	\$20.00
1	FREON	A/C FREON GAS	\$70.00	\$70.00
PAID IN FULL.				

**EXOTIC  
CAR  
SPECIALISTS**

Credit Card Number

Check Number



Other:

Tax: \$184.22

Total: \$3,254.48

Amount \$0.00

Balance Due: \$3,254.48

Authorized signature



SALES • SERVICE  
780 N. Western  
LAKE FOREST, IL. 60045  
(847) 295-6560




FACTORY AUTHORIZED DEALER  
**LFSC**  
LAKE FOREST SPORTSCARS, LTD.



BODY SHOP  
28845 Nagel Ct.  
LAKE BLUFF, IL. 60044  
(847) 295-5389

by Rick Mancini



CUSTOMER ACKNOWLEDGES RECEIPT OF COPY THEREOF.

VEHICLE IDENT. NO.

VEHICLE CTL. NO.

MESSAGE

ADV.

YR/MODEL

95

PHONE-BUS.

RES.

CUSTOMER NO.

TAG NO.

INVOICE NO.

DATE

WORK ORDER NO.

75FRR11A650100630

50100630

6184

075 F25E

LABOR AND PARTS

CHECK ENGINE, 174 SEON DOWN LIGHT IS ON.  
DIAGNOSE WITH SD-1 & FOUND ERROR FOR HIGH CAT TEMP. FOUND  
FAULTY CAT CONTROL ECU, REPLACE ECU & TEST, NOW OK.  
1-160454 ECU

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The seller hereby expressly disclaims all warranties, either express or implied including any implied warranty of merchantability or fitness for a particular purpose and the seller neither assumes nor authorizes any person to assume for it any

COST	WARRANTY ACCOUNT	AMOUNT
15.20	4540	64.00
131.11	4642	174.38

528

COST	INTERNAL ACCOUNT	AMOUNT

COST	ACCOUNT	CUSTOMER PAY DESCRIPTION	AMOUNT
		DLR MEC FER	
		DLR MEC FER-PTS	

DLR MEC FER  
DLR MEC FER-PTS



work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described  
 for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs  
 performed.

Copyright (c) 2015 Mitchell Repair Information Company, LLC. Invo 2.15104

**Auto Tronics**  
 995 B Jaymor Road  
 Southampton, PA. 18966  
 Phone: 215-357-2877 Fax: 215-357-2890

*QW13719H*  
*8/10*

INVOICE  
 18609

**INVOICE**

Work Completed Date : 08/10/2016  
 Vehicle Received: 08/10/2016

Invoice Date: 08/10/2016

1995 Ferrari - F355 Berlinetta - 3.5L, V8  
 Lic #: 0100630 - PA

Odometer In : 18240

VIN #: ZFFPR41A6 S0100630

CUST ID : 1870

Part Description	I Number	Qty	Sale	Ext	Labor Description	Extended
REDLINE GEAR OIL		2.00	69.60	139.20	TOW VEHICLE TO SHOP	95.00
58305					PERFORM MAJOR MAINTENANCE SERVICE	2720.00
MAJOR SERVICE KIT: CAM SEALS,		1.00	1450.00	1450.00	REPLACE TIMING BELT, SEALS, TENSIONERS, SERPENTINE	
CAM O-RINGS, END PLATE GASKET,					BELTS, WATER PUMP, INTAKE BOOTS, SPARK PLUGS.	
SPARK PLUG O-RING, FUEL BLOCK					REPLACE ALL CRACKED VACUUM LINES AND CRACKED OIL	
O-RING, OIL FILTER, WATER PUMP					BREATHER HOSES. FLUSH ALL FLUIDS.	
HOSE, WATER PUMP S-HOSE,					PARTS FREIGHT	48.51
WASHERS, VALVE COVER GASKETS,					DISASSEMBLE REAR SHOCKS, SEND OUT FOR	255.00
PLUG COVER GASKETS, TIMING					REPAIR AND REASSEMBLE	
BELT, AIR FILTER, SERPENTINE					REAR SHOCK REBUILD SERVICE	1150.00
BELTS, SPARK PLUG					PERFORM 4 WHEEL ALIGNMENT	120.00
355SK2					ALIGNMENT	
TIMING BELT TENSIONER		2.00	369.69	739.38	REAR AXLE BOOTS CRACKED	255.00
157356					REPLACE REAR AXLE BOOTS AND CLAMPS	
WATER PUMP		1.00	349.00	349.00	A/C LEAKING FROM COMPRESSOR AND SEAL FOR	510.00
177561D					REAR LINE	
WATER PUMP O-RING		1.00	21.30	21.30	REPLACE A/C COMPRESSOR, REPLACE SEAL FOR A/C LINE.	
105192					REPLACE IN-LINE 30 AMP FUSE FOR A/C SYSTEM (HEATED	
THERMOSTAT		1.00	164.07	164.07	UP) AND REPAIR CONTACTS FOR BLOWER MOTOR	
165473					(CAUSING SPIKE IN SYSTEM TO BURN UP FUSE). FILL	
TIMING BELT HYDRAULIC		2.00	369.69	739.38	SYSTEM WITH FREON. NO OTHER PROBLEMS FOUND AT	
TENSIONER					THIS TIME	
157356					EXEMPT EMISSION TEST	n/c
CRANKSHAFT SEAL		1.00	47.44	47.44	State Insp. Passenger Car	n/c
133628					Emissions Sticker: IM6-5172378	
INTAKE BOOT		2.00	73.78	147.56	Safety Sticker: A16-6806097 Exp: 07/2017	
160701					Brakes: LF(9B) LR(10B) RF(9B) RR(10B)	
COLLAR		4.00	1.93	7.72	Tires: LF(7) LR(4) RF(6) RR(5)	
13001090					Previous Odometer: N/A	
MOLYKOTE HIGH PERFORMANCE		1.00	28.60	28.60	***Discount***	
GREASE					\$750.00 off labor	
BR2						
MOTUL 600 DOT4 SYNTHETIC FLUID		3.00	17.95	53.85		
8068HL						
CASTROL EDGE 5W40 FULL		10.00	8.35	83.50		
SYNTHETIC OIL						
EFMQT						
SEALING RING		1.00	47.44	47.44		
133628						
COOLANT		2.00	24.98	49.96		
82 14 1 467 704						
SHOCK MOUNT		2.00	139.55	279.10		
114812						
REAR AXLE BOOT KIT		2.00	144.62	289.24		
70000868						

Written By: F. Owen - Technicians: O. Arriaga; SELECT TECHNICIAN: F. Owen, Kuhnert, Ibra

Copyright (c) 2015 Mitchell Repair Information Company, LLC. Invo 2.15104



# Auto Tronics

995 B Jaymor Road  
Southampton, PA. 18966  
Phone: 215-357-2877 Fax: 215-357-2890

13719

## INVOICE

15112

## INVOICE

Print Date: 05/07/2015

1995 Ferrari - F355 Berlinetta - 3.5L, V8

Lic #: 0100630 - PA

Odometer In : 18223

VIN #: ZFFPR41A6 S0100630

Part Description / Number	Qty	Sale	Ext	Labor Description	Extended
Annual Inside Safety Sticker	1.00	5.00	5.00	EMISSIONS (DYNO)	50.00
AI STICKER				State Insp. Passenger Car	22.00
FREON	2.00	12.95	25.90	Emissions Sticker: IM5-2942596	
R134A				Safety Sticker: AI5-3479731 Exp: 05/2016	
A/C DYE	1.00	3.73	3.73	PRAETORIAN INSURANCE COMPANY	
DYE				Policy: P0007037631 - Exp Date: 1/4/2016	
Shop Supplies			1.56	Brakes: LF(9B) LR(10B) RF(9B) RR(10B)	
				Tires: LF(7) LR(4) RF(6) RR(5)	
				Previous Odometer: N/A	
				PERFORM 31-POINT DEALER INSPECTION	25.90
				CHECKLIST	
				PERFORM COMPRESSION AND LEAK DOWN TEST	117.00
				CYLINDER 1: 200 PSI, 20% LEAK	
				CYLINDER 2: 180 PSI, 5% LEAK	
				CYLINDER 3: 170 PSI, 20% LEAK	
				CYLINDER 4: 180 PSI, 15% LEAK	
				CYLINDER 5: 180 PSI, 25% LEAK	
				CYLINDER 6: 190 PSI, 15% LEAK	
				CYLINDER 7: 200 PSI, 5% LEAK	
				CYLINDER 8: 200 PSI, 10% LEAK	
				AIR CONDITIONING SERVICE (NO FREON IN	89.00
				SYSTEM)	
				SERVICE AIR CONDITIONER. CHECK CONDITION OF ALL	
				BELTS AND LINES. EVACUATE AND RECHARGE WITH NEW	
				R-134. TEST SYSTEM PERFORMANCE.	

Org. Estimate 340.09 Revisions 0.00 Current Estimate 340.09

Labor:	303.90
Parts:	36.19
Sub:	340.09
Tax:	0.00
Total:	340.09
Bal Due:	\$340.09

(Payments - 1)

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.





54827

**WIDE WORLD**  
OF CARS, LLC

\*INVOICE\*

A New Country Motor Car Group Dealership  
125 East Route 59 • Spring Valley, NY 10977  
(845) 425-2600 • Fax: (845) 425-7387  
1-800-635-BMW  
www.wideworldofcars.com  
Facility ID 7092332

PAGE 1

SERVICE ADVISOR: 361 JENNIFER MOCCIO

SERVICE ADVISOR: 361 JENNIFER MOCCIO

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
YELLOW	95	FERRARI 355BERLINETT	ZFFPR41A6S0100630	LTF25T	12561/12561	T9715	
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
01JAN1995			17:30 25SEP02		VARI	CASH	01OCT2002
R.O. OPENED		READY	OPTIONS: DLR:25770				

11:51 13SEP02 12:30 01OCT02

LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A C/S D/S DOOR RATTLES WHEN DRIVING ESPECIALLY WHEN WINDOW IS OPEN

9F REMOVE OUTSIDE PANEL. CLIP LOOSE ON REGULATOR

DRAIN. REPLACED MISSING SCRES AND RESECURE

LOWER PANEL.

503 CPF

135.00 135.00

1 44581 EPOXY

5.00 5.00 5.00

\*\*\*\*\*

B C/S RATTLE FROM LEFT REAR WHEN MAKING RIGHT TURNS

6F PERFORM FOUR WHEEL ALIGNMENT

503 CPF

540.00 540.00

\*\*\*\*\*

C\*\* PEBBLE BEACH DETAIL

15F PERFORM DETAIL

99 CPF

0.00 0.00

SUBL PEBBLE BEACH DETAILING

CPF

175.00 175.00

\*\*\*\*\*

D\*\* INSTALL NEW TIRES

04F INSTALL FOUR NEW TIRES AND BALANCE - NOTE:

REAR SHOCKS ARE POPPED, CUSTOMER DECLINED

REPAIR.

503 CPF

270.00 270.00

2 P22540ZR18 FRONT TIRES

220.00 220.00 440.00

2 P26540ZR18 P-ZERO ASY

305.00 305.00 610.00

4 TR TIRE REMOVAL

2.00 2.00 8.00

1 ORING ORING

0.69 0.69 0.69

\*\*\*\*\*

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

## STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

DESCRIPTION	TOTALS
LABOR AMOUNT	945.00
PARTS AMOUNT	1063.69
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	175.00
MISC. CHARGES	0.00
TOTAL CHARGES	2183.69
LESS INSURANCE	0.00
SALES TAX	171.97
PLEASE PAY THIS AMOUNT	2355.66

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

CUSTOMER COPY



2085 HUDSON STREET
FORT LEE, NEW JERSEY 07024
(201)947-2371
E.R.F. # 001349

(201)947-2371

E.R.F. # 001349

	INV0000267
	7/20/00
	7/20/00
OF	FERRARI 355 TB YELLOW
MOBIL	ID#100630 JRW26W
PROBLEM DESCRIPTION	10814 95

Miles 10824 replace handle brake shoes

[illegible]

**EXOTIC  
CAR  
SPECIALISTS**

Credit Card Number

Check Number

1044

55

Other:

Tax

\$28.56

**Total:**

\$504.56

Amount

\$0.00

**Balance Due:**

\$504.56

Authorized signature

TOTAL 792.77

be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

13719

**Auto Tronics**  
995 B Jaymor Road  
Southampton, PA. 18966  
Phone: 215-357-2877 Fax: 215-357-2890

INVOICE

21598

INVOICE

Tax Resale #: 84175520

Date: 06/12/2017

1995 Ferrari - F355 Berlinetta - 3.5L, V8

Lic #: 0100630 - PA

Odometer In: 18538

VIN #: ZFFPR41A6 S0100630

Part Description	Number	Qty	Sale	Ext	Labor Description	Ext
COOLANT		4.00	23.51	94.04	State Insp. Passenger Car	22.00
82 14 1 467 704					Emissions Sticker: IM7-5694991	
Annual Inside Safety Sticker		1.00	6.00	6.00	Safety Sticker: AJ7-3764917 Exp: 07/2018	
AI STICKER					UNIVERSAL UNDERWRITERS INSURANCE COMPANY	
Shop Supplies				4.50	Policy: 340396 - Exp Date: 1/4/2018	
					Brakes: LF(9B) LR(10B) RF(9B) RR(10B)	
					Tires: LF(7) LR(4) RF(7) RR(4)	
					Previous Odometer: 18240	
					EXEMPT EMISSION TEST	17.35
					***Discount***	
					\$39.35 off labor	

Org. Estimate 104.54 Revisions 0.00 Current Estimate 104.54

Labor:	39.35
Parts:	104.54
Discount:	-39.35
SubTotal:	104.54
Tax:	0.00
Total:	104.54
Bal Due:	\$104.54

[ Payments - ]

Vehicle Received: 6/12/2017

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Written By: F. Owen - Technicians: SELECT TECHNICIAN; F. Owen

Copyright (c) 2017 Mitchell Repair Information Company, LLC. Inluts 11.10.16b



13719 7/13 PW

15800

## Print Date: 07/15/2015

Lic # : 0100630 - PA

Odometer In : 18298

VIN # : ZFFPR41A6 S0100630

Org. Estimate	173.80	Revisions	0.00	Current Estimate	173.80	Labor:	0.00
STAND						Parts:	173.80
STAND W/ WHEELS							
STAND							
STAND W/ WHEELS							
STAND W/ WHEELS						Sub:	173.80
STAND W/ WHEELS						Tax:	0.00
STAND W/ WHEELS						Total:	173.80
STAND W/ WHEELS						Bal Due:	\$173.80

[ Payments - ]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.



D. G. DAVEN

12/14/94

99

11/06/98

VEHICLE IDENT. NO.

ZFFPR41A6S0100630

VEHICLE CTL. NO.

S0100630

MILEAGE

7494

ADV.

07B

YR/MODEL

95 F355

PHONE-BUS.

WRES. TO

CUSTOMER NO.

013887

TAG NO.

INVOICE NO.

040005

DATE

11/06/98

PAGES

1

WORK ORDER NO.

040005

						LABOR AND PARTS	
						LUBE SERVICE	
						CHANGE OIL & FILTER, CHECK ALL LGTS, FLUIDS,	
37.80						9-4725 AGIP OIL	63.00
0.34						1-130623 OIL	0.28
						1-DRAIN SEAL	0.55
1.5	CCDMF	B	67C	1.5	6	FLUSH BRAKE & CLUTCH FLUIDS	120.00
8.50						PERFORM BRAKE & CLUTCH FLUIDS	
						2-BRAKE FLUID	5.80
1.0	CCDMF	C	67C	1.0	3	FLUSHH COOLANT	80.00
5.35						PERFORM COOLANT FLUSH & PRES. TEST ALL OK	
						1-ANTI-FRZ	8.91
0.0	CCDMF	D	67C	0.0		ADJUST HAND BRAKE	0.00
						COULD NOT ADJ, MAY NEED NEW CABLE	

COST

WARRANTY  
ACCOUNT

AMOUNT

COST

INTERNAL  
ACCOUNT

AMOUNT

COST

ACCOUNT

CUSTOMER PAY  
DESCRIPTION

AMOUNT

90.00	4500 DLR MEC FLR	90.00
56.16	4602 DLR MEC FER-PTS	93.54
	3240 SALES TAX	6.00

TOTAL

419.



to be done along with the necessary material and hereby grant you and/or your employees the right to use the vehicle for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the cost of repair in our shop & cannot exceed the original cost of repair.

Copyright © 2015 Michel Repair Information Company, LLC. 10/15/15

**Ferrari**

THIS LABEL HAS BEEN AFFIXED TO THIS VEHICLE PURSUANT TO THE REQUIREMENTS OF U.S.C. 155 1231 ET SEQ. WHICH PROHIBITS ITS REMOVAL OR ALTERATION PRIOR TO DELIVERY TO THE ULTIMATE PURCHASER.

Ferrari North America, Inc.



LOAD NUMBER	PORT OF IMPORTATION <b>Newark</b>	WAREHOUSE <b>Englewood</b>	SERIAL NUMBER <b>ZFFPR41A6S0100630</b>	MODE OF TRANSPORTATION <b>Via Truck</b>
DEALER TO WHOM DELIVERED <b>LAKE FOREST SPORTSCARS, LTD. 780 NORTH WESTERN AVENUE LAKE FOREST, IL 60045</b>		<b>F355 BERLINETTA YELLOW/BLACK</b> MANUFACTURER'S SUGGESTED PORT OF ENTRY RETAIL PRICE ▶ <b>\$113,000.00</b> 350.00 N/C 5,400.00		
STANDARD EQUIPMENT INCLUDED IN SUGGESTED RETAIL PRICE:		PREPARATION AND DELIVERY ALL WEATHER COOLANT GAS GUZZLER TAX		
<b>LIGHT ALLOY V8 ENGINE (3496 CC)          4 OVHD CAMSHAFTS-5 VALVES/CYL.          DRY SUMP LUBRICATION W/OIL RAD.          BOSCH MOTRONIC 2.7 IGNITION/          INJECTION WITH FEEDBACK CONTROL          AND ON BOARD DIAGNOSTICS          6 SPEED MANUAL TRANSVERSE          GEARBOX WITH OIL PUMP          AND OIL COOLER          LIMITED SLIP DIFFERENTIAL          FOUR WHEEL VENTILATED DISC BRAKES          TEVES ANTI-SKID BRAKING SYSTEM          MICHELIN PILOT SX STEEL          BELTED RADIAL PLY TIRES          255/40 ZR18 FRONT          265/40 ZR18 REAR          MAGNESIUM WHEELS          DRIVER &amp; PASSENGER SIDE AIR BAGS</b>		<b>AUTOMATIC CLIMATE CONTROL          ELECTRIC WINDOWS AND HEATED          EXTERIOR MIRRORS          POWER RACK AND PINION          STEERING SYSTEM          TUNED FREE FLOW EXHAUST          SYSTEM          ELECTRIC DOOR LOCKS          TINTED GLASS          CONNOLLY LEATHER INTERIOR          CAR COVER</b>  <b>OPTIONS:</b>		
<b>NOTICE</b> THIS VEHICLE IS EQUIPPED WITH BUMPERS THAT CAN WITHSTAND AN IMPACT OF 2.5 MPH WITH NO DAMAGE TO THE VEHICLE'S BODY AND SAFETY SYSTEMS. ALTHOUGH THE BUMPER AND RELATED COMPONENTS MAY SUSTAIN DAMAGE. THE BUMPER SYSTEM ON THIS VEHICLE CONFORMS TO THE CURRENT FEDERAL BUMPER STANDARD OF 2.5 MPH.		<b>SUB TOTAL*</b> <b>\$118,750.00</b> <b>DESTINATION CHARGES</b> <b>1,300.00</b> <b>TOTAL SUGGESTED RETAIL PRICE ▶</b> <b>\$120,050.00</b>		
*GASOLINE, LICENSE AND TITLE FEES, LUXURY, STATE AND LOCAL TAXES, DEALER INSTALLED ACCESSORIES ARE NOT INCLUDED.				

Compare this vehicle to others in the **FREE GAS MILEAGE GUIDE** available at the dealer.

**CITY MPG**



**Actual Mileage** will vary with options, driving conditions, driving habits and vehicle's condition. Results reported to EPA indicate that the majority of vehicles with these estimates will achieve between

**8 and 12** mpg in the city,  
and between  
**12 and 18** mpg on the highway.



**1995 FERRARI F355  
BERLINETTA  
3.5 LITER 8 CYLINDER  
MULTIPOINT FUEL INJECTION  
WITH FEEDBACK FUEL CONTROL  
MANUAL 6 SPEED TRANSMISSION**

**Estimated Annual Fuel Cost:**

**\$ 1687  
GAS GUZZLER TAX  
\$ 5400**

**HIGHWAY MPG**



**For Comparison Shopping,**

all vehicles classified as **TWO-SEATER**

have been issued mileage ratings ranging from **9** to **35** mpg city and **14** to **41** mpg highway.

Under EPA's **Previous Fuel Economy Program**, used prior to the 1985 model year this vehicle would have received a single estimate of **N/A** mpg.