

MERLIN AUTO GROUP

MECHANICAL INSPECTION

TECHNICIAN NAME	Malcolm Barnett
YEAR/MAKE/MODEL:	2006 Mercedes Benz SLR
MILEAGE AT TIME OF INSPECTION:	6,302
VEHICLE IDENTIFICATION NUMBER:	WDDAJ76F36M001012
DATE OF INSPECTION:	6/17/26

DISCLAIMER

The contents of this Inspection Report reflect a subjective opinion of the inspector (Merlin Auto Group) on the date of inspection. Merlin Auto Group does not provide any representations or warranties with regard to the condition or provenance of the particular vehicle described in this report. It is the buyer's responsibility to conduct his/her own due diligence. Merlin Auto Group welcomes third-party and/or in-person inspections at its facility and encourages interested buyers to arrange an appointment for an in-person inspection.

LIGHTS

Component	OK	Repair	Replace	Comments/Recommendations
Headlights and assembly	☒	☐	☐	
Turn signals	☒	☐	☐	
High beam flasher	☒	☐	☐	
Side / Directional lights and assembly	☒	☐	☐	
Parking lights	☒	☐	☐	
Hazard lights	☒	☐	☐	
Fog lights (front / rear)	☒	☐	☐	
Rear taillights and assembly	☒	☐	☐	
3rd Brake light and assembly	☒	☐	☐	
Reverse (back-up) lights	☒	☐	☐	
License plate lights	☒	☐	☐	
Dashboard and courtesy lights	☒	☐	☐	
Dome light(s)	☒	☐	☐	
Visor lights	☒	☐	☐	
Glove box light	☒	☐	☐	
Dashboard / cluster lights	☒	☐	☐	

STATIONARY REVIEW

Component	OK	Repair	Replace	Comments/Recommendations
Convertible top (if applicable)	☒	☐	☐	
Sunroof (if applicable)	☐	☐	☐	NA
Antenna	☐	☐	☐	
Seat belts	☒	☐	☐	
Headrest position	☒	☐	☐	
Heated / ventilated seats operation	☐	☐	☐	
Seat memory functions	☐	☐	☐	
HVAC functions (blower, temp settings)	☒	☐	☐	
Windshield defrosters (front and rear)	☒	☐	☐	
Mirror (inside) adjustments and function	☒	☐	☐	
Mirror (outside) adjustments and function	☒	☐	☐	
Door locking functions (all doors)	☒	☐	☐	
Steering column adjustment and functions	☒	☐	☐	
Horn function	☒	☐	☐	
Power windows	☒	☐	☐	
Radio function	☒	☐	☐	
Aux power ports (e.g., cigar lighter)	☒	☐	☐	
Stalk controls (lights, wipers, etc.)	☒	☐	☐	
Gearshift function / indicator	☒	☐	☐	
Parking brake function / indicator	☒	☐	☐	
Key and remote control function	☒	☐	☐	
Front seat condition and functions	☒	☐	☐	

Rear seat condition and functions	☒	☐	☐	
Hood (bonnet) release	☒	☐	☐	
Trunk release, fuel door release	☒	☐	☐	
Glove box functionality	☒	☐	☐	
Wiper blades and assembly	☒	☐	☐	
Windshield Washer jets	☒	☐	☐	
Headlight washer jets	☒	☐	☐	
Alarm functions	☒	☐	☐	
Gas shocks (hood, trunk, engine bay)	☒	☐	☐	All Perform as normal incl Doors

WHEELS / TIRES				
Location	Tire tread depth	Tire/Make/Model/Size	Date Code	Comments
Right Front	8/32	Michelin	2019	Replace per Company Policy
Left Front	8/32	Michelin	2019	NO SIGNS of DRY ROT
Left Rear	8/32	Michelin	2019	
Right Rear	8/32	Michelin	2019	
Spare				

UNDERCARRIAGE				
Component	OK	Repair	Replace	Comments/Recommendations
Brake pad measurements	☒	☐	☐	
Suspension components	☒	☐	☐	
Front control arm bushings	☒	☐	☐	
Steering rack	☒	☐	☐	
Engine mounts	☒	☐	☐	
Transmission mounts	☒	☐	☐	
Lifting blocks	☒	☐	☐	
Exhaust manifold	☒	☐	☐	
Catalytic converters	☒	☐	☐	
Muffler(s)	☒	☐	☐	
Exhaust pipes / tail pipes	☒	☐	☐	
Inner fenders / shock towers	☒	☐	☐	
Axle mountings / boots	☒	☐	☐	
Subframe	☒	☐	☐	

ENGINE / TRANSMISSION				
Component	OK	Repair	Replace	Comments/Recommendations
Cold / hot starting	☒	☐	☐	
Idle	☒	☐	☐	
Vibration at idle	☒	☐	☐	
Belts and belt tensioners	☒	☐	☐	
Coolant hoses	☒	☐	☐	
Power steering hoses	☒	☐	☐	
Fuel lines	☒	☐	☐	
A/C lines	☒	☐	☐	
Alternator	☒	☐	☐	
Battery cables	☒	☐	☐	
Other electrical cables / wiring / fuse boxes	☒	☐	☐	

FLUIDS / LEAKS				
Component	OK	Repair	Replace	Comments/Recommendations
Gasket condition	☒	☐	☐	
Engine oil	☒	☐	☐	
Coolant	☒	☐	☐	
Transmission oil	☒	☐	☐	
Differential	☒	☐	☐	
Half shafts	☒	☐	☐	
Fuel	☒	☐	☐	
Brakes	☒	☐	☐	
Power steering	☒	☐	☐	

Shocks / struts	☒	☐	☐					
A/C	☒	☐	☐					
Hydraulic	☒	☐	☐					
ROAD TEST / DYNAMIC REVIEW								
Component	OK	Repair	Replace	Comments/Recommendations				
Stability	☒	☐	☐					
Acceleration	☒	☐	☐					
Braking	☒	☐	☐					
ABS (if equipped)	☒	☐	☐					
Transmission / clutch function	☒	☐	☐					
Steering alignment	☒	☐	☐					
Vibration	☒	☐	☐					
Cruise control	☐	☐	☐					
Cluster gauges	☒	☐	☐					
Wind noise	☒	☐	☐					
Road noise	☒	☐	☐					
Rattles / squeaks	☒	☐	☐					
Other								
Service reminder presence / advise if service due is indicated	No record of Spark Plug Replacement. No indication of failure							
Describe specific results from diagnostic analysis, e.g., - Clutch settings / wear percentage - Diagnostic Trouble Codes (DTC)	NA							
Engine compression / leak down test results (if applicable)	NA							
TECHNICIAN COMMENTS								
Vehicle has been thoroughly inspected and is in overall Excellent condition. No signs of deferred or outstanding maintenance items were noted, with the exception of aged tires. Note: Spark plugs are currently performing within normal parameters; however, no service records indicating previous replacement were found — recommend monitoring as a preventative measure. No evidence of prior damage or structural repairs was observed. Road test was completed — vehicle performed as designed with no abnormalities noted. The only recommendation at this time is tire replacement due to age-related deterioration								