



MULTIPOINT VEHICLE INSPECTION

REPAIR ORDER #:	0883	DATE:	12-10-2025
YEAR/MAKE/MODEL:	2015 Porsche Panamera 4S	MILEAGE:	49,831
CHASSIS:	050929	TECHNICIAN #:	102
CHECK BATTERY			
BATTERY HEALTH	OK	BATTERY CABLES/ CONNECTIONS	Checked and OK at this time
CHECK TIRES AND TREAD DEPTH			
Location	LEFT	RIGHT	Wear Pattern/Damage observed?
FRONT TIRES	8/32 or Greater	8/32 or Greater	<input type="checkbox"/> LF <input checked="" type="checkbox"/> RF <input type="checkbox"/> RR <input type="checkbox"/> LR <input type="checkbox"/> N/A
REAR TIRES	8/32 or Greater	8/32 or Greater	
Are tires older than 5 years?	No	Specify if alignment, balance or rotation needed	N/A
CHECK BRAKES			
FRONT BRAKES	4mm-6mm	REAR BRAKES	4mm-6mm
MAINTENANCE RECOMMENDATIONS			
<input type="checkbox"/> Engine Oil <input type="checkbox"/> Brake Fluid <input type="checkbox"/> Engine Air Filter(s) <input type="checkbox"/> Cabin Air Filter <input checked="" type="checkbox"/> Wiper Blades <input type="checkbox"/> Coolant <input type="checkbox"/> Power Steering Fluid <input type="checkbox"/> Transmission/Gearbox Fluid <input type="checkbox"/> Belt(s) <input type="checkbox"/> Spark Plugs <input type="checkbox"/> N/A			Service reminder presence? No Warning lights? No
ADDITIONAL CHECKS			
Fuel system (including gas cap)	Checked and OK at this time	Engine, transmission, drive axle, transfer case	Checked and OK at this time
Engine cooling system: leak/other	Checked and OK at this time	Belts: engine, power steering and/or V-drive	Checked and OK at this time
Hoses: engine, power steering and HVAC	Checked and OK at this time	HVAC performance	Checked and OK at this time
Steering components and linkage	Checked and OK at this time	CV drive axle boots or driveshafts and U-joints	Checked and OK at this time
Drive axle (leak/other)	Checked and OK at this time	Shocks and struts	Checked and OK at this time
Exhaust system components	Checked and OK at this time	Evaporate control system	Checked and OK at this time
Lights: headlamps, taillights, turn signals	Checked and OK at this time	Lights: brake lights, reverse lights	Checked and OK at this time
Convertible top/sunroof (if applicable)	Checked and OK at this time	Restraint system component check	Checked and OK at this time
TECHNICIAN SUMMARY			
No diagnostic time requested.			
Front brake pads are close to wear sensors. Right front tire should be replaced due to sidewall damage. Would recommend replacing all wiper blades. Would recommend replacing hood struts at engine compartment.			

TECHNICIAN PHOTOS



Curb damage to right front tire sidewall and wheel.



Curb damage at left front wheel



Curb damage at left rear wheel



Curb damage at right rear wheel



Heavy scratches at right side, lower front bumper



Heavy scratches at left side, lower front bumper.



Scratches at right rear quarter panel



Hood struts weak at front hood